
1/2 TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM DEVELOPMENTAL SIMULATION(U) BOEING COMMERCIAL AIRPLANE CO SEATTLE WA G P BOUCEK ET AL. JUL 82 F/G 17/7 AD-A126 342 NL UNCLASSIFIED



MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

والما المنازي والمجانية المراكمية المناور والرابية

40A126342

DOT/FAA/RD-82/49

Program Engineering & Maintenance Service
Washington, D.C. 20591

Traffic Alert and Collision Avoidance System

Developmental Simulation

G. P. Boucek, Jr.

R. W. White

W. D. Smith

J. M. Kraus

Boeing Commercial Airplane Company P.O. Box 3707 Seattle, Washington 98124

July 1982 Final Report

This document is available to the U.S. public through the National Technical Information Service, Springfield, Virginia 22161.

UTIC FILE COPY



U.S. Department of Transportation Federal Aviation Administration



E

83 04 04 014

4

NOTICE

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof.

ووالمهدائية والأوارية والد

Technical Report Documentation Page

DOT/FAA/RD-82/49	2. Government Access	on No. 3, Re	ecipient s Catalog N	o. !					
4. Title and Subtitle TRAFFIC ALERT AND COLLISION	AVOIDANCE SYS	J	JULY 19	82					
DEVELOPMENTAL SIMULATION		6. Pe	erforming Organizatio	on Code					
7 Author's G. P. BOUCEK, JR.;	R. W. WHITE: W		rforming Organizatio	n Report No.					
J. M. KRAUS									
9. Performing Organization Name and Address SYSTEMS TECHNOLOGY, RESEARCE	H - CREW SYSTEI	1	ork Unit No. TRAIS	, i					
BOEING COMMERCIAL AIRPLANE P. O. BOX 3707	COMP ANY	11. C	Contract or Grant No.						
SEATTLE, WASHINGTON 98124			ype of Report and P	eriod Covered					
12. Sponsoring Agency Name and Address U.S. Department of Transpor	tation	F1	NAL REPORT	!					
Federal Aviation Administra Program Engineering & Maint		19	81 - APRIL 1	982					
Washington, D.C. 20591	enance Service		APM=430						
15 Supplementary Notes									
the Traffic Alert and Colli study was to investigate di of TCAS information on both specific objectives of this	This report describes one of a series of studies being conducted to develop the Traffic Alert and Collision Avoidance System (TCAS). The purpose of this study was to investigate display technology appropriate for the presentation of TCAS information on both conventional and advanced flight decks. The specific objectives of this study phase were to:								
concepts	e areruing erre	ctiveness of candi	idate runs di	ispiay					
	ne variability precede the war	of including a cau ning (RA)	ution level a	llert (TA)					
o Identify min	imum informati	on requirement for	the RA and	TA;					
on Select a TCAS display concept to be used in the operational simulation									
In the tests, experienced transport pilots were presented TCAS alerts while flying a transport simulator. Their responses to the alerts were recorded as were their opinions about the system. Display characteristics are presented with a heavy reliance being put on the recommendation in "Aircraft Alerting System Standardization Study DOI/FAA/RD-81/38/II.									
17. Key Words COLLISION AVOIDANC	E, ALRCRAFT	18. Distribution Statement							
SEPARATION ASSURANCE: ALERT SYSTEMS: ALERTING SYSTEMS; RESPONSE; VISUAL ALERTS; SI DETECTION;	; WARNING SIGNAL	THROUGH THE NATIO SPRINGFIELD, VIRG	NAL INFORMAT	U. S. PUBLIC TON SERVICE,					
SEPARATION ASSURANCE; ALERT SYSTEMS; ALERTING SYSTEMS; RESPONSE; VISUAL ALERTS; SI	; WARNING SIGNAL	THROUGH THE NATIO SPRINGFIELD, VIRG	NAL INFORMAT						

Form DOT F 1700.7 (8-72)

METRIC CONVERSION FACTORS

	Symbol		:	£ .	: I	ī		•	s T	ì				•	.					=	K i	; ;	i'z	Ţ				٠			•.		e.	
Messures	To Stad		į	mches	o de la companya de l	. elie		•	parent inches	seller andies	-			į	į	short tone				fluid sunces	e de la companya de l		Carte fac	Copic yards				f gleanlain	American I	•	2 2	}		,
sions from Motric	Mainiply by	LENGTH	3	•	E -	• 0	AREA		9	7.0	5.5		MASS (weight)	200	2.2	:		VOLUME		0.03	. .	3 3		 		**************************************	SEMPERATORE (SISE)	9.76 (filen	(2C 904		:	-1	- 02	
Approximate Conversions from Matric Measures	When You Know	Ì		Continuetres	neiere reiere	hilgmeter a			Squara contimetters Squara maters	equere hildmeters	hacterne (10,000 m²)		*	į	h i lagrams	tornes (1000 kg)			}	millilliters	Here		cubic meters	Cubic meters		Teact		Colsten	arabastrus 1			4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	- 02-	
	Symbol		E	£	E E	Ę		7	£~=	~ 5	2			•	. 3	•				Ĩ			- ^ 1	°₽				٠			•	0 1	ĭ	•
180.00	EZ 1	1	oz	61		1	 	n I	SI	1	•1	E	:1 	21		. 	01		11:1		•		2 						*				1	cu
l'ala	''		Lil	1"	' -	, Մի	'''	(1') -	'l' •	7'	'1' 	'''' 	 s	'l' 	'l'	'l' 	' <u>'</u>	' <i>1</i> '	'1	' }'	ł	l'	'I'	' ' 	' '		; ;	T	' ' '		יןיןין י	ł		
	Symbol				E !	.			~ _E	~ _E ~	`]	2			_ !	.	•			Ē	Ē.	Ē.		. -	-	٦ _. '	È		٠			1		
Messeres	To Find				continuiors	meters bilgmeters			equere centimeters	Squere meters	squere melets	hecteres			94.50	lornes				millithers.	allilitars.	311111111	6.01		Eres	cubic metera	cubic maters		Ceteive	temperature			iahlen, see MBS Misc. Pid	
Appreximate Conversions to Metric Me	Muttiply by	•	LENGTH		5 7.5	\$ 6 °	4384	TAIL TO SERVICE TO SER	4.5	6.0	6.6 8.7	3	MASS (weight)		2 3	6.0	;	VOLUME		•	=	£ '	0.24	**	1.0	6.03	8 .0	TEMPERATURE (exect)	8/8 (efter	authracting	â		Greaters and make deliberary (1)	
Appreximate Conv	When You Know				inches	a se]	square inches	Beuere feet	squere miles	96198	2	}	S TO	phort tone	(2000 16)			Issepons	1 ablespens	Unid Sunces			. File	Cubic feet	cubic yards	TEMP	Fabrumbeit	(amparatus			*1 in a 1 % to topically if the other pages convertions and make this indication, one NBS first. Publ. 256, 1.1.1. In this topical and soundings a factor of 25 co. Careline to Clinic 256.	
	Sympton				£ 1	: 1 7			" }	~~ [~]	Þ°ī				3 :	2				<u>\$</u>	ž	3	. 1		. 1	. P.	ž						H 76 ~	

This report documents one of a series of studies being conducted to develop and implement an effective collision avoidance system. The primary purpose of this study was to investigate the methods of presenting the system information to the crew and make recommendations concerning the display system. This volume provides the results of the study and a candidate display system concept.

The authors wish to express appreciation to the many pilots who participated in the tests and to the various organizations and companies which permitted the participation; FAA, NASA, Boeing, American Airlines, Republic Airlines, United Airlines, U. S. Air, and Western Airlines. The contract sponsor is the Federal Aviation Administration, and technical quidance was provided by Mr. Richard Weiss, APM-430, the contract monitor.

Acce	ssion For
	GRA&I
DTIC	TAB 🌴
Unan	meunced
Just	ification
By	ribution/
	ilability Codes
	Avail and/or
Dist	Special
A	
	OT.C COPY INSPECTED

1

TABLE OF CONTENTS

		PAGE
1.0	INTRODUCTION AND BACKGROUND	1
	1.1 Report Organization	3
3 . 0	EXECUTIVE SUMMARY	5
	2.1 Program Background	5
	2.2 Developmental Simulation Testing	5
	2.3 Candidate System Description	9
	2.4 Follow-on Verification and Evaluation	10
3.0	TEST FACILITY	11
4.0	DEVELOPMENTAL SIMULATION - TEST DESCRIPTION AND RESULTS	13
	4.1 Test Objectives	12
	4.2 Experimental Design	14
	4.2.1 Test Design 4.2.2 Intruder Flight Path	14 24
	4.2.3 Simulation TCAS Logic	24
	4.3 Pilot Sample	26
	4.4 Crew Tasks	26
	4.4.1 Flight Task	26
	4.4.2 System Alert Resnonse Tasks	29
	4.4.3 TCAS Alert Response Task	35
	A.S. Test Procedures	75 42
	4.6 Measurement Technique 4.6.1 Performance Measures	42
	4.6.2 Subjective Measures	42
	4.7 Data Reduction and Analysis	45
	4.7.1 Experimental Hypothesis	45
	4.8 Test Results	AN.
	4.8.1 Detection Times	ΛQ
	4.8.2 Mesponse Times	19
	4.8.3 Missed Alerts and Incorrect Responses	55
	4.9.4 Pilot Input	55
5.0	DISCUSSION AND CONCLUSIONS	63
6.0	*··· • · • · • · · · · · · · · · · · · ·	60
	6.1 System Design Objectives	69
	6.2 TCAS Display Configuration	69 71
	6.2.1 Master Alerts 6.2.2 Resolution Advisory Displays	74
	6.2.3 Traffic Information Display	76
	6.3 Follow-on Verification and Evaluation	77
REFE	ERFNCES	70
	LIOGRAPHY	81
	ENDIX A TEST FACILITIES	A-1
	ENDIX B PILOT TRAINING CHECKLIST	R-1 C-1
	ENDIX C POST FLIGHT OUESTIONNAIRE ENDIX D DEBRIEFING OUESTIONNAIRE	n-1
Arre	EXPERIMENTAL OFFICER CONTRACTOR OF A STANDARD	/ \

LIST OF FIGURES

FIGURE NO:	TITLE	PAGE
1.0-1	Guidelines for Standardizing Alerting Functions and Methods	4
3.0-1	Kent Visual Flight Simulation Center	12
4.2.1-1	Developmental Simulation Test Design	15
4.2.1-2	TCAS Alertina System	17
4.2.1-3 4.2.1-4	IVSI Command Display for Simulation Tests	18
4.2.1-5	Developmental Simulation LED Display Formats Tabular Traffic Display - Without Bearing	55 10
4.2.1-6	Tabular Traffic Display - With Rearing	22
4.2.1-7	Currently Used Graphic Format	23
4.2.1-8	Advanced Graphic Format	23
4.2.2-1	Intrusion Scenarios	25
4.4.1-1	Flight Deck	28
4.4.1-2	Developmental Simulation Flight Path	30
4.4.1-3	Visual Flight Take-off	२१
4.4.2-1	Pilot's Response Panel	36
4.4.3-1	TCAS Resolution Advisory Alerts and Example	
	IVSI Presentation	37
4.8.1-1	Initial Detection Time as a Function of Alert	
	Display	51
4.8.1-2	Alert Detetion Time - TA Display	52
4.8.2-1	A Comparison of Response and Detection Times as a	
4000	Function of the Traffic Display	54
4.8.2-2	Comparison of Response and Detection Times as a	5.0
4.8.4-1	Function of the Resolution Advisory Display	<u> </u>
4,8.4-2	Pilot Opinion Concerning the TA Display Usefulness Pilot Opinion Concerning the RA Display Clarity	
	rito. Opinion concerning the RA Dispray Granty	6?
5.0-1	Typical Response Times as a Function of Display Type	67
6.2.1-1	Recommended Placement of Visual Signals	72
A.0-1	Kent Visual Flight Simulation Center	A-3
A.1-1	Side View of Blue Cah	A-4
A.1.1-1	Blue Cah Front Panel Layout	A-6
A.2.1-2	Internal View of Blue Cab	A-7
A.2-1	CAS Simulation Equipment Layout	P-A
A.2.1-1	Advisory Message Byte Definition	A-11
A.2.3-1	TCAS Audio-Visual (TAV) Unit	A-14
A.2.3-2 A.2.3-3	TAV Front Panel Layout	A-15
A.2.4-1	Block Diagram of LED TCAS Display	A-18
M.7.4-1	Block Diagram of FAA-Supplied Airhorne Intelligent Display (AID) System	A 10
A.2.4-2	AID Message Byte Defintion	A-19 A-20
A.3.1-1	Audio Equipment Block Diagram	A-27
4.3.1-2	Audio Equipment Rack Layout	A-23
A.3.2-1	Video System Layout	A-25
A.3.3-1	Master Conductor Console Layout	A-27
A.3.3-2	System Block Diagram for Master Control Console	. , .
	Bus Interface	A-28

LIST OF TABLES

TABLE NO.	TITLE	PAGE
4.3-1	Summary of Pilot Experience	27
4.4.1-1	ATC Communication	32
4.4.2-1	Operational and Systems Condition for Alerts	
	and Their Associated Response	77
4.5-1	Random Treatment Assignments	40
4.5-2	Daily Test Schedule	41
4.7-1	Sample of Analysis of Variance Model and Summary	
	Table for a Factorial Experiment with Repeated	
	Measures on Some of the Factors	46
4.8.1-1	ANOVA Summary Table for Initial Detection Time	50
4.8.2-1	AMOVA Summary Table for Response Times	53
A.2.1-1	Summary of Host-to-BEU Simulation Unit Message	
	Formats	A-10
A.2.1-2	Definition of Parallel Data Sent to IVSI and	
	TAV by MicroNova	A-12
A.2.3-1	Voice Vocabulary List	∧-17

LIST OF ABBREVIATIONS

ADI	Attitude Director Indicator
AID	Airborne Intelligent Display
ALPA	Airline Pilots Association
ANOVA	Analysis of Variance
APA	Allied Pilots Association
ARP	Aerospace Recommended Practice
ASA	Aircraft Separation Assurance
ATA	Air Transport Association
ATC	Air Traffic Control
RCAS	Beacon Collision Avoidance System
BEU	BCAS Experimental Unit
CAS	Collision Avoidance System
x?	Chi causuad
CRT	Chi-squared
dB	Cathode Ray Tube Decibel
df	Degrees of Freedom
DME	Distance Measuring Equipment
EADI	Electronic Attitude Director Indicator
EHST	Electronic Horizontal Situation Indicator
FAΛ	Federal Aviation Administration
fpm	Feet per minute
ft-L	Footlambert
r,	Gravity
HST	Horizontal Situation Indicator
нир	Head-up Display
Hz	Hertz
IAS	Indicated Airsneed
TER	Instrument Flight Rules
ILS	Instrument Landing System
IMC	Instrument Meteorological Conditions
IVSI	Instantaneous Vertical Speed Indicator
KIAS	Knots Indicated Airspeed
LED	Light Emitting Diode
MCC	Master Control Console
ml	Millilamhert
msec	Millisecond
MSL	Mean Sea Level
NASA	National Aeronautics and Space Administration
nmi Da	Nautical Miles
PA	Proximate Advisory
PROM	Programmable Read Only Memory
PWI	Proximity Warning Indicator
r RA	Correlation Coefficient
RAM	Resolution Advisory
SAE	Random Access Memory
sin	Society of Automotive Engineers
S/N	Sine of an angle Signal to Noise Ratio
TA	Traffic Advisory
TAV	TCAS Audio Video
TCA	Terminal Control Area
TCAS	Traffic Alert and Collision Avoidance System
VFR	Visual Flight Rules
VMC	Visual Meteorological Conditions
Ϋ́	Arithmetic Mean
	viii

viii

GLOSSARY

Conditions or situations which require Abnormal Conditions other than normal procedures. Operational or aircraft system conditions Advisory Alert that require crew awareness and may require crew action. Caution Alert Abnormal operational or aircraft system conditions that require immediate crew awareness and require prompt corrective or compensatory crew action. Developmental Simulation Phase I of the TCAS display program with the objective of developing minimum information requirements for the TCAS II display system and to recommend a candidate configuration. The time from alert initiation or change Detection Time of state (caution to warning until when the pilot indicates a recognition of the condition by depressing the detection button. Acceleration equivalent to gravity or G 32.2 feet per second squared. Unit of frequency equal to one cycle per Hertz second. An aircraft which violates the TCAS Intruder criteria and represents a potential An aircraft that has a transponder but Non-mode C Aircraft has no altitude reporting from the transponder. Operational Simulation Phase II of the TCAS display program with the objective of developing and validating operational cockpit procedures for a TCAS encounter. The subject aircraft equipped with the Own Aircraft hypothetical TCAS II system. Predetermined set of actions to be taken Procedure by a crewmember in a specific operational

1

list.

situation. May or may not be written in a readily accessible form (e.g., check-

Resolution	Advisory
------------	----------

A warning level alert - a display indication given to the pilot recommending a maneuver to increase separation relative to an intruding aircraft. Corrective, preventative and vertical speed limit advisories constitute the resolution advisories.

Response Time

- The time from alert initiation (RA) until when the pilot had performed the correct response.

TAU

 A derived quantity usually expressed in seconds, which represents the time to the point of closest approach between the own aircraft and an intruder. It is defined as range divided by range rate.

TCAS I

 A less sophisticated collision avoidanc system designed primarily for general aviation.

TCAS II

 A more sonhisticated system providing collision avoidance capabilities in high density areas and designed for larger aircraft.

Time Critical Warning

 Warning condition in which time to respond is extremely limited and the response to the alert is the most important action the pilot can make at that specific time (e.g. ground proximity, collision avoidance, windshear, etc.)

Traffic Advisory

A caution level alert - a display indication that there is traffic in the immediate vicininty which could cause a resolution advisory. The information contains no suggested maneuver.

Traffic Information Display

 A display used to provide the pilot with information about TCAS defined intruder aircraft. It may also be used to present information about non-tau based surrounding traffic.

Transponder

 Piece of equipment on own aircraft which when interrogated by a radar signal emits a coded reply containing specific information about the aircraft.

Unequipped Aircraft

An aircraft that has no TCAS system and may or may not have a mode C transponder.

Warning Alert

Workload

- Emergency operational or aircraft system conditions that require immediate corrective or compensatory crew action.
- A relative term indicating the amount of total mental and physical task loading on a crew member.

1.0 INTRODUCTION AND BACKGROUND

1

In mid-1981 the Federal Aviation Administration announced the details of an airborne-based collision avoidance system in a technical working symposium sponsored by the agency. The Traffic Alert and Collision Avoidance System (TCAS) was described in two levels of sophistication. The simplest level, TCAS I, alerts the pilot of proximity of another aircraft with a visual and/or aural alert. This system is directed primarily toward providing some protection for smaller aircraft. The TCAS II system on the other hand is designed for larger aircraft and has a higher sophistication and cost. The capabilities that have been attributed to the TCAS II system include:

- o "It will have the ability to transmit to others (TCAS I and TCAS II equipped aircraft) traffic advisory information (range, bearing, differential altitude, above/helow information).
- o It will provide collision avoidance protection independently from the ground ATC system using vertical maneuvers, with potential expansion to horizontal maneuvers should technical and economic feasibility be demonstrated.
- o Like TCAS I, it will have an integral transponder capable of responding on Modes A, C and S.
- TCAS II will provide alert and advisory information to the aircraft equipped only with TCAS I, while in the case of two aircraft equipped with TCAS II, coordinated advisories would be provided." (1).

As was pointed out in the symposium, much of the technology associated with the TCAS II system was developed under the earlier Reacon Collision Avoidance System (BCAS) program. The technology discussed was primarily sensor and software based providing a detailed description of how the system will generate information about other aircraft. Of equal importance to the overall operation of the system, however, is the presentation of this information to the crew in such a way that it can be used effectively in an operational aircraft.

As was pointed out "it is difficult to evaluate even a limited array of display devices in operational aircraft, and it is similarly difficult to perform comprehensive workload analyses : nce the variety of flight scenerios is necessarily limited by safety considerations." It was therefore planned to answer these questions in simulator studies.

In August 1981, the Roeing Commercial Airplane Company, Crew Systems Group was awarded a contract by the FAA for the purpose of assisting in the determination of flight deck display requirements for operational implementation of the TCAS II system in commercial transport aircraft. The program is a two phase effort, the Developmental Simulation and the Operational Simulation. The first phase combined a number of resolution advisory as well as traffic advisory display concepts with an integrated crew alerting system to be evaluated for effectiveness by Government, industry and line pilots. The second phase will have primarily line qualified flight crews exercise the TCAS II system in a fully certified operational transport training simulator in order to determine the proper operating procedures, identify workload impact, validate the display system and in general give the system an operational "shakedown" prior to entering the TCAS operational evaluation flight test phase.

Since the transfer of information to the crew in a timely manner about an abnormal situation is the definition of an alert, the cornerstone of any display concept for TCAS should be the voluntary guidelines on alerting systems issued by the FAA in 1991 (2). These quidelines were a culmination of seven years of research sponsored by the FAA and directed toward the improvement and standardization of flight deck alerting systems. This work began by studying concepts for an independent altitude monitor (9) for the reduction of inadvertent terrain impact alerts. It was then expanded to consider the alerting problem as a whole and to look at conventional flight deck alerting methods. The findings from these studies (3,4,5) revealed that there had been a significant increase in the amount of information being presented to the crew and that very little effort had been expended in attempting to standardize this information. Pilots were viewing crew alerting as a nuisance rather than a help. In a 1977 report (6) Cooper stated that "caution and warning systems were originally installed as a reasonable means of assisting pilots to maintain safe, reliable, economical system operation in the face of

high workloads. However, these systems, intended to reduce hazards, are themselves becoming hazards. The vast increase in the number of alerts and the frequent occurrence of false or nuisance alerts impose heavy demands on the aircrew. More alerts require more memorization, higher workloads, and could induce a higher probability of error."

The alerting system quidelines which were produced through a joint effort by the Boeing, Lockheed and McDonnell Douglas Aircraft Companies, describe in detail the recommendations for presentation of alerts of any urgency (see Figure 1.0-1). From the research conducted during this program a set of warning level alerts were identified that were defined as "time-critical." The report (2) describes the alerting methods and media for presenting the time-critical warnings. This data is relevant to the present program because one of the warnings identified as fitting into the time-critical category was the collision avoidance alert. Therefore, in selecting the display characteristics to be tested in the developmental simulation it was necessary to review the crew alerting data base and select those characteristics most likely to provide the most effective information transfer. The literature, test results and pilot's subjective input were used to identify the candidate TCAN II display concept.

1.1 Report Organization

Section 2 of this report contains an executive summary of the major activities and findings of the Developmental Simulation testing effort. A general description of the test facility is presented in Section 3. The methodology, equipment, and results of the testing are discussed in Section 4. Discussions of the major findings and the conclusions drawn from these data may be found in Section 5 and Section 6 describes the objectives of the next study phase.

The Appendices at the end of this report describe in detail the test facility. Also included are the questionnaire that were used to obtain pilot input for incorporation into the display concept.

		Alert system characteristics						
Condition	Criteria	Visual	Aural	Tactile				
Warning	Emergency operational or aircraft system conditions that require immediate corrective or compensatory crew action	Master visual (red) plus centrally located alphanumeric readout (red)	Unique attention- getting warning sound plus voice*	Stick shaker (if required)				
Caution	Abnormal operational or aircraft system conditions that require immediate crew awareness and require prompt corrective or compensatory crew action	Master visual (amber) plus centrally located alphanumeric readout (amber)	Unique attention- getting caution sound plus voice*	None				
Advisory	Operational or aircraft system conditions that require crew awareness and may require crew action	Centrally located alphanumeric readout (unique color)	Unique attention- getting advisory sound	None				
Information	Operational or aircraft system conditions that require cockpit indications, but not necessarily as part of the integrated warning system	Discrete indication (green and white)	None	None				

^{*}Voice is pilot selectable.

Figure 1.0-1. Guidelines for Standardizing Alerting Functions and Methods

2.0 EXECUTIVE SUMMARY

2.1 Program Background

In August 1981 The Boeing Commercial Airplane Company began a program sponsored by the FAA for the purpose of assisting in the determination of flight deck display requirements and operational procedures for the implementation of the TCAS II system in commercial transport aircraft. After initial meetings which established the overall objectives, ground rules and a schedule of activities, candidate display concepts for the developmental simulation were formulated. Since the collision avoidance situation must be announced to the crew, the work that has been done in crew alerting was used as a basis for selection of display characteristics, format, location and combinations. The resolution advisory was classified as a time-critical alert and treated as such when identifying presentation methods and information contents. Reference material was established and display combinations identified.

The major objectives of the developmental simulation were: to evaluate the alerting effectiveness of the candidate TCAS display system concepts; to evaluate display sophistication with respect to different levels of flight deck sophistication; to determine the viability of including a caution level alert known as a traffic advisory (TA) prior to presenting the resolution advisory (RA): to identif the minimum information requirements for the RA and TA; and to recommend a TCAS display concept to he used in future testing phases.

2.2 Developmental Simulation Testing

The TCAS displays and a rudimentary set of algorithms were implemented in the Visual Flight Simulation Facility. Thirteen qualified transport pilots with an average of 9,100 hours flight experience, participated in the test. Each flew fifteen test flights of thirty-one minutes in length and was presented a total of 225 alerting situations.

To simulate a flight deck environment and work pattern, a realistic aircraft model was used for the basic flying task. In addition, the pilots were required to fly a prescribed flight plan (takeoff, climb, cruise, descent and landings), respond to ATC directives, locate and report traffic in the external visual scene and respond to the alerts.

The variables investigated in the test include:

- o Resolution Advisory Display IVSI plus voice, LED plus voice, or voice alone.
- o Traffic Advisory Display none, TCAS light, CRT tabular without hearing, CRT tabular with hearing, CRT current graphic or CRT advanced graphics.
- o Percent of encounters not proceeding to a resolution advisory 10% or 50%

The results of this test are summarized below and described in detail in Section 4.

Since any collision avoidance warning (RA) can be defined as a time-critical alert, the primary design concerns when considering the display system to be used are the speed and accuracy of the response. The time taken by the pilots to detect an alert or a change in the urgency level of an alert is directly related to the time taken to respond to the alerts. Of the three basic alert combinations, the initial detection of a red light in the primary field of view and a warning sound (siren) was significantly faster than an amber light in the primary field of view and an advisory sound (chime) which was, in turn, significantly faster than a CRT presentation in the secondary field of view and an advisory sound (chime). These findings suggest that the master light in the primary field of view does aid detection but more important is the type of sound used for the master agral. Detecting a change in urgency level is also dependent on the alerting sequence. The resolution advisory (warning) was detected fastest when it was preceded by the caution level TCAS light. This detection time was significantly shorter than the time when there was no caution at all and the time obtained using the CRT for the caution alerts. No measurable difference was found between the latter two conditions.

The performance data indicates that both the preliminary alert (caution) information and the time-critical display have an effect on the response to the resolution advisory (warning). A direct relationship was found between response time and detection time. The longer it took a pilot to detect the resolution advisory the slower the response performance. The type of resolution advisory display used also had an effect on performance. The modified IVSI display combined with a voice alert resulted in the fastest responses and the voice display when used alone resulted in the slowest.

Even though system reliability was not a specific variable in the objective test, when questioned about the implementation of TCAS (see debriefing questionnaire Appendix D) seventy-five percent of the pilots tested felt that the system should be required on aircraft as soon as it can be demonstrated to nerform reliably. This opinion was not based solely on the configuration used in testing since seventy-five percent (not necessarily the same pilots as above) of the pilots were familiar with TCAS before participating in the test. This interest in system reliability was expressed in the answers to a number of other questions.

With respect to the major system components, (master alerts, traffic advisories, and resolution advisories) the pilots had the following opinions:

o Master Alerts

- Both master aural and master visual alerts should be used to get the crew's attention under all conditions.
- Three levels of tau-based alerts were too many and two levels were recommended, caution (TA) and warning (RA).

o Traffic Advisory

- All the pilots felt that some form of caution alert was needed
- Opinion was split between using a TCAS light or a CRT traffic information display for the caution level information (TA).

- After each pilot had used the CRT traffic display in 96 encounters, sixty-seven percent responded to a question concerning its affect on outside visual scan by indicating that pilots with an automated traffic advisory display could become complacent in scanning especially for non-transponder equipped aircraft. Since the test had no intruders without transponders, the basis of this concern lies in the pilots' operational experience and possibly on the newness of the display. However, it does point to an area for further testing.
- If a CRT traffic information display is included as part of the system, it should present the information graphically using color for urgency level. It should display no more than 3 aircraft simultaneously. Traffic presented on the display should include bearing data, horizontal separation (both range and time) and altitude relative to the own aircraft.

Resolution Advisory

- Ninety-two percent of the pilots listed corrective quidance alerts (climb/descent) as a necessary portion of TCAS. Since no preventive alerts (don't climb/don't descend) were tested in the simulation, the pilots were less sure that these should be included as a necessary part of the system.
- An arrow was selected as the appropriate method for presenting climb and descend quidance.
- Vertical speed should be included on the resolution advisory display.
- Bars or indexes associated with the vertical speed should be used to impose limits.
- The modified IVSI was the display of choice for the pilots

2.3 Candidate System Description

The final effort of the developmental simulation was the recommendation of a traffic and resolution advisory display combination and component characteristics of the displays for the subsequent phases of the program and flight verification. Because the objective of TCAS displays is to get the crew's attention and provide them with information, the recommended configuration closely followed the guidelines set forth by the FAA for the standardization of crew alerting systems.

Since the TCAS information can be classified as alerts, the displays should perform the functions attributed to the alerting system which are:

- o Attract the attention of the crew and direct that attention to the alerting condition so that corrective action can be taken.
- o Inform the flight crew of the location and nature of the alerting condition. Sufficient information should be provided to enable the crew to initiate timely, corrective action.
- o Provide the crew feedback on the adequacy of their corrective action.
- o Provide the crew with a mechanism(s) to control the system to enable them to assess aircraft status quickly, and to identify new alerts.

The need for each of these functions was identified by Cooper (6), Boucek, Erickson, Berson, Hanson, Leffler, and Po-Chedley (8), and in ARP-450D (10). The manner in which these basic functions are implemented will determine the effectiveness of the alerting system. ARP-450D states that "safety of flight is greatly enhanced by an alerting system designed to provide early crew recognition of flight crew operational error, as well as aircraft system or component status or malfunctions". For example, the system should attract the crew's attention to an alerting situation, but should not be so disruptive that it degrades other crew task performance, information processing, or the decision-making required to take corrective actions. The guidelines for designing these basic functions are described in the Aircraft Alerting Systems Standardization Study (2).

To accomplish these functions the following components should be provided:

o Traffic Advisory

A unique sound and amber light on the glareshield should be used as a caution level indication.

o Resolution Advisory

- A unique warning sound and red light on the glareshield should be used to attract the crew's attention.
- Visual resolution advisory display providing quidance using arrows for vertical maneuvers and indexes associated with vertical speed for limits.
- Voice alert with information equivalent to the visual display and continuous until cancelled.

o Traffic Information Display

- Before a CRT display can be recommended as a necessary system component, further testing should be conducted with the traffic information display to assess its impact on system operation.
- Display should provide a color coded (by alert level) graphic presentation of the traffic information including at least bearing, altitude, horizontal separation and vertical direction information.

2.4 Follow-on Verification and Evaluation

Phase II of the study, the Operational Simulation, will implement the concept TCAS II display system in simulation hardware and install it into a motion base cab with full operational capability. The appropriate TCAS software will be implemented to provide fidelity to the alerting situations and to make the findings more generalizable to actual operations.

3.0 TEST FACILITY

1

The various study requirements dictated the use of a facility in which a flight deck system could be integrated, tested and evaluated in a simulated environment. This facility consists essentially of a generic cab that serves as an "operational breadboard" to facilitate the development of flight deck system concepts, functional capabilities, and interface features. Proposed systems, system changes, and alternative mechanizations can be evaluated and demonstrated in such a facility. It also provides a flexible experimental simulation laboratory that allows for easy introduction of new hardware and change to the flight deck system configuration. System software is modularized to facilitate change; interface equipment is flexible and thus allows for wide varieties of engineering developmental evaluations. These elements have been designed into the Boeing Company Kent Flight Simulation Center. See Figures 3.0-1 for an illustration of these facilities. For more detailed descriptions refer to Appendix A.




Figure 3.0.1. Kent Visual Flight Simulation Center

4.0 DEVELOPMENTAL SIMULATION - TEST DESCRIPTION AND RESULTS

The primary purpose of the Developmental Simulation testing phase was to evaluate the TCAS information requirements and develop a set of functional recommendations for the necessary displays. The following sections will describe in detail the simulation test performed to achieve these goals and the results obtained.

4.1 Test Objectives

The TCAS developmental test was designed to evaluate information presentation on both the Resolution Advisory (RA) display and the traffic advisory (TA) display and identify minimum information recommendations. The test was designed to examine the following experimental questions concerning the presentation of TCAS information:

- 1. Does a caution level alert have any effect on the response performance to the resolution advisory?
- 2. How much information is needed to make a caution level alert effective?
- 3. Is there any difference in the use of the traffic information display when the alerts are presented graphically or alpha-numerically?
- 4. Does the response to the resolution advisory change as a function of different display combinations and formats?
- 5. Does the type of resolution advisory display have an effect on resnonse performance?
- 6. Can the pilots use the information on the traffic display to anticipate the resolution advisory?
- 7. Does the certainty of the occurance of a warning have an effect on response or detection performance?

- 8. Is alert detection affected by display combinations?
- On the display combinations have any differential effect on the way a bilot responds to the alert?
- 10. What information is needed for the resolution advisory?
- 11. What information would the pilots like to see on the traffic information display?
- 4.2 Experimental Design

4.2.1 Test Design

The basic experimental design for the developmental simulation was a factorial analyses of variance with repeated measures on at least one of the variables. The design of the test was chosen to evaluate the effectiveness of different combinations of TCAS display types in eliciting an accurate and rapid response from the pilots. The test configuration is presented in Figure 4.2.1-1. There were three independent variables for the test: a) RA display format b) TA display format and c) percent of the encounters which did not proceed to an RA. The RA display variable had three levels: A modified vertical speed indicator combined with voice, an LED presentation combined with voice and a voice presentation without any visuals. The traffic display was presented in six formats: no traffic display at all, an amber TCAS light, a CRT tabular presentation of the range and altitude of the intruder aircraft, a CRT tabular presentation of the range, altitude and bearing of the intruder and two different CRT graphic presentations of the intruder position. Finally, the percent of the encounters which proceeded to an RA was either 90 or 50percent.

Time and resources did not permit the administration of all 36 treatment combinations to every pilot; therefore, the test was administered as illustrated in Figure 4.2.1-1 in two different factorial designs, a 2 x 6 (percent non-RA encounters x Traffic display format) design with pilots nested within the encounter variable and a 2 x 3 x 4 (percent non-RA display format x TA display format) design, also with pilots nested within the encounter variable and repeated measures on the other variables.




Figure 4.2.1-1. Developmental Simulation Test Design

Figure 4.2.1-2 illustrates the arrangement of the alerting components used in the test. Each display combination tested consisted of three basic components, the master alerts, the traffic alert and the resolution advisory. A split-legend master visual alert was located in the pilot's primary field of vision, on the glareshield. The upper half of the master alert was red and lahelled WARNING; the lower half was amber and lahelled CAUTION. The master aural plents were presented over a dedicated speaker located to the pilot's left. The sounds used for the alert levels were consistent with those recommended in the literature (2) and can be described as follows:

- WARNING (RA) A sound characterized as a European police siren. This sound consisted of two tones (high 660 Hz and low 330 Hz) which alternated back and forth at a rate of two times a second.
- CAUTION (TA) A steady sound consisting of two frequencies, 750 Hz and 500 Hz. The sound was present for 2 seconds and then repeated every 10 seconds until it was cancelled or the alert went away.
- ADVISORY (PA) A single stroke chime. A 475 Hz tone was presented with a 50 milliseconds rise and a 1.8 second decay in intensity.

The peak intensity level for the tones were adjusted to approximately 78 dB which was 8 dB above the average ambient noise in the simulator. The signal-to-noise ratio was held constant by an automatic gain control.

The traffic advisories were presented on either an amber TCAS light located on the glareshield or on one of the two CRT's located forward of the throttles. The CRT displays presented the location of the intruder aircraft either in an alphanumeric (tabular) form or a graphic form.

Two displays were used to visually produce the RA alert. A vertical speed indicator which had been modified by adding directional arrows and limit bars (See Figure 4.2.1-3) was located below the altimeter. An LED display which provided directional and limit guidance both graphically and alphanumerically (see Figure 4.2.1-4) was located to the left of the Horizontal Situation Indicator. A voice display was also used to present the RA alerts. The voice




Figure 4.2.1-2. TCAS Alerting System




Figure 4.2.1-3. IVSI Command Display for Simulation Tests




Figure 4.2.1-4. Developmental Simulation LED Display Formats

messages came from the dedicated alerting speaker and were preceded by a 0.75 second presentation of the warning sound. The voice message was repeated until the pilot physically cancelled it or performed the correct maneuver.

Therefore, the sequence of events that occurred for each alerting situation which went to an RA is as follows:

TAH = 45 seconds

PA LEVEL ALFRT - Chime sounds and depending on the test conditions either the TCAS light or the CRT is activated with blue coding (no alert is given at the level if it is an RA only trial).

TAU = 35 seconds

TA LEVEL ALERT - C-chord sounds master caution or the TCAS light illuminates if the CRT is being used the information concerning the TA level intruder turns amber (no alert is given at this level if it is an RA only trial).

TAII = 25 seconds

RA LEVEL ALERT - European siren sounds, the red master warning light illuminates, the CRT (if used) information for the RA intruder changes red and the appropriate RA displays activate (depending on the test condition) with the guidance message.

All of the variables were chosen to evaluate the effectiveness of the system in alerting rapid and accurate responses. Therefore, the selection of each variable had as a basis the amount and type of information presented to the pilot about the intruder aircraft and subsequent evasive action. The rationale for selecting the display types, display formats and non-RA encounter variables are described below.

The traffic display served to provide the pilot with a caution level alert which prepared him for the RA. The format of this "lower" level alert is in question. If the alert were simply a "GET READY" for the RA, then a light could serve this purpose. If on the other hand the pilots could use information about the location and approach of the intruder to increase their confidence in the RA or anticipate the direction of the command maneuver them a more complex alert would be appropriate. Therefore, each of the traffic display formats were chosen because they either provided more information or they presented the information differently. The tabular format providing altitude and range (Figure 4.2.1.5) gave the pilot some indication of the intruder flight path but did not pinpoint the location. The addition of bearing information to the tabular format (Figure 4.2.1.6) suppolied more information to the pilot, but that information had to be accurately converted to a spatial representation. The two graphic formats (Figures 4.2.1-7 and -8) presented this information, and also provided at least a plan view of the spatial relationship. Finally, a recorded version of ATC traffic advisories were presented on one flight for each pilot to provide a baseline condition in the test.

The second variable to be investigated was the type of RA display. Three methods of presentation were investigated in which the pilot must receive the alert, understand it, and act on it in a very short period of time. The modified IVSI had the advantage of integrating vertical guidance with the instrument used to display the vertical speed of the aircraft. This instrument was also compatible with currently used instrumentation. Though the display is located in the pilots' primary field of vision (15° from centerline) in the head down position, it is not when the pilot is head up. Also it was felt that the arrangement of lights on the display may cause confusion, especially for those alerts which require a specified climb rate. The LED display presented graphically and alphanumerically all the RA quidance. It was located on the main instrument panel, however, it could be located on the glareshield where it would be in the pilot's primary field vision both head up and head down. Finally, the voice display was not affected by the direction of the pilot's vision.

RNG ALT
1.6 +7

* 0.7 -16
...

Figure 4.2.1-5. Tabular Threat Display - Without Bearing

CLK	RNG	ALT
2	1.6	+7
* 10	0.7	-16
•••	•••	•••

Figure 4.2.1-6. Tabular Threat Display—With Bearing





Figure 4.2.1-7. Currently Used Graphic Format



Note. Predictor (dashed line) is broken in three segments representing distances traveled in 10 sec. If the total distance is too short, then a solid line is used.

Figure 4.2.1-8. Advanced Graphic Format

The third variable under consideration was the frequency in which a threat at the caution level (TA) became a warning (RA). In the operational sense it is expected that because of its flight path, an aircraft could trigger a traffic advisory and not an evasive maneuver. The question to be answered was that if this situation occurs often will the pilots respond the same to the resolution advisories when they do occur? To answer the question, the traffic advisories progressing to resolution advisories was tested at either 50 or 90 percent of the time.

4.2.2 Intruder Flight Path

In order to make the TCAS alerting situations realistic and to provide a variety of displayed information, a number of different flight paths were developed for the intruder aircraft. These flight paths can be classified into four general categories (see Figure 4.2.2.1). The first category consisted of intruders flying on an intercept course with a difference in altitude of 500 to 1500 feet either above or below the own aircraft. This category was called altitude offset. The second category, known as longitudinal offset, called for the intruder to fly at the same altitude as the own aircraft on a course that would take it .25 to .50 mile either to the front or to the rear. The third category called for the intruder to be climbing or descending into the own aircraft. This maneuver may or may not be accompanied by either altitude or longitudinal offset. This category was referred to as changing altitude flight paths. Finally, the own aircraft was faced with more than one intruder. The intruders were the same altitude as the own aircraft and on an intercept course. They could be either both at the same angle of arrival or have widely different angles. This category was known as the multiple intruder.

4.2.3 Simulation TCAS Logic

A much simplified set of logic was used to activate the TCAS displays. This was possible because the objective of the test was to study the pilots response to the displays in a systematic manner rather than to test the full TCAS system and provide a definitive work on the operational procedures. Therefore, the intruder aircraft flew canned flight paths which activated the




Figure 4.2.2-1. Intrusion Scenarios

displays in the following manner: A proximate advisory (PA) activated when the intruder was 45 seconds from the point of closest approach (also known as TAU). The traffic advisory (TA) or caution alert activated when TAU reached 35 seconds. Finally, the resolution advisory (RA) or warning alert activated when TAU reached 25 seconds. The direction of the RA vertical quidance was always away from the intruder with the smallest TAH value. The vertical rate limits were imposed during flight segments in which the nominal flight path called for a climb or descent profile. The limits were consistent with the expected vertical speed. The correct response to any vertical alert was .25G (8 foot per second squared) vertical maneuver in the appropriate direction. A Change in vertical speed which exceeded the correct response maneuver terminated the alert.

4.3 Pilot Sample

Thirteen pilots with a wide range of experience, including line pilots, instructors, and management pilots, participated in the developmental simulation tests at the Boeing facility. The group consisted of representatives from Boeing, from domestic airlines including American, Republic, United, U. S. Air, and Western, from FAA, and from NASA. A summary of the pilot experience is presented in Table 4.3-1; numerical entries on the right hand side of the table indicate the specific experience by aircraft type and recency of the experience (A is most recent).

4.4 Crew Tasks

4.4.1 Flight Task

To simulate the flight deck environment and work pattern, the pilots performed test flights of 31 minutes duration in the simulator. An aircraft model was used for the basic flying task; the pilots were required to fly a prescribed flight plan, respond to ATC communications, locate targets in an external visual scene and respond to alerts. The flight instrumentation available to the pilots to perform their tasks, shown in Figure 4.4.1-1, consisted of an airspeed indicator; an electronic attitude director indicator (EADI-roll, pitch, glideslope); an altimeter; a rate of climb indicator; a horizontal

Table 4.3-1. Summary of Pilot Experience

	Pilot experience			Specific aircraft experience									
Statistic	Age	TCA's past year	Flight- hours (1,000)	Recency*	707	7 2 7	737	747	DC-8	DC-9	DC-10	L-1011	Other
Mean	43.4	190	9.1	А	1	5	2			2			2
Standard deviation	4.5	209	4.2	В		2	3		1	1	1		3
_	37.0	12	4.0	С	3	3		1			2		
Range	to 51.0	to 600	17.0	D	1		1	1		1		1	

^{*} A is the most recent aircraft flown.

	Pilo	t affiliation	
● FAA	3	● ATA	3
● NASA	1	● ALPA	3
Boeing	2	● APA	1




Figure 4.4.1-1. Flight Deck

situation indicator (HSI-course, DME, localizer); the pilot's time-critical display; and a clock to indicate flight time. The center panel contained the visual information display, the electronic engine instrument display, flaps indicator and gear lights.

The flight controls available to the pilot included: wheel and column with trim; rudder and toe brakes; speed brakes; flap handle; dear handle; fire handles; throttle; response key matrix; and a 12 key input panel.

The tests flight plan is illustrated in Figure 4.4.1-2. It was divided into five flight phases: takeoff, climb, cruise, descent and landing. The pilot performed a visual takeoff (Figure 4.4.1-3) on a heading of 360° at a rate of climb resulting from IAS of 210 knots. The outside visual scene disappeared after takeoff. To achieve a more controlled flight path for the flights, the auto throttle was engaged at 2000 feet and flew the prescribed speed profile for the remainder of the flight. The pilot leveled off and held 15000 feet through turns 1, 2 and 3. At a point 10 miles from waypoint D he received an ATC clearance to descend to 10,000 feet. After executing turn 4, ATC cleared the aircraft to 3000 feet. At 9.5 miles he was further cleared for ILS approach and landing. The glideslope raw data box appeared on the EADI. At one mile and 350 feet the visual scene was again presented for landing. The ATC clearances associated with the flight plan are presented in Table 4.4.1-1.

4.4.2 System Alert Response Tasks

When the pilots detected a system alert, they were required to depress a button located on the left side of the control wheel. This action was used to mark the time that the pilot perceived the new alert. After identifying the specific alert, the pilot performed a prescribed response to solve the problem. Table 4.4.2-1 presents the operational or system conditions that were used, along with their associated responses. As can be seen, the responses were divided between two categories, those that were made with operable system elements (e.g., wheel back, cycle gear, etc.) and those that were made through a response panel by depressing the switch corresponding to the system which had a problem (e.g., L SYS HYD PRESR, ANTI-ICE). The response panel had 18 switches located in the center aisle stand, and configured as




Figure 4.4.1-2. Developmental Simulation Flight path



31

Table 4.4.1-1. ATC Communication

	Distance	Altitude	ATC
1	0	0	Boeing 101: Pinevalley Tower: cleared for takeoff runway 36, wind calm altimeter 29.92. Cleared left heading 310 deg at fix ALPHA, Monitor Pinevalley Approach Control 348.2 after takeoff.
2	21.7 nmi	15,000	Boeing 101: Pinevalley Approach Control: fix COCOA, turn left heading 242 maintain 15,000.
3	29.3 nmí	15,000	Boeing 101: Pinevalley Approach Control: fix COCOA, turn left heading 169 maintain 15,000.
4	71 nmi	15,000	Boeing 101: Pinevalley Approach Control: descend to 10,000, cleared penetration and ILS approach runway 36.
5	90.8 nmi	10,000	Boeing 101: Pinevalley Approach Control: have you starting approach, do not descend below 4,000 feet until DME 9.5 nmi, current winds light and variable altimeter 29.92, monitor Pinevalley Tower 253.8.
6	112.3 nmi	4,000	Boeing 101: Pinevalley Tower: cleared to land runway 36.

Table 4.4.2-1. Operational and System Conditions for Alerts and Their Associated Response

Alert Al		CRT message	Urgency levelb	Pilot's response	Flight engineer's response
Left engine fire	8	L ENG FIRE	w	PULL LEFT FIRE HANDLE	RF FIRE
APU fire	9	APU FIRE	w	PULL CENTER FIRE HANDLE	RP FIRE
Flaps set improperly	10	TAKEOFF FLAPS	w	CYCLE FLAP HANDLE	RP CONFIG
Flaps set improperly	15	LANDING FLAPS	w	CYCLE FLAP HANDLE	RP CONFIG
Right engine failure	11	R ENG FAIL	w	RP ENG STATUS	RP ENG STATUS
Gear not down	12	GEAR NOT DOWN	w	CYCLE GEAR HANDLE	RP GEAR
Overspeed	13	OVERSPEED	w	THROTTLEBACK	RP OVRSPD
Cabin altitude	14	CABIN ALT	w	COLUMN FORWARD	RP CABN ALT
Left generator drive oil	16	GEN DRIVE OIL	С	RPELEC	DISCONNECT
			1		GENERATOR
Gear disagree	17	GEAR DISAGREE	С	RP GEAR	RP GEAR
Right system hydraulic pressure	18	R SYS HYD PRSR	С	RP HYD	CYCLE RIGHT HYDRAULIC SYSTEM
Antiskid inoperative	19	ANTI-SKID INOP	С	RP ANTI-SKID	RP ANTI-SKID
Left air-conditioning pack trip off	20	L PACK TRIP	С	RP ECS	RP ECS
Forward main door open	21	FWD MAIN DOOR	С	RP DOOR	RP DOOR
Right engine oil pressure low	22	R ENG OIL PRSR	С	RP ENG STATUS	RP ENG STATUS
Anti-ice inoperative	23	ANTI-ICE	С	RP ANTI-ICE	RP ANTI-ICE
Autospoiler inoperative	24	AUTO-SPOILER	С	RP AUTO-SPLR	
Altitude alert	25	ALTITUDE	С	RP ALT	RP ALT ALRT
Left bleed off	26	L BLEED OFF	A	RP ECS	RP ECS
Galley bus off	27	GLY BUS OFF	A	RPELEC	CYCLE SWITCH
Utility bus off	28	UTIL BUS OFF	A	RPELEC	CYCLE SWITCH
Right engine hydraulic pump	29	R ENG HYD PUMP	A	RP HYD	CYCLE SWITCH
Left engine fire detector	30	L ENG FIRE DET	A	RP FIRE	RPFIRE
Left brake overheat	31	L BRAKE OVHT	A	RPBRK	RPBRK
Right forward fuel pump	32	R FWD FUEL PUMP	A	RP FUEL	CYCLE SWITCH
Forward cabin call	33	FWD CABIN CALL	A	RP CABN CALL	RP CABN CALL
SELCAL	34	SELCAL	A	RP SELCAL	RP SELCAL

^aRP = response panel

 $^{^{\}mathbf{b}}\mathbf{W}$ = warning \mathbf{C} = caution \mathbf{A} = advisory

Table 4.4.2-1. Operational and System Conditions for Alerts and Their Associated Responses (Concluded)

Alert	Alert code	CRT message	Urgency level	Pilot's response	Flight Engineer's response
Upper yaw damper failure	35	UPPER YD FAIL	С	RP FLT CONTRL	RP FLT CONTRL
Leading edge flaps	36	LE FLAPS	С	RP FLT CONTRL	RP FLT CONTRL
Air-conditioning pressure	37	AIRCOND/PRSR	С	RP ECS	RP ECS
Left generator off	38	L GEN OFF	A	RP ELEC	CYCLE SWITCH
Left bus tie	39	L BUS TIE	A	RP ELEC	CYCLE SWITCH
Right electric hydraulic pump	41	R ELEC HYDPUMP	A	RP HYD	CYCLE SWITCH
Autothrottle disconnect	43	A/T DISC	С	RP A/T	RP A/T

seen in Figure 4.4.2-1. Caution and advisory level alerts were always responded to through this panel. When the pilot made the correct response, the alert message was removed from the screen, the master visual alert was extinguished and the aural alerts were silenced.

4.4.3 TCAS Alert Response Task

When the pilots detected a TCAS alert they responded by pressing the button on the left hand side of the control wheel. This action marked when the alerts were detected. They were also required to respond with this button each time the alert changed urgency levels, i.e., advisory to caution or caution to warning. For those encounters in which the intruder aircraft was visible, the pilot was also asked to push the right hand button when he had identified the aircraft. After the alert had proceeded to the resolution advisory alert the pilot performed the maneuver that was displayed. They were instructed to achieve approximately a .25G climb or descent to an excursion of 1000 feet per minute on the IVSI. When the pilot made the correct response (i.e., aircraft achieved .25G vertical acceleration in the correct direction), the alert was discontinued. A second type of resolution advisory was also possible. This alert type called for the pilots to limit a vertical maneuver that they were already performing. Examples of the two types of alerts are presented in Figure 4.4.3-1.

4.5 Test Procedures

1

The variables tested in the developmental simulation are described in section 4.2.1. All variables not tested were held constant or controlled to avoid hiasing or confounding the results. Simulated aircraft ambient noise with an average intensity of approximately 70 dB was presented during the flight task to mask the uncontrolled noise that may have been occurring around the cab. The ambient noise was controlled by throttle position and airspeed to provide a realistic sound spectrum based on aircraft performance. During each flight, variations of the noise level were kept within the range of 67dB and 72dB. The ambient light levels were kept very low (5 ft-L) to permit the use of the outside visual scene. ATC communications were presented at 75dB and held constant for all trails; visual message contrast was also held constant for all trials. All pilots received the same instructions to minimize experimenter bias (see Appendix B).




Figure 4.4.2-1. Pilot's Response Panel




Figure 4.4.3-1. TCAS Resolution Advisory Alerts and Example IVSI Presentation

Each test flight was 31 minutes in length and contained 15 alerts: twelve TCAS intrusions and three system alerts. This number of alerts is not indicative of the number expected in actual system operation. A larger than expected number of alerts were chosen for the simple reason that to obtain a sufficient amount of data with realistic time periods between the resolution advisories would have required testing time far in excess of the scope for the study. The effect on the data of using a higher rate of alert occurences was to reduce somewhat the surprise and uncertainty factors, thus making the response and detection times shorter than would be expected in actual operation. These times were also affected by the fact that the pilots knew that it was a TCAS test and were expecting the alerts. Therefore, the times obtained for the test cannot be directly applied to operational situations. This does not, however, mean that the data cannot be used. Since all display combinations were used with the same number of alerts, the relative differences in time between these combinations do give an indication of the information transfer occurring with the displays. This kind of result meets the objectives of the test. Therefore the number of alerts combined with a relatively high workload to keep the pilots involved in flying do provide appropriate information in a cost effective manner. The alerts were presented on a schedule of two minute intervals; however, to help prevent the pilot's anticipation of the alerts, a 45 second interval around each two minute mark was allocated for the alerts. The alerts could therefore be presented as close together as 30 seconds. The times were chosen at random, and 12 different time scenarios were developed. The only restriction on the time selection was that no alert could occur after 30 minutes into the flight to permit the pilot at least 60 seconds to respond to the last alert. To reduce the possibility of influencing the data by the order in which the alerts were presented, 12 random alert orderings were developed and combined at random with the time scenarios to produce the test scenarios.

Whenever task performance is measured under several different treatment conditions over an extended period of time, learning or fatigue may affect performance on later trials. Care was taken to design an appropriate counterbalancing scheme to prevent carry-over effects from differentially affecting the performance measures for the different treatment conditions. It should be noted, therefore, that the order in which the pilot received the

experimental treatments was also randomly assigned to prevent order bias from confounding the results (see Table 4.5-1). Immediately prior to each flight the pilot was briefed on the alerting system configuration that he would be using.

The daily test schedule for the developmental simulation tests is presented in Table 4.5-2; all pilots were to fly only one non-encounter condition. Two pilots were tested each week spending two days per pilot in the simulation.

The test participation began with an introduction to the Visual Flight Simulation Facility and a review of the program. The pilots were briefed on the flight plan and given the nominal flight path parameters (see Figure 4.4.1.2). They were encouraged to take notes on their briefing sheet and to use them during flight. Following the briefing, the pilots entered the cab for instruction on the operational characteristics of the simulator and the test flight tasks (see Appendix B for the briefing checklist).

The pilots were informed of the basic tasks to be carried out during each flight. The first involved flying the simulator from take-off to landing on the specified flight plan. The second was responding to the alerts which was done by performing the prescribed actions associated with each alert.

Before participating in the data collection flights, each pilot made a series of practice flights. The purpose of these flights was twofold - to acquaint the pilots with the flight characteristics and dynamics of the simulation airplane model and the flight plan; and to become proficient at performing the correct alert responses. The first practice flight was 31 minutes in which the complete flight pattern was flown. There were no alerts to distract the pilots during most of this flight. The instructions on how to respond to the alerts were explained during the practice flight, and any questions the pilot had were answered. The second practice flight included a short segment after take-off in which TCAS alerts were presented in order to familiarize the pilots with the correct TCAS responses. Then the alerts were repeated and the pilots were asked to respond to them by performing the corrective action. The time for training was two and one half hours.

Table 4.5-1. Random Treatment Assignments

	Graphic 2	15	13	9	8	3	11	4	2	15	9	6	7	41
Voice	Tab 1	14	ı	ε	7	11	13	10	6	4	14	8	12	5
Š	Light	13	9	4	6	15	10	9	11	ε	4	13	1	11
	None	12	2	14	9	8	ဗ	Ĺ	13	12	1	11	4	10
	Graphic 2	11	10	6	15	1	2	14	9	4	8	12	9	7
LED	Tab 1	10	7	8	5	4	15	2	3	6	12	14	10	-
3	Light	6	က	2	11	14	9	12	4	9	13	ı	15	6
	None	80	7	15	10	4	12	1	14	2	6	3	9	13
	Graphic Graphic	7	14	12	3	9	6	5	8	13	10	4	11	2
	Graphic 1	9	9	10	13	9	7	6	1	8	4	15	2	12
) Si	Tab 2	മ	12	9	1	6	14	8	7	11	15	2	13	3
IVSI	Tab 1	4	8	13	12	2	4	15	2	1	11	10	3	9
	Light	3	6	11	4	13	5	11	10	14	3	7	8	15
	None	2	=	2	14	12	1	3	15	10	2	9	6	8
ATC	ATC	-	15	-	7	10	8	13	12	9	5	2	14	4
	Threat display	Flight number												
Command display	Subject	number	-	4	5	7	10	12	2	က	9	8	on .	=
S disi				10% Non-RA	encounters					à	Non-RA encounters			

Table 4.5-2. Daily Test Schedule

	Day 1
000 - 1:00 0:30 - 2:30 2:30 - 4:30	Cab warmup and preflight Pilot training Flights 1 through 3
4:30 - 5:15 5:15 - 6:30 6:30 - 6:45 6:45 - 8:00	Lunch Flights 4 and 5 Break Flights 6 and 7
	Day 2
000 - 1:00 1:00 - 3:00 3:00 - 3:15 3:15 - 5:15 5:15 - 6:00 6:00 - 7:15 7:15 - 8:00	Cab warmup and preflight Flights 8 through 10 Break Flights 11 through 13 Lunch Flights 14 and 15 Pilot debriefing

The test day consisted of eight flights with approximately four hours of flying. Brief rest periods were taken throughout the day in an effort to reduce fatique. After each test flight in which a new display was introduced the pilots were given a short questionnaire (see Appendix C) to evaluate the display. Upon completing the data collection flights the pilots participated in a short debriefing session. Their impressions of the TCAS concepts and the application of these concepts were solicited. The formal debriefings included an informal discussion between the pilots and experimenter and relevant pilot comments were recorded for further evaluation. The pilots were then given an extensive questionnaire which they were to complete and return at a later date. (See Appendix D).

4.6 Measurement Technique

4.6.1 Performance Measures

The performance measures used in the tests fell into two categories - those associated with the flight task and those associated with the alert response tasks. The parameters that reflect how well the pilot performed the flight task included altitude deviations, wheel and column reversals, landing performance, accuracy of detection of the outside visual targets. The parameters were especially important for the time period immediately around the alerts because they provide a measure of the efficiency and effectiveness of the pilot in performing the flight maneuver. A second set of dependent variables, used to quantify the responses to the alerting system, included the time and accuracy of alert detection, and the time and accuracy of the response to the alert.

4.6.2 Subjective Measures

Finally, subjective data expressing the pilot's opinions about the various alerting system characteristics were gathered for all test configurations. The pilots were asked to comment on and rate the effectiveness of the candidate TCAS displays, clarity of the message, format and system components.

Ouestionnaires were administered immediately after each flight in which a new display was introduced so that the pilots could establish their reaction to the display while it was still fresh in their minds. These questionnaires were very brief and directed specifically toward a display used in the preceding flight.

After completing the entry test sequence the pilots participated in a debriefing which permitted them to provide inputs after experiencing all configurations. This debriefing consisted of an informal interview after the last flight and an extensive questionnaire (See Appendix D) which the pilots were asked to take with them, complete and return at a later date. The debriefing questionnaire was in two sections: the first directed toward biographical and experimental data; and the second section was directed toward the pilot's opinion about collision avoidance systems in general and the test display configurations specifically.

A number of different types of questions were asked in the second section to provide the pilots with the maximum flexibility for expressing their opinion. The first type of question used was the rating scale in which a question was asked and the pilot was given a scale with which to answer. An example of the type of questions would be:

How useful is including the vertical speed on the resolution advisory display?

Extremely	Useful	Of No	Netrimental	Extremely
Useful		Use		Detrimental

The second type of question was the forced choice question in which the pilot was asked to select the best of a number of alternatives. For example:

In what intervals should the altitude information be given?

a.	One foot	
b.	Ten foot	
с.	Hundred foot	
d.	Thousand foot	

The third type of question was rank ordering in which the pilots were given a list of alternatives and asked to rank them from best to worst. The fourth type of question was the open-ended pilot opinion in which the pilot is asked the questions and then given space to provide his answer. For example:

What information should a collision avoidance system provide?

This type of question provides for a written structured interview.

The next technique is called semantic differentiation which was used to develop opinion profiles. The semantic differential provides a means to judge opinion in a systematic way. The scale was developed by using a series of polar adjectives and requiring the pilots to indicate where their opinion falls between the ends of the scale. An example of this type of question would be:

Suppose the pilot is asked to judge one of the TCAS display options on the following scale:

Good				Bad

If he feels that the display is very good he would check the hox nearest that adjective. An opposite reaction would result in a check at the other end of the scale and a neutral opinion would result in the center hox being marked.

Finally the pilots were asked to design their ideal system including necessary components, information requirements and the format of the displays. They were asked to relate the system to both a conventional and advanced flight deck design.

4.7 Data Reduction and Analyses

The data obtained in the Developmental Simulation testing falls into two general categories - objective (or performance) data and subjective (questionnaire/debriefing) data. A time-based tabulation of all events that occurred in the cab, switch and light states, displayed messages and fault situation initiation, was generated from the data. From this tabulation, sums, means and standard deviations were calculated for all performance variables. The performance was analyzed with respect to all the alerts and was also partitioned from the various alert categories. Analyses of variance were performed on the reduced data to determine if the various treatment conditions had a differential affect upon performance. The statistical model used for the data reduction was the analyses of variance. As described in Section 4.2, two separate analyses were performed both of which were mixed designs. All of the pilots had treatment conditions associated with a nortion of the variables but one variable (percent no-RA encounters) divided the pilots into two groups. The model and source table for this type of analyses is presented in Table 4.7-1.

Since developmental testing requires that system developers be very sure before they reject any candidate system concept, and since the time critical tests were exploratory in nature, an error probability of .10 was selected as a test for significance for the statistical tests performed on both experiments.

4.7.1 Experimental Hypothesis

The following were the hypotheses upon which the tests were based:

 Pilot detection time is not affected by the type of alert (i.e. warning versus advisory).

Table 4.7-1. Sample of Analysis of Variance Model and Summary Table for a Factorial Experiment With Repeated Measures on Some of the Factors

Model						
$X_{ikj} = \mu + \sigma_i + \gamma_{k(i)} + \beta_j + \sigma\beta_{ij} + \beta\gamma_{jk(i)} + \epsilon_{k(ij)}$						
	Summary table					
Source	Expected mean square	F ratio				
A	σ_e^2 + ba σ_s^2 + nb σ_A^2	MS _A /MS _{sub}				
Subject within A	$\sigma_{\rm e}^{\ 2}$ + ba $\sigma_{\rm s}^{\ 2}$					
В	$\sigma_{\rm e}^2$ + a $\sigma_{\rm Bs}^2$ + na $\sigma_{\rm B}^2$	MS _B /MS _{Bs}				
A×B	$\sigma_{\rm e}^2$ + a $\sigma_{\rm Bs}^2$ + n $\sigma_{\rm AB}^2$	MSAB/MSBs				
B x subjects within A	$\sigma_{\rm e}^2$ + a $\sigma_{\rm Bs}^2$					

Note: The example is a two-factor experiment with repeated measures on one factor.

- 2. The presence or absence of the traffic alert will not have an effect on the detection of the resolution advisory.
- 3. The type of traffic advisory presented will not affect the initial detection time of the alert.
- 4. The percent of none-RA encounters will have no effect on detection time.
- 5. ATC traffic advisories will be detected just as fast as any internal alert.
- 6. The location of the traffic advisory visual alert has no effect on detection performance.
- 7. The type of traffic advisory has no effect on the pilots response performance.
- R. The presence or absence of a traffic alert has no effect on response performance.
- 9. Voice presentation of the resolution advisory is just as effective as voice combined with visual in producing the correct response.
- 10. The IVSI and LED resolution advisory displays are equally as effective as measured by response performance.
- 11. The percent non-RA encounters will have no effect on response performance.
- 12. Altitude change during the response will not be related to any of the test variables.
- 13. The accuracy of the pilots' response will not be related to any of the test variables.

4.8 Test Results

Although some of the results reported in the following sections as being statistically significant may appear to be of insufficient magnitude to be of practical importance, this may be a false assessment of the results due to the nature of the tests. It must be kept in mind that the pilots knew alerts were going to occur during the flight, and the anticipation of the alert resulted in a response that was faster than would normally occur. The speed that a pilot can respond to an alert is a function of certain physical factors such as recognition and reaction times. As a pilot responds faster he approaches these physical limits. As these limits are approached it is found that the response times tend to group or stack up at the low end of the scale. This factor has the effect of reducing the spread of response time scores. Another example of this type of effect can be seen in a simple physical experiment of throwing a hall. Imagine 100 neople throwing a ball as far as they can. Each person's score would be the distance their ball traveled. For the first throw there is a spread of scores from say 50 to 190 ft. and the distribution of scores was bell shaped with the most scores occurring at 120 ft. Now for the second throw a large wall is built at 100 ft. All those people who can't throw further than 100 ft. will throw just like they did at first. However, the rest of the people will hit the wall and it will look in their scores like they can only throw 100 ft. This will reduce the spread of the scores thus reducing the variability of the results. In the actual TCAS operation, it is expected that the pilots will not be anticipating the alerts and therefore the overall response times will be slower getting them away from the "wall" of the physical parameters and permitting a wider range of times. This would have the effect of increasing the observed size of any real differences that exist between the experimental treatments (14, 15, 16).

4.8.1 Detection Times

Detection time has been defined as the time from the initiation of the alert to when the pilot first noticed that either an alert had occurred or any existing alert had changed urgency level. These two detection times actually have different meanings in the alerting paradigm. The initial detection is a measure of the attention getting quality of the alert. Alert change detection, on the other hand, reveals how well the alert is transmitting urgency information and could possibly provide a measure of complexity.


The analysis of variance summary tables for the initial detection time is presented in Table 4.8.1-1. The main effect attributed to the alert display was signficant (F=15.99 df 6.60) and can be seen in Figure 4.8.1-1. Using Duncan's New Multiple Range test it was discovered that the CRT display and sound (4.84 seconds to 5.25 seconds) were detected significantly slower than either the TCAS light and advisory sound (4.20 seconds) or the resolution advisory with no caution alerts (2.50 seconds). Looking at the detections for each level of urgency the proximate advisory (PA) is detected signficantly slower (as expected) than either the traffic alert (TA) or the resolution advisory (RA) for all the display types (F=55.8 df 2.12). As can be in Figure 4.8.1-2 using the TCAS light as the caution alert resulted in the shortest detection time (1.46 sec) for the RA. This time was signficantly shorter than either the 2.52 seconds for the RA without cautions (t=8.1 df 22) or the 2.15 seconds when using the CRT as a for caution alerts (t=1.9 df 22). The detection of the ATC traffic advisory is comparable to using the advisory sound and CRT. Finally, the percent of encounters that progressed to an RA had no effect either on the detection of the initial alert or on the detection of the RA. Nor were there any interactive effects between the alert type and the percent of non-RA encounters.

4.8.2 Response Times

The analysis of various summary tables for the response times is presented in Table 4.8.2-1. The mean effect attributed to the traffic display was significant (F=2.34 df 3,30) with the mean response time for the RA which was preceded by the TCAS light (3.49 seconds) being significantly shorter than for those conditions with either no precursors (4.57 seconds) or when the CRT was used as a precursor (4.6 seconds to 4.38 seconds). This result may be misleading, however, due to the composition of the response time. Each response had two components, the time to detect the alert and the time to respond. As can be seen in Figure 4.8.2-1 the significant differences found in the response time is due solely to the differences in the RA detection times. When the component is factored out, there are no measurable differences in the response times among the treatment conditions.

Table 4.8.1-1. ANOVA Summary Table for Initial Detection Time

Source	Sum of squares	Degrees of freedom	Mean square	F	Probability F exceeded
Mean	1,930.05	1	1,930.05	457.05	0.0
Non-RA (N)	5.11	1 1	5.11	1.21	0.2
Error	42.22	10	4.22		{
Alert display (A)	80.84	6	13.47	,	
AN	2.30	6	0.38	15.98	0.0
Error	50.55	60	0.84	0.45	0.8



*All visual displays were accompanied by a master aural alert.

Figure 4.8.1-1. Initial Detection Time as a Function of Alert Display




Figure 4.8.1-2. Alert Detection Time-TA Display

Table 4.8.2-1. ANOVA Summary Table for Response Times

Source	Sum of squares	Degrees of freedom	Mean square	F	Probability F exceeded
Mean	5,406,86	1	5,406.86	816.34	0.00
Non-RA encounters (N)	4.39	1	4.39	0.66	0.43
Error	66.23	10	6.62		
RA display type (R)	182.85	2	91.42	51.71	0.00
RxN	1.10	2	0.55	0.31	0.73
Error	35.35	20	1.76		
TA display type (T)	8.91	3	2.97	2.34	0.10
TxN	1.66	3	0.55	0.43	0.72
Error	38.21	30	1.27		
RxT	3.10	6	0.51	0.32	0.92
RxTxN	8.24	6	1.37	0.86	0.52
Error	95.36	60	1.58		
Vertical maneuver (V)	1.12	, ,	1.12	1.57	0.23
VxN	1.10	1 1	1.10	1.56	0.23
Error	7.11	10	0.71		1
RxV	0.49	2	0.24	0.21	0.80
RxVxN	0.81	2	0.40	0.35	0.70
Error	22.75	20	1.13		
TxV	1.25	3	0.41	0.38	0.76
TxVxN	1.39	3	0.46	0.43	0.73
Error	32.18	30	1.07		
RxTxV	5.77	6	0.96	0.95	0.46
RxTxVxN	8.69	6	1.44	1.43	0.21
Error	60.60	60	1.01		1




Figure 4.8.2-1. A Comparison of Response and Detection Times as a Function of the Traffic Display

The main effect attributed to the resolution advisory display was also significant (F=51.71 df 2,20). The mean response time for the voice only condition (5.45 seconds) was significantly longer than for either the IVSI (3.63 seconds) or the LED (3.94 seconds) display. When combined with voice even though the IVSI display consistantly produced shorter response times than the LED display, the mean differences were not statistically significant. When the response times are again partitioned into these two components it can be seen (Figure 4.8.2-2) that the differences observed between displays are due in this case to the response to the display rather than the detection of the RA condition. The detection time curve has no measurable difference across the displays while the response curve does exhibit the pronounced difference for the voice display.

4.8.3 Missed Alerts and Incorrect Responses

The pilots responded to all of the alerts. In all cases the direction of response was correct. This result corresponds to the data obtained from previous alerting studies in which no warning level alerts were missed. There were some alerts, however, which though correct in direction were not of the prescribed magnitude (8 feet per second squared) and therefore were not included in the data. This set of responses (105) constituted eight percent of the total number of responses (1380) and was not concentrated in any one treatment condition.

4.8.4 Pilot Input

The debriefing questionnaire is presented in Appendix D. Ninety-two percent of the pilots who participated in the simulator tests returned a completed questionnaire. The majority (75%) of pilots participating in the test were familiar with the TCAS program prior to testing. This fact does not make the opinions expressed any less usable; however, it does suggest that the test design and display configurations may have had less impact on the opinions of this group of pilots than they would have had on a less informed group. The most often stated aspect required of the TCAS system was reliability. Seventy-five percent of the pilots felt that the system should not be required on aircraft until it can be demonstrated to perform reliably. The three criteria that were mentioned for system implementation were:




Figure 4.8.2-2. Comparison of Response and Detection Times as a Function of the Resolution Advisory Display

- o System Reliability
- o Economic Reasonability
- o ATC Compatibility

System unreliability was most often given as the only reason for the pilot not following the RA quidance. Seventy-five percent of the pilots felt that the system should be designed so that the pilot would not be justified in refusing to do the RA maneuver. In reviewing the test system, all of the pilots said they usually agreed with the quidance presented. Some concern was voiced, however, that when they did not agree with the alert (for whatever reason), there was some hesitation in following it.

When considering the operational environment eighty-four percent of the pilots responded that horizontal maneuvers should be considered in the TCAS system for those situations where a vertical maneuver may be inappropriate such as: when operating close to the ground or obstacles; when close to performance limits of the aircraft; when given a hard altitude by ATC; to eliminate crossing altitudes; in high density situations. Agreement was not reached on changes in the amount of communication that will be required with ATC, forty-two percent saw a decrease and sixteen percent said that it would remain unchanged. There were some changes in operational procedures that were identified as being required for TCAS implementation. These were: providing the Captain with emergency authority to break clearance due to an RA; provide for an automatic transmission to ATC when an RA occurs; defining who has authority if ATC and RA should provide conflicting commands. Finally the pilots report that even though there should be no reduction in present traffic separation. (75%), they would feel more confident when overflying another aircraft and that TCAS would result in a safer operational environment (1009).

In conjunction with opinions concerning general system operations, it was also an objective to obtain more specific reactions to the system features. The following will be a summary of those questions dealing with the three major system components, the master alerts, the resolution advisory and the traffic

information display. Eighty-four percent of the nilots responded that both an aural and visual master alert were needed to get the crew's attention under all conditions. Ninety-two percent of the pilots rated the aural sounds used in the test as either good or excellent. It was indicated, however, that three levels of alerting urgency were too many and only two levels were recommended, caution (TA) and warning (RA). The attention getting quality of the master alerts was also rated as good to excellent by ninety-two percent of the pilots. Changes that were recommended concerning the master alert were primarily directed toward the timing sequences. Some of the pilots were bothered by the fact that the tone and the light and the CRT displays did not all come on at the same time. This lack of coordination was caused by the way that the alerts were initiated because the aural alerts had a direct path to the main computer and the visual alerts were dependent on the BEU update rate (2 seconds). This problem will be solved for future testing.

All of the pilots felt that some form of caution level alert would benefit the TCAS system. The reasons most often given for having the caution alert (84%) were to reduce the startle effect of the RA and to prepare the crew for possible action. The answer to the question of how to provide this preliminary alert was not so clear cut. Forty-five percent of the pilots reported that an amber light should be used and fifty-five percent wanted to see a graphic CRT presentation. In conjunction with this result, sixty-seven percent of the pilots expressed concern that an automated traffic advisory display (CRT) could lead to pilot complacency with insufficient visual scan time being devoted to nontransponder-equipped aircraft.

The data indicates that if a traffic information display is included it should present the information graphically (100%) using color for the urgency level (100%). The average number of traffic advisories that the pilots felt they could monitor simultaneously while attending to flight duties were 2.5 intruders and the range of responses was from zero to five intruders. As can be seen in Figure 4.8.4-1 the graphic displays were considered more useful than current ATC traffic advisories. If hearing information is included on the tabular display, the pilots considered the display equally as useful as the ATC traffic advisories; however, the majority of the pilots (75)% commented that this was true only for a single intruder. If multiple




Figure 4.8.4-1. Pilot Opinion Concerning the TA Display Usefulness

intruders were present, the tabular display was much more difficult to use even with bearing information presented on the displays. The graphic displays were rated the least ambiguous and the tabular display without bearing information, the most. The advanced graphic display was the most preferred CRT traffic advisory format, being preferred by ninety-two percent of the pilots.

There was no consensus among the pilots as to what traffic should be presented if a CRT type of display is available. Thirty-three percent of the pilots felt that only threats as defined by TCAS should be presented and thirty-three percent felt that TCAS threats should be presented with the option of displaying surrounding traffic when a threat is present, finally thirty-three percent felt that the surrounding traffic should appear automatically when a TCAS threat is present. When an intruder is shown on the CRT, the majority of pilots required the following information about it: bearing data (67%); horizontal separation (75%) both range and time; and the altitude of the intruder if known (100%) relative to own altitude (75%) and in hundred foot increments (92%). Other information that some of the pilots would like to know about the intruder includes: direction of vertical movement (33%; closure rates (33%); heading or track (25%); and vertical speed (17%). One option available on the traffic display is to permit the intruder aircraft to remain on the display after a corrective maneuver has been accomplished, to show the pilot where it went. The majority of the pilots tested (67%) felt that this feature would not be useful. When investigating the traffic information display utility with respect to flight phases the pilots felt that it would be most useful in the climb, cruise, descent and approach phases and least useful during takeoff and landing.

The third component of the TCAS display system is the resolution advisory display. Ninety-two percent of the pilots tested felt that corrective types of RA's (e.g., CLIMB or LIMIT DESCENT to 500 fpm) are necessary to the system and only thirty-three percent felt that predictive alerts (e.g., don't descent) are necessary. Sixty-seven percent of the pilots rated the corrective alerts more critical than the predictive while none of the pilots selected the opposite rating. For the presentation of the corrective alerts, an arrow was selected as the most appropriate indication of a vertical

maneuver (100%). Since the present system only provides for vertical resolution advisories, ninety-two percent of the pilots indicated that the vertical speed should be included on the resolution advisory display. Considering these responses it is not unexpected that the modified TVST was rated the clearest, least ambiguous resolution advisory display (see Figure 4.8.4-2) and the LED display the least clear, especially by those pilots who saw both vertical maneuver alerts and vertical limit alerts.

Care must be used in selecting the voice messages. During the test a number of occasions were reported where the pilot mistook the voice alert "Limit climb two thousand feet per minute" as being "Limit climb to a thousand feet per minute". Ninety-two percent of the pilots felt that the modification of the IVSI did not detract from the primary purpose of the instrument and that the use of color did help the interpretation of the information presented.

Some of the changes suggested for the displays used in the test include:

- IVSI make brightness adjustable
 - add horizontal maneuver arrows
 - indicate required climb rate
 - make needle more visible
- LED reduce complexity
 - make brightness adjustable
 - move to glareshield
- VOICE reword messages to eliminate ambiguity
 - automatically cancel after two repetitions
 - make more urgent

Finally, all of the pilots felt that the alerts provided them sufficient time to react and the pilots usually agreed with the resolution advisory.




Figure 4.8.4-2. Pilot Opinion Concerning the RA Display Clarity

5.0 DISCUSSION AND CONCLUSIONS

Since any collision avoidance warning can be defined as a time-critical alert, of primary importance when considering the display system to be used is the speed and accuracy of the response produced. Therefore, anything that increases the speed of alert detection and response without having an adverse effect on response accuracy should be considered in the system recommendations.

Care must be used when interpreting the results of this experiment and their real world significance, because the pilots know that alerts are going to occur during any experimentation with crew alerting. When investigating time-critical alerts especially, the time between alerts must be artificially short because the experiments would not be very cost effective if a more realistic time scale were used. Therefore, in the present study, the pilots were expecting the alerts and their responses were faster than they would normally be. They were also faster because the pilots did not have to complete the entire evasive maneuver for their response but rather they only had to attain an acceleration of .25G. These constraints lead to a skewing of the data toward zero and reduced the differences among treatment means raising the level of difficulty in discovering significant differences between the means. Therefore, any effects that were found to be statistically significant should be considered even though they may not look to be of practical significance, since it is expected that the differences will become larger in real life situations.

The results of the study indicate that not only the initial detection time but also the change detection time is very sensitive to the alerting displays. The initial detection time was dependent on three basic alert combinations: a red light in the primary field of view with a warning sound; an amber light in the primary field of view with a chime; and a CRT display in the secondary field of view with the chime. Each of these combinations produced a significantly different mean detection time from the others. The warning light and sound producing a faster detection than the amber light and sound even though the amber light had twice the lighted surface area than the red light. The warning alert also had a voice component which could have been

contributing to detection performance; however, if this were the case, the ATC traffic advisories should have been detected faster than the TCAS light. This was not the case. These results tend to indicate that the sound characteristics were more important in attracting the crew's attention. It shows that for warning situations, especially when time is critical, a chime may not be able to produce sufficiently rapid response times. The results, that show significantly faster detection with a light in the primary field of view than with a visual display in the secondary field of view, are consistent with previous studies (7,8) and indicate that if the alert requires immmediate attention, a visual alert should be located in the primary field of view and combined with a sound that is appropriate for the urgency level.

The next question to answer is whether or not the caution or "get ready" alert is benefical and how much information does it need to supply to the crew. If the system is going to use multiple urgency levels, the detection of level change becomes an important factor. The TCAS light represents the least complex caution alert. The only information that it carries is the fact that an intruder aircraft has come to a caution level position. This alert resulted in a significant improvement in the RA detection time when compared to RA's which had no previous caution. One might then ask, if a little bit is good, should more be better? The conditions that used the CRT display for traffic had two alert levels before the PA. With the urgency levels changing every ten seconds you would expect that having two urgency levels before the RA would be as good or better than the single level and signficantly better than with none at all. This was not the case. As the results show, the RA detection with the CRT traffic displays was signficantly slower than with the TACS cuation light. There was no measurable difference between having a CRT for the lower level alert and having no caution at all. This finding indicates that something else is overcoming the advantage created by using the CRT as a for the caution level alerts. If the RA is considered an intruding task when the pilot is using the traffic display, a workload explanation can be postulated for the increase in detection time. Rolfe (12) has shown that as workload increases the performance of other tasks decreases. Therefore, as the traffic display presents the pilot with an increase in information it becomes more difficult for the resolution advisory to attract his attention and therefore for him to start the correct response. The response performance also

indicated this effect. Response time to the RA which followed the TCAS light (TA alert with the least information) was significantly shorter than the times for the RA response following a CRT presented TA. It was further found that when the response time was broken into its two components, the detection component and the response component, the former was the driving factor in the overall time. This indicates that when the time to respond is the only measurement criteria, the sooner the pilot gets the critical information the faster he will respond. In the case of this study, the critical information was the quidance presented on the resolution advisory display.

Another benefit attributed to the information on the CPT display is that it will permit the pilot to anticipate the direction of the resolution advisory maneuver if he is familiar with the algorithms. In order to look at this effect, the pilots were briefed that the resolution advisory would always direct them vertically away from the intruder (i.e., if the intruder is above the RA will be "Descend"). With this type of instruction, the pilots should have been able to use the positional information on the CRT to prepare for the RA maneuver and thus perform the maneuver faster than when they did not have the information. Even though sixty-seven percent of the pilots reported that they were using the CRT information to anticipate the RA maneuver, the performance data do not support this result. As pointed out above, the differences observed in response performance were due almost exclusively to the differences in the time to detect the resolution advisory. Once the alert has been detected, the response is not dependent on the amount of information the pilot had prior to the alert.

The resolution advisory display did have an effect on the pilots response performance, and when the response times were partitioned into the detection and response components it was found, as expected, that the differences were due to the response component. Therefore, the presentation media and format of the RA information was affecting the pilots response. The modified IVSI when combined with voice resulted in the quickest responses and the voice alone the slowest. The results support the pilots contention that they were using the visual display to initiate the action and the voice to verify response accuracy. To accomplish this procedure with the voice display alone would require extra time due to the serious nature of the voice message.

These data support previous findings, a summary of which can be seen in Figure 5.0-1, (13) which indicate that the best presentation method for information which requires rapid action is by using a combination of voice and visual displays. The complexity of the information presented on the visual display seems to have been a contributing factor to the response and preference differences between the IVSI and LED displays. The nilots felt that the LED display was overly complex and the data tend to support this feeling. Even though both displays presented a directional arrow for the alert, the response to the LED was consistently slower than to the IVSI. The increase in visual complexity with the tri-color background could have caused the difference. The lack of a dynamic vertical speed indication on the LED display was discussed as a major drawback for the vertical limit alerts as was the perceived ambiguity of the display.

The pilot inputs have been reported in the results section and in previous studies (4,6,7,8). They support a system that has two levels of urgency, caution and warning, with master alerts, both visual and aural, announcing each level. The resolution advisory display should provide quidance information in as straight forward and least complex manner as possible. Arrows should be used to show the direction of the prescribed maneuver and bars or some other index should be used in conjunction with a vertical speed indicator to set vertical limits. Color is desirable but too much color confuses the display. The voice messages should be consistent with the visual display and they should be distinctive so that there is no confusion between alerts.

The pilots were unanimous in their desire for a caution level alert but their opinion was mixed as to how this should be implemented. If however, some form of traffic display were included in the system, there are certain characteristics that the pilots would like the display to contain. The results indicate that the pilots desire a color graphic display which presents at a minimum the range, altitude and bearing of tau based intruder aircraft. The altitude requested was relative to the own aircraft: however, absolute altitude was not used in the test. A previous study (11), which had the pilot use absolute altitude and not relative, reported exactly the opposite findings. These results suggest that the pilots can use either presentation and are happy with the one most familiar to them.

Nature of stimuli	Response time (sec)	Test conditions and results			
Visual Visual and buzzer Visual and voice	12.12 4.02 2.40 Tracking task; no impact on concurrent tracking task performance				
Visual and buzzer Visual and voice	4.57 1.94				
Visual and tone Visual and voice	9.35 7.89	Tracking task; better tracking with voice warning			
Visual and buzzer Visual and voice	2.63 1.62				
Visual Voice	128.27 3.03	High-speed, low-level military flight tests			
Visual Voice	44.05 2.93	Visual consisted of analog instruments and lights in an F-100 aircraft			
Auditory Visual	2.2 2.7	Simulation of a typical cooluin anni-			
Voice Buzzer	1.94 2.5?	Simulation of a typical cockpit environment			
Tone Voice	9.35 7.89	F-111 simulator; each alert consisted of a master caution light, alert identification light, and aural annunciation of the type described to the left			
Tone, voice, and visual Tone and visual Voice Tone and voice Visual ^a Visual ^b	5.0 6.0 5.9 6.3 7.6 6.0	Simulation of electronic cockpit environment			

Figure 5.0-1. Typical Response Times as a Function of Display Type

^aVisual presented outside pilot's primary field of view. ^bVisual accompanied by a master alert in the pilot's primary field of view.

6.0 TCAS CANDIDATE SYSTEM DESCRIPTION

The final step of the developmental simulation was to identify the TCAS display configuration which would be used not only in the operational simulation but also in future flight test programs. In order to perform this task it was necessary to review the TCAS and crew alerting data bases and utilize the relevent information. The literature (2,3,5,7,8,11), test results and the pilots' subjective input (Section 4) were used to identify the actual display characteristics. In the operational simulation, the recommended display configuration will be implemented in simulation hardware and validated while testing various operational procedures.

6.1 System Design Objectives

A number of design objectives were used in identifying the characteristics and logic of the displays recommended for TCAS. A major objective was to define a minimum set of information required by the system and relate that information to displays which are applicable not only to advanced flight decks which have an integrated alerting system but also to conventional flight deck which requires dedicated alerts. In this framework, there was a desire to develop an efficient and effective display configuration. Presentation of the information should minimize the time for the flight crew to detect, assess, and respond to the alerts. Information processing and memorization capabilities should be kept as low as possible. All displays and alert logic should be quided by the quiet dark cockpit philosophy. Finally, distraction and startle effects should be minimized to reduce disrupture of aircraft control.

6.2 TCAS Display Configuration

One of the major objectives of the developmental simulation was to define the recommended display configuration for implementation in subsequent phases of the TCAS effort.

In order to display TCAS information, two levels of alert urgency should be used:

- Warning Resolution Advisory situations that require immediate corrective action.
- Caution Traffic Advisory situations that require immediate crew awareness.

As a minimum these levels should be reflected in the combination of system components.

Three primary display components were identified, a master caution (TA), a master warning (RA) and resolution advisory display (both visual and voice). These components may be combined as follows:

o Master Alerts

- Unique caution sound and amber annunciator as the traffic advisory (TA).
- Unique warning sound and red annunciator for the resolution advisory.
- o Resolution Advisory Displays
 - o Visual display providing information available on the modified IVSI
 - o Voice alert with information equivalent to the visual display and continuous until cancelled

The presentation of traffic information on a CRT display is also a method of presenting the caution level alerts. However, before this type of display is recommended for inclusion as a necessary component of the TCAS system, further

testing should be conducted to assess its impact on the total aircraft system. Therefore, it is recommended that a CRT display presenting a color graphic representation of traffic position and containing at least bearing, altitude, horizontal separation and vertical direction information for each intruder, he included in follow-on test efforts to provide this assessment.

The following sections will present some of the major characteristics of the system components. A more comprehensive description of component characteristics and the basis upon which they were recommended can be found in the design quidelines from the Aircraft Alerting Systems Standardization Study (2).

6.2.1 Master Alerts

The master alerts are used to attract the attention of the crew and provide preliminary information about the urgency of the alert. In the TCAS system only two levels of intruder alerts have been recommended, warning (resolution advisory) and caution (traffic advisory). The master alert should be unique for each level. Due to the attention getting qualities of these alerts, they may become a distraction once they have performed their function. Therefore, they should be manually cancellable and should also cancel automatically when the situation no longer exists.

It is further recommended that both visual and aural alerts be used to get the crews attention so that the system will be effective under the majority of workload and environmental conditions.

Master visual alerts should be provided for each of the crew members. The location of the alerts for the captain and first officer should be within fifteen degrees of each one's centerline of vision (see Figure 6.2.1-1) both head-up and head down. This is known as the primary field of view and has been defined as follows:

o Head-up - centerline of vision is a line from the eye reference point in the aircraft extending forward approximately ten degrees below horizontal.




Figure 6.2.1-1. Recommended Placement of Visual Signals

o Head-down - centerline of vision is a line extending from the eye reference point to the center of the ADI.

Using these definitions will place the master visual alerts on or near the glareshield. The master visual alerts should subtend at least one square degree of visual angle. The lighted portion of the alert should be colored with amber being used for the traffic advisory (caution) and red being used for the resolution advisory (warning).

On conventional flight decks, discrete annunciators should be used for the TCAS masters. The legend "TCAS' should be clearly visual on all the annunciators. For flight decks that have an integrated alerting system with a comprehensive centrally located visual information display, the existing master warning/caution annunciators should be utilized with a "TCAS" message output on the information display.

A different master aural alert should be used for each undency level. The sounds that are chosen should be designed to most effectively penetrate the noise spectrum in the cab. The intensity should be set at 8± 3 dB above the masked threshold and be held at that level by using automatic gain control.

So that the crew can quickly recognize the sounds and voice as being generated by the alerting system, they should be perceptually separated from competing sound sources (e.g. ATC, ground communication, etc.). The sounds should be selected to reflect the alert urgency level. In order to do this the sounds should have the following characteristics:

o Caution Sound (TA)

- steady sound composed of at least two frequencies between 300 and 1500 Hz.
- sound duration between 1.2 and 2.0 seconds
- sound should repeat every 8 to 12 seconds until cancelled

o Warning sound (RA)

- sound consisting of two alternating frequencies (European siren) in the 400 to 1000 Hz range separated by at least 300 Hz.
- each frequency should be on for 0.2 to 0.3 seconds before alternating to the other
- master warning should be active for 0.75 seconds before switching to voice
- a silent time of 0.15 to 0.5 seconds should be provided between the sound and voice

Figure 6.2.1-2 provides a graphic presentation of sample master alerting sounds.

6.2.2 Resolution Advisory Displays

The resolution advisory alert meets the qualifications of a "time-critical" alert set forth in the alerting system design quidelines (2). The purpose of any time-critical display is to provide the crew with direct cues for responding to the highest-urgency level of warning. Therefore, recommendations for the presentation of alert information on the RA displays should follow those quidelines.

The resolution advisory will use both the auditory and visual channels to provide the pilots quidance for resolving the conflict. The information provided should be designed to facilitate the rapid detection and performance of the appropriate response.

A visual resolution advisory display should be provided for both the captain and first officer. The displays should be located within each pilot's head-down primary field of view. This recommendation is consistent with the findings of Cooper (6) which state "the most urgent warnings should be located adjacent to the controls and displays involved in alleviating the warning".

He further stated that "warnings related to aircraft control, such as "PULL UP" should be located adjacent to the instruments that the pilot is using such as the ADI or IVSI". These findings are also consistent with the recommendation that the RA display have vertical speed as an integral part of its information. The display should provide the pilot quidance as to the correct action. The most effective way to provide the information has been found to be graphic using color to connote urgency. Care must be used in developing any graphic scheme so that the format is easily understood. An arrow should be used to give the direction of any vertical maneuvers. If the RA imposes a limit on a maneuver already in progress, bars or other types of indexes should be in conjunction with the vertical speed indicator to show the limits. These limit hars should extend down to zero feet per minute. In hoth of these cases the alert calls for immediate action by the crew and thus should be coded red. The visual RA display should remain active until the alerting situation no longer exists and then cancel. As with any other flight instrument, the RA display should provide the crew with some indication when it has failed. Two types of failure have been identified for consideration, hardware and logic. System hardware failures should be identified on the display by a physical indication to the crew (e.g., flags, lights, bars, etc.) that the system is not operative. If the aircraft has an integrated alerting system, a message should also appear on the visual information display. The second failure type occurs when an RA condition exists but the logic cannot provide guidance for that particular situation. In this case the crew needs to know that they are in an RA situation but it must be very clear that the system cannot give guidance. One way to accomplish this would be to illuminate all the lights on the display.

The voice display for the resolution advisory should repeat the information provided on the visual display. Because of the time critical nature of the alert, the voice message should be activated automatically after a 0.75 second presentation of the warning sound. The alerting sound and essential elements of the voice message should be conveyed within 2.5 seconds. The message should repeat until, 1) the pilot cancels it manually 2) the alerting situation no longer exists or 3) the message changes. In each of these cases the message should complete then discontinue. In case three the new message would be preceded by the warning sound. The voice message should be presented in a monotone with an intensity that is 8+ dB above the ambient noise.

6.2.3 Traffic Information Display

The test data indicate that the information increase resulting from a CRT traffic information display used for the TA can increase the pilot response times to the time-critical resolution advisory. Therefore, care must be used in developing procedures with a TCAS dispaly system that includes this type of display. However, since the developmental simulation tested the CRT display only with respect to its affect on the resolution advisory response time, including the pilots anticipation of the response, it is recommended that further testing be conducted with a color graphic presentation of traffic information to assess its impact on the use of TCAS and on the operation of the aircraft as a whole.

For testing, the display should present traffic information graphically using color to portray the urgency level of each individual aircraft. The number of aircraft present on the screen should be limited to a manageable number. Data has shown that three aircraft on the screen at any one time should be a maximum. The utiliziation of the display should conform to the quiet dark cockpit philosophy which calls for alerting displays to be dark when everything is normal. When the display is active, the symbology should move smoothly. Update rate should be increased or some smoothing function applied to the symbols to keep them from iumping.

Care should be taken in developing the graphic presentation so that the display can be easily interpreted and the symbology does not conflict with symbology already present on the flight deck. The own aircraft symbol should be centered horizontally and located toward the bottom of the screen to allow for faster head-on closure rates. The symbol should be consistent with other displays such as EHSI or HUD. At least one range ring should be provided to give the pilot some sense of distance to the traffic. The symbol representing traffic should be distinctly different from the own aircraft and it should change color with respect to its danger to the own aircraft. Altitude associated with each traffic symbol, if known, should be displayed in the same color as the traffic symbol. This altitude may be given in either absolute or relative to the own altitude. If absolute altitude is given for the traffic, the own aircraft altitude should also be presented on the display. Finally,

associated with the traffic should be some indication of vertical motion. If the traffic is non-mode C equipment, some indication (i.e, question marks) should be used in place of the altitude to show the crew that no altitude is available.

If surrounding non-tau based traffic is to be displayed, it should be available during the TA-RA sequence only to conform to the quiet dark cockpit. It should also be color coded with a color other than red or amber.

6.3 Follow-on Verification and Evaluation

Phase II of the study, the Operational Simulation, will have as its objectives:

- o Develop and evaluate the operational procedures associated with CAS alerts under both normal and abnormal flight operations.
- o Assess changes inflight deck operation associated with the CAS alerts
- Assess operational procedures as related to ATC control
- o Assess the impact of TCAS display requirements on flight deck systems and layouts
- o Validate the display concept in operational conditions

Phase II will complement the concept TCAS display system in simulation hardware and install it into a motion-base simulator with full operational capability. The appropriate TCAS software will be implemented to provide fidelity to the situation and to make the findings more generalizeable to actual operations.

REFERENCES

- 1. Anon, "FAA Workshop to Explain Details of Anti-Collision Systems" Aviation Daily, June 25, 1981, p. 310.
- 2. Berson, B.L., Po-Chedley, D. A., Boucek, G. P., Hanson, D. C., Leffler, M. F., Wasson, R. L., "Aircraft Alerting Systems Standardization Study, Volume II: Aircraft Alerting System Design Guidelines", FAA Report, FAA-RD-81-3811, January, 1981.
- 3. Veitengruber, J. E., Boucek, G. P., and Smith, W. D., "Aircraft Alerting Systems Criteria Study, Volume I: Collation and Analysis of Aircraft Alerting System Data", FAA Report, FAA-RD-76-222, May, 1977.
- 4. Veitengruber, J. F., "Design Criteria for Aircraft Warning, Caution and Advisory Alerting Systems", 77-1240-AIAA Aircraft Systems and Technology Meeting, Seattle, Washington, August, 1978.
- 5. Boucek, G. P., Veitengruber, J. E., and Smith, W. D., "Aircraft Alerting Systems Criteria Study, Volume II: Human Factors Guidelines and Aircraft Alerting Systems", FAA Report, FAA-RD-76-222, May, 1977.
- 6. Cooner, G. E., "A Survey of the Status of and Philosophies Relating to Cockpit Warning Systems", Report No. NASA CR-152071. NASA Ames Research Center, Moffett Field, California, 1977.
- 7. Boucek, G. P., Po-Chedley, D. A., Berson, B. L., Hanson, D. C., Leffler, M. F., White, R. W., "Aircraft Alerting Systems Standardization Study, Volume I: Candidate System Validation and Time-Critical Display Evaluation", FAA Report, FAA-RD-81-381, January, 1981.
- 8. Boucek, G. P., Erickson, J. B., Berson, B. L. Hanson, D.C., Leffler, M. F., Po-Chedley, D. A., "Aircraft Alerting Systems Standardization Study, Phase I Final Report", Report No. FAA-RD-80-68, February, 1980.
- 9. Smith, W. D., Veitengruher, J. E., Neuherger, W. K., Osgood, A. G., and Comisky, G. E., "Independent Altitude Monitor Alert Methods and Modes Study", FAA-RD-75-86, July, 1975.
- 10. Society of Automotive Engineers, "Aerospace Recommended Practice: Flight Deck Visual, Audible and Tactile Signals (Draft ARP-4500)", Society of Automotive Engineer's Inc., New York, September, 1979.
- 11. Morgenstern, B. and Berry, T. P., An Evaluation of Aircraft Separations
 Assurance Concepts Using Airline Flight Simulators, Publication No.
 1343-01-3-2058, ARIMC Research Corporation, 1979.
- 12. Rolfe, J. M., "The Secondary Task as a Measure of Mental Load, Measurement of Man at Work", Ed Singleton, W. T., Fox, J. G., and Whitfield, Van Nostrand Reinhold Co., New York, 1971.

REFERENCES (Continued)

- 13. Boucek, G. P., Hanson, D.C., Po-Chedley, D. A., Berson, B. L., Leffler, M. F., and Hendrickson, J. F. Aircraft Alerting Standardization Study, paper presented to the AIAA/IEEE, 4th Digital Avionics Conference, St. Louis, Mo., November, 1981.
- 14. Stevens, S. S., "Handbook of Experimental Psychology," John Wiley and Son, New York, 1951.
- 15. Edwards, A. L., "Experimental Design in Psychological Research," Holt-Rinehart and Winston, New York, 1965.
- Chapanis, A., "Research Techniques in Human Engineering," John Hopkins Press, 1959.

BIBLINGRAPHY

- Adams, J. A., and Chambers, R. W., Response to Simultaneous Stimulation of Two Sense Modalities, Journal of Experimental Psychology, Volume 63, pp. 193-206, 1962.
- Adams, J. A., Humes, J. M., Stenson, H. H., Monitoring of Complex Visual Displays: III Effects of Repeated Sessions of Human Vigilance, Human Factors, Volume 4 (3), pp. 149-158, 1962.
- Bate, A. J., Cockpit Warning Systems Comparative Study, Report No. AMRL-TR-68-193, Aeromedical Research Laboratory, Wright-Patterson AFR, Ohio, 1969.
- Bateman, C. D., Introduction of the Ground Proximity Warning System (GPWS) into Airlines Service. Sundstrand Data Control, Redmond, Washington, Paper presented at 29th International Air Safety Seminar, Flight Safety Foundation, Inc., October 25-29, 1976, Anaheim, California.
- Educek, G. P., Veitengruber, J. E., and Smith, W D., <u>Aircraft Alerting Systems</u> Criteria Study, Volume II: <u>Human Factors Guidelines and Aircraft Alerting</u> Systems, FAA Report, FAA-RD-76-222, May, 1977.
- Boucek, G. P. Erickson, J. B., Berson, B. L., Hanson, D. C., Leffler, M. F., Po-Chedley, D. A., Aircraft Alerting Systems Standardization Study, Phase T Final Report, Report No. FAA-RD-80-68, February, 1980.
- Boucek, G. P., Hanson, D. C., Po-Chedley, D. A., Berson, B. L., Leffler, M. F., and Hendrickson, J. F., Aircraft Alerting Systems Standardization Study, paper presented to the AIAA/IEEE, 4th Digital Avionics Conference, St. Louis, Missouri, November, 1981.
- Rritish Airways, Warning Systems, International Air Transport Association Twentieth Technical Conference, Istanbul, November, 1975.
- Brown, J. E. Bertone, C. M., and Obermayer, R. W. Army Aircraft Voice Warning System Study (GO131-8U1). Canoga Park, California: Bunker-Ramo Corporation, February, 1968.
- Burrows, A. A. and Ford, H. K., Sounds in Warnings in Aircraft (Report No. FPRC966). Great Britain: Flying Personnel Research Committee, May, 1956.
- Cooper, G. E., A Survey of the Status of and Philosophies Relating to Cockpit Warning Systems, Report No. NASA CR-15071, NASA Ames Research Center, Moffett Field, California, 1977.
- Crawford, A., The Perception of Light Signals: The Effect of the Number of Irrelevant Lights, Ergonomics, Volume 5, pp. 417-428, 1962.
- Crawford, A., The Perception of Light Signals: The Effect of Mixing Flashing and Steady Irrelevant Lights, Ergonomics, Volume 6, pp. 287-294, 1963.

- Davis, R. C., Motor Components of Responses to Auditory Stimuli: The Effect of Stimulus Intensity and Instructions to Respond, American Psychologist, Volume 2, pp. 308, 1947.
- Edwards, Elwyn, 1977. Flight Deck Alarm Systems, Human Factors Bulletin, January/February, 1977, Flight Safety Foundation, Inc., Arlington, Virginia
- Egan, J. P., Carterette, E.C., and Thwing, E. J., Some Factors Affecting Multi-Channel Listening, Journal of the Acoustical Society of America, Volume 26, pp. 774-782, 1954.
- Eike, D., Malone, T., and Fleger, F., Human Engineering Design Criteria for Modern Display Components and Standard Parts Essex Corporation, Alexandria, Virginia, 1980.
- Eldred, K. M., Gannon, W. J., Vongierke, H., <u>Criteria for Short Time Exposure of Personnel to High Intensity Jet Aircraft Noise</u>, <u>Report No. WADC-Tn-55-355</u>, <u>Wright Air Development Center</u>, <u>Wright-Patteron AFB</u>, Ohio, 1955.
- Erickson, J. B., Voice Warning Questionnaire Results, Internal McDonnell-Douglas Company AVI, December 1978.
- Evaluation and Use of Auditory Displays and Aircraft Voice Warning Systems (Report No. 63-135). Newport Beach, California: Astrpower, Inc., September, 1963.
- Federal Aviation Regulation 25.1322, Airworthiness Standards: Transport Category; Airplanes, Department of Transportation, Federal Aviation Administration, Washington, D. C., June 1974.
- FED-STD-595, Colors, Washington, D. C., March, 1979.
- Fletcher, H., Munson, W. A., Loudness, Its Definition, Measurement, and Calculation, Journal of the Acoustical Society of America, Vol. 5, pp. 82-108, 1933.
- Fletcher, H., Speech and Hearing in Communications, D. Van Nostrand Company, Inc., Princeton, N. J., 1953.
- Gerathewohl, S. G., Conspicuity of Steady and Flashing Light Signals: Variation of Contrast, Journal of the Optical Society of America, Volume 43, pp. 567-571-1953.
- Gopher, D., Kahneman, D., <u>Individual Differences in Attention and the Prediction of Flight Criteria</u>, <u>Perceptual and Motor Skills</u>, <u>Vol. 33</u>, pp. 1335-1342, 1971.
- Graham, W. <u>Human Factors Considerations in Pilot Warning Systems</u> (FAA RD71-114). Washington, D. C.: Federal Aviation Administration, December, 1971.
- Hart, S. A. and Simpson, C. A., Effects of Linquistic Redundancy on Synthesized Cockpit Warning Message Comprehension and Concurrent Time Estimation (NASA TMX-73, 170), 12th Annual Conference on Manual Control, University of Illinois at Champaign-Urbana, Illinois, May 1976.

- Hawkins, H. L., Stevens, S. S., The Masking of Pure-Tones and of Speech by White Noise, Journal of the Acoustical Society of American, Vol. 22, No. 6, 1950.
- Hector, R. G. Methods of Auditory Display for Aircraft Collision Avoidance Systems (N72-14005). Edwards Air Force Base, California: Air Force Flight Test Center, August, 1971.
- Henneman, R. H. and Long, E. R., <u>A Comparison of the Visual and Auditory Senses as Channels for Data Presentation (WADC Tech. Report No. 54-363).</u> Wright-Pattern Air Force Base, Ohio: August, 1954.
- Kemmerling, P., Geiselhart, R., Thorburn, D. E., Cronhurg, J. G., <u>A Comparison of Voice and Tone Warning Systems as a Function of Task Loading</u>, <u>Technical Report ADS-TR-69-104</u>, <u>Air Force Systems Command</u>, <u>Wright-Patterson AFB</u>, Ohio, 1969.
- Kerce, E. W., Intelligibility Testing of Voice Model and Phoneme-Synthesized Voices for Aircraft Caution Warning Systems, California State University, Long Beach, California, 1979.
- Kohfeld, D. L., Simple Reaction Time as a Function of Stimulus Intensity in Decibels of Light and Sound, Journal of Experimental Psychology, Volume 8872), pp. 251-257, 1971.
- Licklider, J. C., <u>Audio Warning Signals for Air Force Weapon Systems</u>, USAF, WADD, Technical Report 60-814, March, 1961.
- Luckiesk, M., Light, Vision and Seeing, Van Mostrand, New York, 1944.

1

- McCormick, E. J., <u>Human Factors Engineering</u>, McGraw-Hill Book Company, New York, 1970.
- McFarland, A. L., Human Factors Considerations in Establishing Aircraft Collision Avoidance System Alert Thresholds, SAFE Journal, Vol. 8, No. 1, 1978, pp 9-13.
- Meister, D., and Sullivan, D. J., Guide to Human Engineering Design for Visual Displays, AD 693237, Office of Naval Research, Department of the Navy, Arlington, Virginia, 1969.
- Merriman, S. C., Operational Attention Intrusion Effects Associated with Aircraft Warning Lights of Various Size, Report No. NADC-AC-69D1, Department of the Navy, Naval Air Development Center, Aerospace-Crew Equipment Department, Warminster, Pennsylvania, 1969.
- Miller, G. A., <u>The Magical Number Seven</u>, <u>Plus or Minus Two: Some Limits on Our Capacity for Processing Information</u>, <u>Psychological Review</u>, <u>Volume 63(7)</u>, <u>np. 81-96</u>, <u>1956</u>.
- Mills, A. W., On the Minimum Audible Angle, Journal of the Acoustical Society of American, Volume 30, pp. 237-245, 1958.

- MIL-C-25050, Colors, Aeronautical Lights and Lighting Equipment, General Specification for, Department of Defense, February 17, 1972.
- MIL-M-18012B, Markings for Aircrew Station Displays, Design and Configuration of, Department of Defense, Februay 17, 1982.
- MIL-STD-411D, Aircrew Station Signals, Department of Defense, Washington, D. C., August, 1967.
- MIL-STD-1472B, Human Engineering Design Criteria for Military Systems, Equipment, and Facilities, Department of Defense, May 10, 1978.
- Morgan, C. T., Cook, J. S., Chapanis, A., Lund, M. W., <u>Human Engineering Guide</u> to Equipment Design, McGraw-Hill Book Company, New York, 1963.
- Mudd, S. A., The Scaling and Experimental Investigation of Four Dimensions of Pure-Tones and Their Use in an Audio-Visual Monitoring Problem, Ph. D. Thesis, Purdue University, Lafayette, Indiana, 1961.
- Munns, Meredith, Ways to Alarm Pilot, Aerospace Medicine, July, 1971 np. 731-734.
- Munson, W. A., The Growth of Auditory Sensitivity, Journal of the Acoustical Society of America, 1947.
- Noise Lectures presented by Bonvallet at the In-service Training Course on Acoustical Spectrum, February 5-8, 1952. Sponsored by the University of Michigan School of Public Health and Institute of Industrial Health, University of Michigan Press, Ann Arbor, Michigan.
- Parks, D. L., Personal Communication Concerning Unpublished Test Results, 1979.
- Pearsons, K. S. and Bennett, R. L. Effects of Interior Aircraft Noise on Speech Intelligibility and Annoyance (NASA CR-145203, N 77-29918/8 WT). Bolt, Beranch and Newman, Inc.
- Pearson, K., Effect of Tone/Noise Combination on Speech Intelligibility, Journal of the Acoustical Society of America, Vol. 61, No. 3, March, 1977.
- Po-Chedley, D.A., Burington, C. P., The Effects of Alert Prioritization and Inhibit Logic on Pilot Performance, Report No. MDC J9076, McDonnell Douglas Corporation, 1981.
- Pollack, I., Ficks, L., Information of Multidimensional Auditory Displays, Journal of the Acoustical Society of America, Vol. 26, pp. 155-158, 1954.
- Pollack, I., The Information of Elementary Auditory Displays, Journal of the Acoustical Society of America, 24, pp. 745-459, 1952.
- Pollack, I. D., Teece, J., <u>Speech Annunciator Warning Indicator System:</u>
 Preliminary Evaluation, Journal of the Acoustical Society of American, Vol. 30, pp. 58-61, 1958.

- Pope, L. T., and McKechnic, D. F., Correlation Between Visual and Auditory Vigilance Performance, Report No. AMRL-TDR-63-57 Aerospace Medical Research Laboratories, Wright-Patterson AFB, Ohio. 1963.
- Raab, D., and Fehrer, E., The Effects of Stimulus Duration and Luminance on Visual Reaction Time, Journal of Experimental Psychology, Volume 64(30, pp. 326-327, 1967.
- Randle, R. J., Larson, W. E., Williams, D. H., <u>Some Human Factors Issues in the Development and Evaluation of Cockpit Alerting and Warning Systems</u>, <u>NASA</u>, <u>Ref. Publication 055</u>, <u>January</u>, <u>1980</u>.
- Sheehan, D. J., <u>Heads-Up Display Warning Requirement Research</u>, Final Report NR 213-086, Office of Naval Research, Department of the Navy, Arlington, Virigina, 1972.
- Shower, E. G., and Biddulph, R., Differential Pitch Sensitivity of the Ear, Journal of the Acoustical Society of America 3, pp. 275--287, 1931.
- Siegel, A. I., and Crain, K., Experimental Investigations of Cautionary Signal Presentations, Ergonomics, Volume 3, pp. 339-356, 1960.
- Simpson, C. A., Effects of Linquistic Redundancy on Pilot's Comprehension of Synthesized Speech, Proceedings of the Twelfth Annual Conference on Manual Control, NASA TMX-73, pp. 294-308, May, 1976.
- Simpson, C. A., and Williams, D. H., <u>Human Factors Research Problems in</u> Electronic Voice Warning System Design, M75-33681, 11th Annual Conference on Manual Control, NASA Ames Research Center, Moffett Field, California, May, 1975.
- Simpson, C. A., and Park, S. G., Required Attention for Synthesized Perception for Three Levels of Aquistic Redundancy, 93rd Meeting of the Acoustical Society of America, Pennsylvania State College, June, 1977.
- Simpson, C. A., and Williams, D. H., The Effects of an Alerting Tone and of Semantic Context on Pilot Response Time for Synthesized Speech Voice Warnings in a Simulated Air Transport Cockpit, MCI Report No. 78-001, NASA Ames Research Center, Moffett Field, California, 1978.
- Society of Automotive Engineers, Aerospace Recommended Practice: Flight Deck Visual, Audible and Tactile Signals (Draft ARP-450D), Society of Automotive Engineers, Inc., New York, September, 1979.
- Speith, W., Curtis, J. F., Webster, J. C., <u>Responding to One of Two Simultaneous Messages</u>, <u>Journal of the Acoustical Society of America</u>, Vol. 26, pp. 391-396, 1954.
- Steinman, A. R., Reaction Time to Change Compared with Other Psychophysical Methods, Archives of Psychology, New York, Volume 292, pp. 34-60, 1944.
- Stevens, S. S., and Davis, H., <u>Hearing, Its Psychology and Physiology</u>, John Wiley and Sons, New York, 1938.

Stevens, S. S., Handbook of Experimental Psychology, John Wiley and Sons, Inc., New York, 1951.

VanCott, H. P. and Kinkade, R. G., Human Engineering Guide to Equipment Design, United States Printing Office, Washington, D. C., 1972.

Vanderschraff, A., <u>Problem Area: Warning Systems</u>, Fokker, VFW Aircraft. Proceedings from the 20th International Air Safety Seminar of the Flight Safety Foundation, Anaheim, California, October 25-29-, 1976.

Veitengruber, J E., Design Criteria for Aircraft Warning, Caution and Advisory Alerting Systems, 77-1240 AIAA Aircraft Systems and Technology Meeting, Seattle, Washington, August, 1978.

Tannas, L. E., Jr., and Goede, W. F., Flat Panel Displays, a Critique, I.E.E. Spectrum, pp. 26-32, July, 1978.

Thorburn, D.E., Voice Warning Systems, A Cockpit Improvement That Should Not Be Overlooked (AMRL-TR-70-138). Wright-Patterson Air Force Base, Ohio: Aero-medical Research Laboratory, Aerospace Medical Division, 1971.

Tobias, J. V., Auditory Effects of Noise on Air-Crew Personnel (FAA-AM-72-32). Washington, D. C.: Federal Aviation Administration, November 1972.

Wegel, R. L. and Lane, C. E., The Auditory Masking of One Pure-Tone By Another and Its Probable Relation to the Dynamics of the Inner Ear, Psychological Review, Vol. 23, pp. 266-285, 1924.

Williams, D. H. and Simpson, Carol A., A Systematic Approach to Advanced Warning Systems for Air Transport Operations: Line Pilot Preferences, NASA Aircraft Safety and Operating Problems Conference, NASA Langley Research Center, October, 1976.

AD-A126	`342	TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM DEVELOPMENTAL SIMULATION(U) BOEING COMMERCIAL AIRPLANE							2/2	2/2			
UNCLASS	IF1ED	CO SEATTLE WA G P BOUCEK ET AL. JUL 82 DOT/FAA/RD-82/49 F/G 17/7						NL	NL				
				7,1									
													-
		3.	54	2.							END		
	and from the second	AAA.	Ž	AND THE RESERVE	es and a						4 83		



MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS 1963-A

and and of the second

APPENDIX A

TEST FACILITIES

A.Ø Simulation Center and Hardware Layout and Summary

The various requirements of this study called for an easily reconfigurable facility in which several flight deck systems could be demonstrated, tested and evaluated in a realistic environment. The Kent Visual Flight Simulator at the Flight Simulation Center was chosen. Located in a flexible experimental simulation laboratory, the simulator, called the Blue Cab, was modified to represent a generic wide body cockpit configuration with a working pilots station.

The cockpit instrumentation included two TCAS advisory displays, a TCAS advisory annunciator and two TCAS alertino devices (LED display and IVSI with directory lights). Several combinations of the TCAS aquipment were used but they were never all used together.

An external visual workload was provided to the bilot through the forward windscreens; computer controlled video used for takeoff, target location. The bilot was also presented alerting agrals, aid traffic control commands, background communications, and engine and were sounds.

The test conductor was in visual and vaice contact with the city conductor to the tests from his console. This console coabled the test conductor to interface directly with the main computer and control all audio and video parameters. Figure A.O-1 depicts the layout of the simulation center.

A.1 Cockpit Simulator

The Blue Cab had a hybrid (electronic and conventional) main instrument panel, standard center console, and seats for the pilot and conflot. Active flight instruments were provided for the pilot only. Mounted on a hydraulic platform, the cab was positioned towards the front (projection screen side) of the lowered platform. This placed the pilot's eye reference point in an optimal relationship with respect to the hemisperical projection screen. The projector was located directly above the pilot and the eye reference point was about eighteen feet from the screen. A cita view of the flee Cab is illustrated in Figure A.1-1.




Figure A.O-1. Kent Visual Flight Simulation Center




Figure A.1-1. Side View of Blue Cab

A.1.1 Pilots' Instrumentation

The Blue Cab's main instrument panels, supporting framework and glareshield was designed to represent a generic wide body commercial aircraft. The pilots' instrumentation consisted of raster scan CRT's, standard electro-mechanical instruments, annunciators and switches. A (9 inch) color Hitachi CRT was used for the EADI and it was driven by a Boeing huilt color graphics generator. Advanced system alerts were presented on a (5 inch) color Hitachi CRT. A Lexidata model 3400 color graphics generator was used to drive this CRT. A (9 inch) black and white CRT used to display engine instrument information was driven by a Boeing built har graphics generator. Refer to Figure A.1.1-1.

The servo and synchro motors of the electro-mechanical instruments were driven from a local controller. Digital information from the host computer was fed to the controller. The controller then passed it through digital to analog and digital to syncro converters. Discrete input cards sampled the switches when requested by the host computer.

This included the Pilot Response Panel switches (Figure A.1.1-2). Except for the "TCAS ALERT" and master Warning/Caution switch lamps, all lighted annunciators were driven with discrete output cards. The (amber) "TCAS ALERT" and (red and amber) warning and caution switches were controlled by a TCAS audio-video (TAL) unit, (Section A.2.2).

The FAA supplied a modified IVSI (with director lamps) which is discussed in Section A.2.6. Two different CAS Advisory Displays were evaluated. They were mounted in the center console forward of the throttles (Figure A.1.1-2). These advisory displays are described in Section A.2.5.

A.2 CAS Simulation Equipment

The CAS Simulation Equipment was designed to operate as an integral subsystem to the Blue Cab with only two interface links required between it and the host computer (Figure A.2.-1). This design made it possible for the system to be checked out before installation, eased integration and checkout in the simulation center, and will permit easier installation in different cockpit simulators for other phases of this study. The six subunits that make up the CAS equipment are described below.

A-5




Figure A.1.1-1. Blue Cab Front Panel Layout




Figure A.1.1-2. Internal View of Blue Cab




Figure A.2-1. CAS Simulation Equipment Layout

A.2.1 BEU Simulator Unit

In a TCAS equipped aircraft, Beacon Electronics Unit (BEU) will integrate aircraft performance data and compare it against TCAS interrogative aircraft in the general vicinity. If an intercept with one or more aircraft is predicted, the BEU will alert the flight crew with an advisory and/or time critical warning device.

An actual BEU was not available for this study so a Data General MicroNova was used to simulate some of the BEU functions. The MicroNova had 32k bytes RAM and a dual flexible disk unit for program and data storage. Three RS-232 serial ports and one 16-bit parallel port were used.

Much of the BEU active logic was not needed because "canned" intrusion scenarios were used. For this reason the slower and less powerful MicroNova capably supported this study.

The MicroNova was signaled from the host computer when to start each intrusion sequence via RS-232 link. Table A.2.1-1 lists the messages sent between the host computer and the MicroNova.

The MicroNova output to the Advisory Display RS-232 Port throughout each simulation run. This RS-232 port was connected to a switching box that permitted the test conductor to select the AID display, the Smith/Collins display or no advisory display at all.

The 29-byte message that was output at a rate of once per second (1 Hz) could contain information on up to three intruding aircraft in addition to own aircraft performance data. Figure A.2.1.1 depicts the advisory message byte definition.

When a PA, TA and/or RA alert occurred one or more of the twelve lines from the MicroNova to the TCAS Lamb Driven Unit were activated. The ten least significant lines corresponded to the ten TCAS/IVSI director lamps. The other two lines signaled TA's and PA's. Table A.2.1.2 lists the valid message/bit combinations.

Table A.2.1-1. Summary of Host-to-BEU Simulation Unit Message Formats

Description	Word number	Word definition	Scaling	Range	Units	BEU simulation unit receiving modes
Initiate intruder	1 2	Start of message Number of bytes		0A05 (HEX)		Run mode only
	3	Message ID = 1		1	}	
Message	4	Intruder ID	{	+(1-40)		
No. 1	5	Advisory status	Discrete			
Initialization	1	Start of message		0A05 (HEX)		Reset mode only
status	2	Number of bytes	1	8		
·	3	Message ID = 2		2	İ	
	4	BEU performance	11	0 to 7]	
Message	5	AOA status	Discretes	0 or 1		
No. 2	6	T ₁ (iteration)	T1/4	0.25 to 4	Sec	
	7	T ₂ (aid update)	T2/4	0.25 to 4	Sec	
System time	1	Start of message		0A05 (HEX)		Reset and run modes
and simulation	2	Number of bytes	l i	8	1	only
aircraft	3	Message ID 3		3	-	,
parameters	4	Hours]	0 to 23		
	5	Minutes		0 to 59	[
Message	6	Seconds	i l	0 to 5 9	1	
No. 3	7	Aircraft altitude	H,50	50 to 60,000	Ft	
BEU mode	1	Start of message		0A05 (HEX)	 	Reset run, and hold
commands	2	Number of bytes	!	2	:	
	3	Message ID ≈ 4	! }	4	1	
Message No. 4	4	Mode definition	Discretes			
Intruder	1	Start of message		0A05 (HFX)	† -	Run mode only
termination	2	Number of bytes		4		,
status	3	Message ID = 100	i	100		
	4	Intruder ID		1.40	1	
	5	Termination status		0	ļ	
Message No. 100						
Error	1	Start of message		0A05 (HEX)		Run, reset, or hold
message	2	Number of bytes	1	2		modes
	3	Message ID = 101	! [101		
Message No. 101	4	Error code		1 to 10		




Figure A.2.1-1. Advisory Message Byte Definition

Table A.2.1-2. Definition of Parallel Data Sent to IVSI and TAV by MicroNova.

12 BIT OUTPUT	TCAS MESSAGE	Resolution advisors
11-bit 0		Number
000000000000	NO VERTICAL COMMAND	
001000000000	CLIMB- MAX RATE	1
000100000000	DESCEND-MAX RATE	2
000011110000	ZERO CLIMB	3
000011106000	CLIMB LIMIT 500 ft/map	4
000011000000	CLIMB LIMIT 1,300 ft/min	5
000010008000	CLIM3 LIMIT 2,009 from	€:
000000001111	ZERO DESCEND	7
000000000111	DESCEND LIMIT 500 tr. mm.	8
00000000011	DESCEND LIMIT 1,000 tons	g
00000000001	DESCEND LIMIT 2,000 ft mm	10
000000011111	CLIMB FASTER THAN 500 ft. 605	11
000000111111	CLIMB FASTER JHAN 1,000 temin	12
000001111111	CLIMB FASTER THAN 2,000 ft/m ii	13
000011111000	DESCEND FASTER THAN 500 fr min	14
000011111100	DESCEND FASTER THAN 1 200 fumin	15
000011111110	DESCEND FASTER THAN 2,000 thanks	16
000011111111	3 AND 7	17
000011101111	4 \ NO T	18
000011001111	o AMO 7	19
000010001111	6 Al- 3 7	20
000011110111	2 24D 8	21
000011100111	4 AND 8	22
000011000111	5 AND 8	23
000010000111	6 AND 8	2.4
000011110011	3 AND 9	25
000011100011	4 AND 9	26
000011000011	5 AND 9	3/
000010000011	6 AND 9	29
000011110001	3 AND 10	29
000011100001	4 AND 10	3.:
000011000001	5 AND 10	31
000010000001	6 AND 10	2°
000011011111	5 AND 11	33
000010011111	6 AND 11	34
000010111111	6 AND 12	35
000011111011	9 AND 14	36
000011111001	10 AND 14	37
000011111101	10 AND 15	38
010 00000 0000	I DA CAUTION	1

Note: The ten (10) least agent card bits are for BA's let 10 or to TA's agent or TT is for PA's.

A.2.2 Lamp Driver for TCAS/IVSI and TAV Unit

The Lamp Driver was was mounted in the same rack as the MicroNova and the TAV unit. It accepted inputs (12 lines) from the MicroNova and provided high voltage drive signals for the 28 volt lamps in the IVSI and the high voltage receivers in the TAV unit. Switches on the Lamp Driver gave the test conductor the option of outputing to the TCAS/IVSI and/or TAV and conducting a lights test feature.

A.2.3 TCAS Audio-Video (TAV) Unit

The TAV unit functioned as an alert controller in this study. (Figure A.2.3.1). A Zilog ZRØ microprocessor monitored and prioritized incoming TCAS alert signals from the MicroNova (via Lamp Driver) and aircraft system alerts from the host computer (via Warning and Caution control console). Table A.2.1.2 lists valid TCAS alerting messages. Only three types of system alerts were recognized by the TAV unit; Warning, Caution and Advisory.

The TAV front panel has several switches for selecting alerting options and a LED display that mirrors the status of the IVSI director lamps, Figure A.2.3-2. This layout gave the test conductor the ability to easily change alerting arrangements and monitor intrusion runs.

Three alerting tones are produced by the tone generator; warning = European Siren, caution = C-Chord and advisory = Single Chime. These tones were used for TCAS and System alerts. The C-Chord had a 9 second cycle, 2 seconds on and 7 seconds off, until cancelled.

The speaker enclosure was located behind the pilots' right shoulder, Figure A.1.1-2. A microphone and preamp for the automatic gain control were also mounted in the speaker enclosure. The automatic gain control was set up to keep the aural tones about 8dB above the ambient noise. The "critical bandwidth" monitored was 300 to 2400 hertz.




Figure A.2.3-1. TCAS Audio-Video (TAV) Unit




Figure A.2.3-2. TAV Front Panel Layout

A National Semiconductor voice synthesizer chip was used to produce the TCAS voice messages that are listed in Table A.2.1.2. The individual words were stored on PROM's. A total of 277 phrases, tones and bauses were available. All recordings were done by National. The complete vocabulary is listed in Table A.2.3-1.

The two lighted alerting switches were mounted on the glareshield as shown in figure A.1.1.1. The split legend Master Warning/Caution and TCAS Alert switches were controlled and sensed by the TAV unit. Roth switches were also monitored by the host computer.

Sigure A.2.3-3 is a block diagram of the LED ICAS display unit. The TAV unit sent an eight bit address to the LED unit to display the LED images. The bit maps for all the TCAS graphic and alphanumeric displays were stored on PROM's in the LED unit.

A.2.4 FAA CAS Advisory Display

An Airborne Intelligent Display (AID) and required support equipment were supplied by the EAA. The AID was a modified Bendix color weather radar display. A microprocessor based controller had its program stored in PROM and on power-up it initialized and assumed Tabular Display Mode. This AID was only used in tabular mode, although it had some graphic capability. A block diagram of the AID system is shown in Figure A.2.4-1.

The AID system received data from the REC Complation unit (Micro NOVA) via RS-232 line running at 9600 baud rate. To formation was transferred to the AID in formatted data blocks of up to 20 8 bit bytes ence every two seconds. Face data block began with a sync byte and have counter followed by nine byte header of own aircraft status and then up to three advisory data blocks of intruding aircraft. A data block was transferred to the AID every two seconds whether or not advisories were present. If advisories were not present nothing was displayed on the monitor. Refer to Figure A.2.4-2 for AID message byte definition.

Table A.2.3-1. Voice Vocabulary List

TWO R DATE HEADING NOTICE S THREE S DAY HELLO NUMBER S FOUR T DE HELP OF S FIVE U DECREASE HERTZ OFF S SIX V DEGREE HIGH OHMS S SEVEN W DEPOSIT HIGHER ON S EIGHT X DIAL HOLD ONWARD S NINE Y DIVIDE HOUR OPEN S ELEVEN ABORT DOLLAR INCHES OR S ELEVEN ABORT DOULAR INCORRECT OUT S TWELVE ADD DOOR INCORRECT OUT S THIRTEEN ADJUST DOWN INCORRECT OUT S SIXTEEN AGAIN ED IS PASS T SIXTEEN ALERT END JUST PERCENT T EIGHTEEN AUL ENTER KEY PICO T NINETEEN AMPERE ENTRY KILO PLACE T TWENTY AND EQUAL LEFT PLEASE T TWENTY ASSISTANCE ERROR LESSER POINT T FIFTY ASK ER LESS PLUS T SIXTY ATTENTION EXIT LIMIT PRESS T SIXTY ATTENTION EXIT LIMIT PRESS T SIXTY ATTENTION EXIT LIMIT PRESS T THOUSAND CANCEL FAST MARK RE VACUATE LOCK PULSE L THOUSAND CANCEL FAST MARK RE VACUATE LOCK PULSE L THOUSAND CANCEL FAST MARK RE VACUATE HOLD CANCER T THOUSAND CANCEL FAST MARK RE VACUATE HOLD CANCER T THOUSAND CANCEL FAST LOWER RANGE V THOUSAND CANCEL FASTE MAINTAIN RATE VINNETY BUT FOR FAILURE LOCK PULSE L THOUSAND CANCEL FASTER MAINTAIN RATE VINNETY BUT FIRST MEGA RECEIVE V THOUSAND CANCEL FASTER MAINTAIN RATE VINNETY BUT FIRST MEGA RECEIVE V THOUSAND CANCEL FASTER MAINTAIN RATE VINNETY RECORD THE CONCENT OF THE		
TWO R DATE HEADING NOTICE S THREE S DAY HELLO NUMBER FOUR T DE HELP OF S FIVE U DECREASE HERTZ OFF S SIX V DEGREE HIGH OHMS S SEVEN W DEPOSIT HIGHER ON S EIGHT X DIAL HOLD ONWARD S NINE Y DIVIDE HOUR OPEN S TEN Z DO IN OPERATOR S ELEVEN ABORT DOLLAR INCHES OR S TWELVE ADD DOOR INCORRECT OUT S THIRTEEN ADJUST DOWN INCREASE OVER T FOURTEEN ADVISORY EAST INTRUDER PARENTHESIS T FIFTEEN AGAIN ED IS PASS T SIXTEEN ALARM EMERGENCY IT PER S SEVENTEEN ALERT END JUST PERCENT T EIGHTEEN ALL ENTER KEY PICO T THIRTY AND EQUAL LEFT PLEASE T TWENTY AND EQUAL LEFT PLEASE T THENTY ASK ER LESS PLUS T FORTY ASSISTANCE ERROR LESSER POINT T SIXTY ATTENTION EXIT LIMIT PRESS T SIXTY ATTENTION EXIT LIMIT PRESSURE L EIGHTY BUTTON FAILURE LOCK PULSE L THOUSAND CANCEL FASTE MAINTAIN RATE W MILLION CASE FEET MARK RE THOUSAND CANCEL FASTER MAINTAIN RATE MILLION CASE FEET MARK RE THOUSAND CANCEL FASTER MAINTAIN RATE MILLION CASE FEET MARK RE CENTI FIRST MEGA RECEIVE W C CHANGE FLIGHT METER RECORD T FIETH MAXIMUM REACH W MILLION CASE FEET MARK RE CENTI FIRST MEGA RECEIVE W C C CHANGE FLIGHT METER RECORD T C C CLIMB FROM MINUS ROOM 2 L COMPLETE GO NEAR SELECT 33	Q	SLOWER
THREE S DAY HELLO NUMBER S FOUR T DE HELP OF S FIVE U DECREASE HERTZ OFF S SIX V DEGREE HIGH OHMS S SEVEN W DEPOSIT HIGHER ON S EIGHT X DIAL HOLD ONWARD S NIME Y DIVIDE HOUR OPEN S TEN Z DO IN OPERATOR S TEN Z DO IN OPERATOR S TWELVE ADD DOOR INCORRECT OUT S TWELVE ADD DOOR INCORRECT OUT S FOURTEEN ADJUST DOWN INCREASE OVER T FOURTEEN ADJUST DOWN INCREASE OVER T FOURTEEN ADJUST DOWN INCREASE OVER T SIXTEEN ALARM EMERGENCY IT PER SEVENTEEN ALL ENTER KEY PICO T NINETEEN ALL ENTER KEY PICO T TWENTY AND EQUAL LEFT PLEASE T THIRTY ASK ER LESS PLUS T FORTY ASSISTANCE ERROR LESSER POINT T SIXTY ATTENTION EXIT LIMIT PRESS T SIXTY ATTENTION EXIT LIMIT PRESS T SIXTY ATTENTION EXIT LIMIT PRESS T SIXTY BUTTON FAILURE LOCK PULSE UNINETY BUY FARAD LOW QUARTER L HUNDRED CALL FAST LOWER RANGE W HUNDRED CALL FAST REGA RECEIVE W CHANGE FEIGHT METER RECORD W HUNDRED CALL FAST REGA RECEIVE W CHANGE FLIGHT METER RECORD W HUNDRED CALL FAST MARK RE ZERO CAUTION FIFTH MAXIMUM REACH W A CENT FIRST MEGA RECEIVE W CHANGE FLIGHT METER RECORD W HULLION CASE FEET MANIMUM REACH W A CENT FIRST MEGA RECEIVE W CHANGE FLIGHT METER RECORD W HULLION GAS FROM MINUS ROOM 2 H COLLISION GAS MORE SECOND H COLLISION GAS MORE SECOND J COMMA GET MOVE SECURE S	R	SMOKE
FOUR FIVE U DECREASE HERTZ OFF S SIX V DEGREE HIGH OHMS S SEVEN W DEPOSIT HIGHER ON S SEVEN NINE Y DIVIDE HOUR OPEN S S TEN Z DO IN OPERATOR S S ELEVEN ABORT DOLLAR INCHES OR S S ELEVEN ABORT DOULAR INCORRECT OUT S S TWELVE ADD DOOR INCORRECT OUT S S THITTEEN ADJUST DOWN INCREASE OVER T FOURTEEN ADVISORY EAST INTRUDER PARENTHESIS T FIFTEEN AGAIN ED IS PASS T SIXTEEN ALARM EMERGENCY IT PER SEVENTEEN ALERT END JUST PERCENT T SEVENTEEN ALL ENTER KEY PICO T NIMETEEN AMPERE ENTRY KILO PLACE T WENTY AND EQUAL LEFT PLEASE T THIRTY ASK ER LESS PLUS T THIRTY ASSISTANCE ERROR LESSER POINT T FIFTY AT EVACUATE LEVEL POUND T SIXTY ATTENTION EXIT LIMIT PRESS T SEVENTY BRAKE FAIL LOAD PRESSURE L EIGHTY BUTTON FAILURE LOCK PULSE L FAST LOWER RANGE V THOUSAND CANCEL FASTE MAINTAIN RATE V HUNDRED CALL FAST LOWER RANGE V THOUSAND CANCEL FASTE MAINTAIN RATE V MILLION CASE FEET MARK RE V THOUSAND CANCEL FASTE MAINTAIN RATE V C C CHANGE FLIGHT METER RECORD V C C CHANGE FLIGHT MILLI RIGHT E C C CHANGE FLIGHT MINUTE SAFE A C COMMAL GET MOVE SECURE S COMMAL K COMPLETE GO NEAR SELECT S C C COMPLETE C C C C C C C C C C C C C C C C C C		SOUTH
FIVE U DECREASE HERTZ OFF SIX V DEGREE HIGH OHMS SIX V DEGREE HIGH OHMS SIX SEVEN W DEPOSIT HIGHER ON SIX SEVEN W DEPOSIT HIGHER ON SIX DIAL HOLD ONWARD SIX		SPACE
SIX V DEGREE HIGH OHMS S SEVEN W DEPOSIT HIGHER ON S EIGHT X DIAL HOLD ONWARD S NINE Y DIVIDE HOUR OPEN S TEN Z DO IN OPERATOR S ELEVEN ABORT DOLLAR INCHES OR S TWELVE ADD DOOR INCORRECT OUT S THIRTEEN ADJUST DOWN INCREASE OVER T FOURTEEN ADVISORY EAST INTRUDER PARENTHESIS T FIFTEEN AGAIN ED IS PASS SIXTEEN ALARM EMERGENCY IT PER SEVENTEEN ALERT END JUST PERCENT T EIGHTEEN ALL ENTER KEY PICO T NINETEEN AMPERE ENTRY KILO PLACE T TWENTY AND EQUAL LEFT PLEASE T THIRTY ASK ER LESS PLUS T FIFTY AT EVACUATE LEVEL POUND T SIXTY ATTENTION EXIT LIMIT PRESS T SEVENTY BRAKE FAIL LOAD PRESSURE L EIGHTY BUTTON FAILURE LOCK PULSE EIGHTY BUTTON FAILURE LOCK PULSE THOUSAND CANCEL FASTER MAINTAIN RATE W MILLION CASE FEET MARK RE THOUSAND CANCEL FASTER MAINTAIN RATE W MILLION CASE FEET MARK RE ZERO CAUTION FIFTH MAXIMUM REACH W A CENT FIRST MEGA RECEIVE W G CHECK FLOOR MINUS ROOM H CLOSE FUEL MINUTE SAFE A K COMPLETE GO NEAR SELECT 33		SPEED
SEVEN W DEPOSIT HIGHER ON SELECT SALE SEVEN W DEPOSIT HIGHER ON SELECT SALE SEVEN SEVENTY BUY FARAD LOW GIVEN SEVENTY BUY FARAD LOW GUARTER WILLION CASE FEET MARK RE COMPLET SELECT SAFE SEVENT SEVENTY BUY FARAD LOW GUARTER WILLION CASE FEET MARK RE COMPLET SECURE SECU		SS
EIGHT X DIAL HOLD ONWARD S NINE Y DIVIDE HOUR OPEN S TEN Z DO IN OPERATOR S ELEVEN ABORT DOLLAR INCHES OR TWELVE ADD DOOR INCORRECT OUT S THIRTEEN ADJUST DOWN INCREASE OVER T FOURTEEN ADVISORY EAST INTRUDER PARENTHESIS T FIFTEEN AGAIN ED IS PASS SIXTEEN ALARM EMERGENCY IT PER T SEVENTEEN ALERT END JUST PERCENT T EIGHTEEN AMPERE ENTRY KILO PLACE T TWENTY AND EQUAL LEFT PLEASE T THIRTY ASK ER LESS PLUS THIRTY ASSISTANCE ERROR LESSER POINT T FIFTY AT EVACUATE LEVEL POUND T SIXTY ATTENTION EXIT LIMIT PRESS T SEVENTY BRAKE FAIL LOAD PRESSURE L EIGHTY BUTTON FAILURE LOCK PULSE HONDRED CALL FAST LOWER RANGE V THOUSAND CANCEL FASTER MAINTAIN RATE WILLION CASE FEET MARK RE ZERO CAUTION FIFTH MAXIMUM REACH V A CENT FIRST MEGA RECCIVE V B COMPLETE GO NEAR SELECT 33 KK COMPLETE GO NEAR SELECT 33		STAR
NINE Y DIVIDE HOUR OPEN S TEN Z DO IN OPERATOR S ELEVEN ABORT DOLLAR INCHES OR S TWELVE ADD DOOR INCORRECT OUT S THIRTEEN ADJUST DOWN INCREASE OVER T FOURTEEN ADVISORY EAST INTRUDER PARENTHESIS T FIFTEEN AGAIN ED IS PASS T SIXTEEN ALARM EMERGENCY IT PER T EIGHTEEN ALL ENTER KEY PICO T NINETEEN AMPERE ENTRY KILO PLACE T TWENTY AND EQUAL LEFT PLEASE T THIRTY ASK ER LESS PLUS T FORTY ASSISTANCE ERROR LESSER POINT T SIXTY ATTENTION EXIT LIMIT PRESS T SEVENTY BRAKE FAIL LOAD PRESSURE LEIGHTY BUTTON FAILURE LOCK PULSE NINETY BUY FARAD LOW QUARTER LOW GUARTER LOCK PULSE NINETY BUY FARAD LOW QUARTER LOW THOUSAND CANCEL FASTER MAINTAIN RATE MILLION CASE FEET MARK RE ZERO CAUTION FIFTH MAXIMUM REACH W MILLION CASE FEET MARK RE ZERO CAUTION FIFTH MAXIMUM REACH W A CENT FIRE MEG READY W B CENTI FIRST MEGA RECEIVE W C CHANGE FLIGHT METER RECORD Y C CHECK FLOOR MICRO REPLACE Z FORWARD MILLI RIGHT E G CLIMB FROM MINUS ROOM J COMMA GET MOVE SECURE I		START
TEN Z DO IN OPERATOR S ELEVEN ABORT DOLLAR INCHES OR S TWELVE ADD DOOR INCORRECT OUT S THIRTEEN ADJUST DOWN INCREASE OVER T FOURTEEN ADVISORY EAST INTRUDER PARENTHESIS T FIFTEEN AGAIN ED IS PASS T SIXTEEN ALARM EMERGENCY IT PER SEVENTEEN ALERT END JUST PERCENT T EIGHTEEN ALL ENTER KEY PICO T NINETEEN AMPERE ENTRY KILO PLACE T TWENTY AND EQUAL LEFT PLEASE T THIRTY ASK ER LESS PLUS T THIRTY ASK ER LESS PLUS T FIFTY AT EVACUATE LEVEL POUND T SIXTY ATTENTION EXIT LIMIT PRESS SEVENTY BRAKE FAIL LOAD PRESSURE L EIGHTY BUTTON FAILURE LOCK PULSE LIMITY BUY FARAD LOW QUARTER L HUNDRED CALL FAST LOWER RANGE V THOUSAND CANCEL FASTER MAINTAIN RATE MILLION CASE FEET MARK RE JERO CAUTION FIFTH MAXIMUM REACH V A CENT FIRE MEG READY V B CENTI FIRE MEG READY V C CHANGE FLIGHT METER RECORD D CHECK FLOOR MICRO REPLACE Z C CHANGE FLIGHT METER RECORD C CHECK FLOOR MICRO REPLACE Z C CHANGE FLIGHT METER RECORD C CHECK FLOOR MICRO REPLACE Z C CHANGE FLIGHT METER RECORD C CLIMB FROM MINUS ROOM COMMA GET MOVE SECURE IS COMPLETE GO NEAR SELECT 33		STATION
ELEVEN ABORT DOLLAR INCHES OR TWELVE ADD DOOR INCORRECT OUT STATE TOWN INCREASE OVER TOWN INCREEN AGAIN ED IS PASS TOWN INCREEN AGAIN ED IS PASS TOWN INCREEN ALARM EMERGENCY IT PER TOWN INCREASE OVER TOW		STOP
TWELVE ADD DOOR INCORRECT OUT SET THIRTEEN ADJUST DOWN INCREASE OVER TO THIRTEEN ADJUST DOWN INCREASE OVER TO THIRTEEN ADJUSC EAST INTRUDER PARENTHESIS TO SIXTEEN AGAIN ED IS PASS TO SIXTEEN ALARM EMERGENCY IT PER TOWN TOWN TOWN TOWN TOWN TOWN TOWN TOWN		SWITCH
THIRTEEN ADJUST DOWN INCREASE OVER TOURTEEN ADVISORY EAST INTRUDER PARENTHESIS TO FIFTEEN AGAIN ED IS PASS TOURTEEN ALARM EMERGENCY IT PER TOURTEEN ALERT END JUST PERCENT TOURTEEN ALERT END JUST PERCENT TOURTEEN ALERT END JUST PERCENT TOURTEEN AMPERE ENTRY KILO PLACE TOURTEEN ASSISTANCE ERROR LESS PLUS TOURTEEN ASSISTANCE ERROR LESSER POINT TOURTEEN AT EVACUATE LEVEL POUND TOURTEEN AT EVACUATE LEVEL POUND TOURTEEN AT EVACUATE LOWER PRESSURE LEIGHTY BUTTON FAILURE LOCK PULSE LEIGHTY BUTTON FAILURE LOCK PULSE LEIGHTY BUY FARAD LOW QUARTER LOWER RANGE WILDINGTON CANCEL FASTER MAINTAIN RATE WILDING CANCEL FASTER MAINTAIN RATE WILDION CASE FEET MARK RE WILLION CASE FEET MARK RE WE CENTI FIRST MEGA RECCIVE WILLION CHARDER FLIGHT METER RECORD WE COMMON TOURTE FLOOR MICRO REPLACE		SYSTEM
FOURTEEN ADVISORY EAST INTRUDER PARENTHESIS TO FIFTEEN AGAIN ED IS PASS TO SIXTEEN ALARM EMERGENCY IT PER TO SEVENTEEN ALERT END JUST PERCENT TO EIGHTEEN ALL ENTER KEY PICO TO TO NINETEEN AMPERE ENTRY KILO PLACE TO THIRTY AND EQUAL LEFT PLEASE TO THIRTY ASK ER LESS PLUS TO THIRTY ASK ER LESS PLUS TO THIRTY ASSISTANCE ERROR LESSER POINT TO THIRTY AT EVACUATE LEVEL POUND TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEGITY BUTTON FAILURE LOCK PULSE LOCK PULSE LOCK PULSE LOCK PULSE LOW QUARTER LOW QUARTER LOW QUARTER LOW QUARTER LOW THOUSAND CANCEL FASTER MAINTAIN RATE WILLION CASE FEET MARK RE CENTI FIRST MEGA RECCIVE WILLION CHANGE FLIGHT METER RECORD WILLION CHECK FLOOR MICRO REPLACE TO CHECK FLOOR MICRO REPLACE TO CHECK FLOOR MICRO REPLACE TO CLEAR FORWARD MILLI RIGHT OF COUNTY OF THE COLLISION GAS MORE SECOND FOR THE COUNTY OF THE COLLISION GAS MORE SECOND FOR THE COUNTY OF THE COLLISION GAS MORE SECOND FOR THE COUNTY OF THE		TEST
FIFTEEN AGAIN ED IS PASS TO SIXTEEN ALARM EMERGENCY IT PER TO SEVENTEEN ALERT END JUST PERCENT TO SEVENTEEN ALL ENTER KEY PICO TO SIXTEEN ALL ENTER KEY PICO TO SIXTEEN AMPERE ENTRY KILO PLACE TO SIXTEEN AMPERE ENTRY KILO PLACE TO SIXTEEN AND EQUAL LEFT PLEASE TO SIXTEEN AND EXAMPLE SEVENTY BRAKE ERROR LESSER POINT TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEGHTY BUTTON FAILURE LOCK PULSE LOW QUARTER LOW QUARTER LOW QUARTER LOW QUARTER LOW QUARTER LOW GUARTER GUART GUART GUART GUARTER GUART GUART GUART GUART GUART GUART GUA		
SIXTEEN ALARM EMERGENCY IT PER TO SEVENTEEN ALERT END JUST PERCENT TO SEVENTEEN ALERT END JUST PERCENT TO SEVENTEEN ALL ENTER KEY PICO TO SEGMENT TO SEVENTY AND EQUAL LEFT PLEASE TO THIRTY ASK ER LESS PLUS TO SIXTY ASSISTANCE ERROR LESSER POINT TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEGITY BUTTON FAILURE LOCK PULSE LEGITY BUTTON FAILURE LOCK PULSE LEGITY BUY FARAD LOW QUARTER LEGITY BUY FARAD LOW RANGE WILLION CASE FEET MARK RE WILLION CASE FLIGHT METER RECORD WILLION CHANGE FORWARD MILLI RIGHT COLLISION GAS MORE SECOND COMMA GET MOVE SECURE TO SECUR		
SEVENTEEN ALERT END JUST PERCENT TO EIGHTEEN ALL ENTER KEY PICO TO NINETEEN AMPERE ENTRY KILO PLACE TO TWENTY AND EQUAL LEFT PLEASE TO THIRTY ASK ER LESS PLUS TO THIRTY ASSISTANCE ERROR LESSER POINT TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEGITY BUTTON FAILURE LOCK PULSE LOWER RANGE WILLIAM RATE WILLIAM REACH W		THAN
EIGHTEEN ALL ENTER KEY PICO TO NINETEEN AMPERE ENTRY KILO PLACE TO TWENTY AND EQUAL LEFT PLEASE TO THIRTY ASK ER LESS PLUS TO THIRTY ASSISTANCE ERROR LESSER POINT TO THE FIFTY AT EVACUATE LEVEL POUND TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEGHTY BUTTON FAILURE LOCK PULSE UNINETY BUY FARAD LOW QUARTER LOWNINETY BUY FARAD LOW RANGE WILLION CASE FEET MARK RE MILLION CASE FEET MARK RE CENT FIRE MEG READY WE ARE SECOND TO THE FORWARD MILLI RIGHT RECORD TO THE FORMARD TO THE		THANK
NINETEEN AMPERE ENTRY KILO PLACE TOWNSTY AND EQUAL LEFT PLEASE TOWNSTY ASK ER LESS PLUS THIRTY ASK ER LESS PLUS TOWNSTY ASSISTANCE ERROR LESSER POINT TOWNSTY ATTENTION EXIT LIMIT PRESS TOWNSTY BRAKE FAIL LOAD PRESSURE LEGHTY BUTTON FAILURE LOCK PULSE LEGHTY BUY FARAD LOW QUARTER LOWNSTAND CANCEL FAST LOWER RANGE WILLION CASE FEET MARK RE WILLION CASE FEET MARK RE WILLION CASE FEET MARK RE WILLION CASE FEET MEG READY WAS A CENT FIRE MEG READY WAS A CENT FIRE MEG READY WAS A CENT FIRE MEGA RECEIVE WE CENT FLOOR MICRO REPLACE TOWNSTAND CHANGE FLIGHT METER RECORD WILLION CHANGE FLOOR MICRO REPLACE TOWNSTAND CHANGE FLOOR MICRO REPLACE TOWNSTAND FROOM TOWNSTAND TO		THE
TWENTY AND EQUAL LEFT PLEASE THIRTY ASK ER LESS PLUS TORTY ASSISTANCE ERROR LESSER POINT TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEGHTY BUTTON FAILURE LOCK PULSE LEGHTY BUY FARAD LOW QUARTER LOWNINETY BUY FARAD LOW QUARTER LOWNINETY BUY FARAD LOW QUARTER LOWNINDERD CALL FAST LOWER RANGE WILLION CASE FEET MARK RE WILLION CASE FEET MARK RE WILLION CASE FEET MARK RE WILLION CASE FEET MEG READY WAS BUTTON FIRE MEG READY WAS BUTTON FIRE MEG RECEIVE WAS CENTI FIRST MEGA RECEIVE WAS CENTI FIRST MEGA RECEIVE WAS CENTI FIRST MEGA RECEIVE WAS CENTI FLOW MILE REVERSE AS CIRCUIT FLOW MILLI RIGHT AS CICCUIT FLOW MOVE SECURE AS COMPLETE GO NEAR SELECT AS COMPLETE GO NEAR SELECT		THIRD
THIRTY ASK ER LESS PLUS TO FORTY ASSISTANCE ERROR LESSER POINT TO FIFTY AT EVACUATE LEVEL POUND TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEGHTY BUTTON FAILURE LOCK PULSE LEGHTY BUY FARAD LOW QUARTER LOWNINETY BUY FARAD LOW QUARTER LOWNINETY BUY FARAD LOW QUARTER LOWNINETY BUY FARAD LOW GUARTER LOWNINETY GOOD CANCEL FASTER MAINTAIN RATE WE WILLION CASE FEET MARK RE WE WILLION CASE FEET MARK RE WE WILLION CASE FEET MAXIMUM REACH WE WILLION CASE FEET MEGA RECEIVE WE WILLION COUNTY FIRE MEGA RE		THIS
FORTY ASSISTANCE ERROR LESSER POINT TO FIFTY AT EVACUATE LEVEL POUND TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEIGHTY BUTTON FAILURE LOCK PULSE LEIGHTY BUY FARAD LOW QUARTER LONDER RANGE WITHOUSAND CANCEL FASTER MAINTAIN RATE WITHOUSAND CANCEL FASTER MAINTAIN RATE WITHOUSAND CASE FEET MARK RE WITHOUSAND CAUTION FIFTH MAXIMUM REACH WITHOUSAND CAUTION FIFTH MAXIMUM REACH WITHOUSAND CAUTION FIFTH MAXIMUM REACH WITHOUSAND COUNTY FIRE MEG READY WITHOUSAND COUNTY FIRE MEG READY WITHOUSAND COUNTY FIRE MEGA RECEIVE WITHOUSAND MICHOR REPLACE ZEAR FLOOR MICHOR REPLACE ZEAR FORWARD MILLI RIGHT REFERSE AND MINUS ROOM COUNTY FLOW MILE REVERSE AND MINUS ROOM COUNTY FOR MINUS ROOM		TIME
FIFTY AT EVACUATE LEVEL POUND TO SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEIGHTY BUTTON FAILURE LOCK PULSE LOW QUARTER LO		TOTAL
SIXTY ATTENTION EXIT LIMIT PRESS TO SEVENTY BRAKE FAIL LOAD PRESSURE LEIGHTY BUTTON FAILURE LOCK PULSE LEIGHTY BUY FARAD LOW QUARTER LEIGHTY BUY FARAD LOWER RANGE WENT THOUSAND CANCEL FASTER MAINTAIN RATE WENT LOWER RANGE WENT LOWER		TRAFFIC
SEVENTY BRAKE FAIL LOAD PRESSURE LEIGHTY BUTTON FAILURE LOCK PULSE LEIGHTY BUY FARAD LOW QUARTER LEWINDED CALL FAST LOWER RANGE WITHOUSAND CANCEL FASTER MAINTAIN RATE WITHOUSAND CASE FEET MARK RE WITHOUSAND REACH WITHOUSAND REPLACE ZEED CHANGE FLIGHT METER RECORD WITHOUSAND REPLACE ZEED CHECK FLOOR MICRO REPLACE ZEED CHECK FLOOR MILLI RIGHT REPLACE ZEED CHECK FLOOR MILLI RIGHT REPLACE ZEED CHECK FLOOR MILLI RIGHT REPLACE ZEED CHECK FLOOR MINUS ROOM ZEED CHECK FUEL MINUTE SAFE AND COMMA GET MOVE SECURE TO COMMA GET MOVE SECURE TO COMMA GET MOVE SECURE TO COMPLETE GO NEAR SELECT SECOND		TRY
EIGHTY BUTTON FAILURE LOCK PULSE LOWINETY BUY FARAD LOW QUARTER LOWINETY BUY FARAD LOW QUARTER LOWINETY BUY FARAD LOW QUARTER LOWING RANGE WITHOUSAND CANCEL FASTER MAINTAIN RATE WITHOUSAND CASE FEET MARK RE WITHOUSAND CASE FEET MARK RE WITHOUSAND CASE FEET MARK RE WITHOUSAND REACH WITHOUSAND RECEIVE WITHOUSAND RECEIVE WITHOUSAND RECEIVE WITHOUSAND RECEIVE WITHOUSAND RECEIVE WITHOUSAND RECEIVE WITHOUSAND REPLACE ZOWING REPLACE WITHOUSAND REVERSE AND WILL REVERSE AND WILL RECEIVE WITHOUSAND ROOM COMMANDED ROOM COMMAND ROOM		TURN
NINETY BUY FARAD LOW QUARTER LY HUNDRED CALL FAST LOWER RANGE W THOUSAND CANCEL FASTER MAINTAIN RATE W MILLION CASE FEET MARK RE ZERO CAUTION FIFTH MAXIMUM REACH W A CENT FIRE MEG READY W B CENTI FIRST MEGA RECEIVE W C CHANGE FLIGHT METER RECORD N D CHECK FLOOR MICRO REPLACE Z E CIRCUIT FLOW MILE REVERSE A F CLEAR FORWARD MILLI RIGHT E G CLIMB FROM MINUS ROOM H CLOSE FUEL MINUTE SAFE I COLLISION GAS MORE SECOND J COMMA GET MOVE SECURE K COMPLETE GO NEAR SELECT		UP
HUNDRED CALL FAST LOWER RANGE VERY THOUSAND CANCEL FASTER MAINTAIN RATE VERY MILLION CASE FEET MARK RE VERY MILLION CASE FEET MARK RE VERY MARK MEGA RECEIVE VERY		USE
THOUSAND CANCEL FASTER MAINTAIN RATE WILLION CASE FEET MARK RE VILLION CASE FEET MARK RE VILLION FIFTH MAXIMUM REACH VILLION FIRE MEG READY VILLION FIRST MEGA RECEIVE VILLION CONTROL OF CHANGE FLIGHT METER RECORD VILLION CHECK FLOOR MICRO REPLACE ZILLION MILE REVERSE AS FORWARD MILLI RIGHT ES CLEAR FORWARD MILLI RIGHT ES CLIMB FROM MINUS ROOM ZILLION CASE FUEL MINUTE SAFE AS COMPLETE GO NEAR SELECT 33		UTH
MILLION CASE FEET MARK RE ZERO CAUTION FIFTH MAXIMUM REACH W A CENT FIRE MEG READY W B CENTI FIRST MEGA RECEIVE W C CHANGE FLIGHT METER RECORD Y D CHECK FLOOR MICRO REPLACE Z E CIRCUIT FLOW MILE REVERSE A F CLEAR FORWARD MILLI RIGHT B G CLIMB FROM MINUS ROOM Z H CLOSE FUEL MINUTE SAFE A I COLLISION GAS MORE SECOND J COMMA GET MOVE SECURE II		WAITING
ZERO CAUTION FIFTH MAXIMUM REACH V A CENT FIRE MEG READY V B CENTI FIRST MEGA RECEIVE V C CHANGE FLIGHT METER RECORD Y D CHECK FLOOR MICRO REPLACE Z E CIRCUIT FLOW MILE REVERSE A F CLEAR FORWARD MILLI RIGHT B G CLIMB FROM MINUS ROOM Z H CLOSE FUEL MINUTE SAFE A I COLLISION GAS MORE SECOND J COMMA GET MOVE SECURE II		WARNING
A CENT FIRE MEG READY V B CENTI FIRST MEGA RECEIVE V C CHANGE FLIGHT METER RECORD Y D CHECK FLOOR MICRO REPLACE Z E CIRCUIT FLOW MILE REVERSE A F CLEAR FORWARD MILLI RIGHT E G CLIMB FROM MINUS ROOM Z H CLOSE FUEL MINUTE SAFE A I COLLISION GAS MORE SECOND E K COMPLETE GO NEAR SELECT 33		WATER
B CENTI FIRST MEGA RECEIVE V C CHANGE FLIGHT METER RECORD Y D CHECK FLOOR MICRO REPLACE Z E CIRCUIT FLOW MILE REVERSE A F CLEAR FORWARD MILLI RIGHT E G CLIMB FROM MINUS ROOM Z H CLOSE FUEL MINUTE SAFE A I COLLISION GAS MORE SECOND E J COMMA GET MOVE SECURE II K COMPLETE GO NEAR SELECT		WEIGHT
C CHANGE FLIGHT METER RECORD YOUR CHECK FLOOR MICRO REPLACE ZEE CIRCUIT FLOW MILE REVERSE AS FORWARD MILLI RIGHT EEE CLIMB FROM MINUS ROOM ZEE CLIMB FROM MINUS ROOM ZEE CLIMB FROM MINUTE SAFE AS FOLLISION GAS MORE SECOND EEE COMPLETE GO NEAR SELECT 33		WEST
D CHECK FLOOR MICRO REPLACE E CIRCUIT FLOW MILE REVERSE F CLEAR FORWARD MILLI RIGHT G CLIMB FROM MINUS ROOM H CLOSE FUEL MINUTE SAFE I COLLISION GAS MORE SECOND J COMMA GET MOVE SECURE K COMPLETE GO NEAR SELECT		WINDOW
E CIRCUIT FLOW MILE REVERSE F CLEAR FORWARD MILLI RIGHT E G CLIMB FROM MINUS ROOM H CLOSE FUEL MINUTE SAFE I COLLISION GAS MORE SECOND J COMMA GET MOVE SECURE K COMPLETE GO NEAR SELECT		YES
F CLEAR FORWARD MILLI RIGHT & G CLIMB FROM MINUS ROOM 2 H CLOSE FUEL MINUTE SAFE 4 I COLLISION GAS MORE SECOND & G COMMA GET MOVE SECURE 1 K COMPLETE GO NEAR SELECT 3		ZONE
G CLIMB FROM MINUS ROOM H CLOSE FUEL MINUTE SAFE I COLLISION GAS MORE SECOND J COMMA GET MOVE SECURE K COMPLETE GO NEAR SELECT		400-Hz TONE
H CLOSE FUEL MINUTE SAFE 4 I COLLISION GAS MORE SECOND E J COMMA GET MOVE SECURE 1 K COMPLETE GO NEAR SELECT 3		800-Hz TONE
I COLLISION GAS MORE SECOND E J COMMA GET MOVE SECURE 1 K COMPLETE GO NEAR SELECT 3		20-ms SILENCE
J COMMA GET MOVE SECURE 1 K COMPLETE GO NEAR SELECT 3		40-ms SILENCE
K COMPLETE GO NEAR SELECT 3		80-ms SILENCE
, , , , , , , , , , , , , , , , , , , ,		160-ms SILENCE
		320-ms SILENCE
L CONNECT GOING NEED SEND		
M CONTINUE GRAM NEXT SERVICE		
N CONTROL GREAT NO SET		
O COPY GREATER NORMAL SIDE		
P CORRECT HALF NORTH SLOW	COF	




Figure A.2.3-3. Block Diagram of LED TCAS Display




Figure A.2.4-1. Block Diagram of FAA-Supplied Airborne Intelligent Display (AID) System




Figure A.2.4-2. AID Message Byte Definition

A.2.5 GRAPHIC CAS ADVISORY DISPLAY

Graphic CAS advisories were presented on a Collins color monitor driven by a Smiths color graphics generator. The test conductor was able to select between two graphic modes. One mode was identical to the one supplied with the FAA AID. The other was an advanced graphic presentation.

The data format and bus to the Smiths graphics generator was identical to the one defined in Section A.2.4.

A.2.6 CAS/IVSI UNIT

An Intercontinental Dyanmics Corporation instantaneous vertical speed indicator (IVSI) modified with collision avoidance system director lamps was used for the tests. The IVSI analog syncro needle was driven by the host simulation computer with an analog syncro driver. The eight "eye brow" lamps and two arrows were driven by the BEU simulation unit. Refer to Figure A.2-1.


A.3 SIMULATION AUDIO AND VIDEO SUPPORT

A.3.1 Simulation Audio

1

A multiple tape player audio system was used to provide specific and general ATC information plus aero and engine noise. Figures A.3-1 and A.-3-2 show the audic system block diagram and equipment arrangement.

The three ATC audio cassette players and aero-engine reel-to-reel tape player were under limited control of the host computer via the Master Control Console, Section A.3.3. The aero-engine noise and ATC background audio tapes could only be started and stopped. The ATC special and ATC TCAS messages could be started by the host but they would not stop until the host signaled a stop and an end of message signal was sensed on the tapes second audio channel. This arrangement allowed the host computer to precisely start ATC messages. The tapes would stop at the end of one message and be positioned at the start of the next one.






Figure A.3.1.1 Audio Equipment Block Diagram




Figure A.3.1-2. Audio Equipment Rack Layout

All the ATC audio cassettes outputs were mixed and amplified by one channel of a 60 watt per channel Morantz amplifier. A microphone input for the test conductor was also mixed with the ATC messages. This microphone was normally used before and after a mission scenario.

The aero-engine noises were output on separate channels from the reel-to-reel tape player. The host controlled the output levels of channel with programmable amplifiers. The programmable amplifiers are described in Section A.3.3. An Altec Lansing audio frequency equalizer was used to shape the aero and engine noises to make them more realistic sounding. After the equalizer, an audio mixer was used so that each of the two large speakers would have both aero-engine noises. A 300 watt per channel audio amplifier was able to boost the aero-engine noise levels to realistic volumes.

A.3.2 Simulation Visual

A moving outside visual scene was projected on a thirty foot diameter hermispherical screen in front of the cah. This scene was projected by a black and white projector that was mounted on foo of the cah, directly over the pilot's head. The moving scenes were provided by a closed-circuit serve camera and "canned" visual intrusions on a video cassette player. Figure A.3.2-1 shows the video system layout.

Take-off and landing scenes were generated with the closed-circuit serve camera scanning an airport model. The intruder scenes were prerecorded on the inch video cassette. When a intrusion sequence was to start the host computer started the video player. The master control console had circuitry that would sense the end of the scene and stop the tape.




Figure A.3.2-1. Video System Layout

A.3.3 Simulation Audio and Vider Control

Located next to the cab, on the main floor of the simulation room, the master conductor console provided a good view of the projection screen, the pilot station, and the audio and video equipment. Through a terminal on the console, the test conductor controlled the simulation host computer and varies simulation parameters. An intercom system permitted communication with the host computer room, the model room, and the cab. The console layout is shown in Figure A.3.3-1.

The audio equipment rack was located next to the console. Most of the audio system controls were remoted to the console, and the close proximity of the equipment rack afforded easy visual verification of actions taken. The master conductor console had an internal in line has that was fed from a 16-bit interface with the host. This interface allowed the bost computer to directly control the audio players, video tisyer, three clocks, aero-engine programmable amplifiers. It also provided an interface with the TAV unit to pass aircraft system alerts. Pefer to Figure A.3.3-2 for a block diagram of the interface bus. The device into faces are defined below.

Device Interface #1, Address 1 famous

```
Data Line -
             0
                     slide projector direction, high = focward, low = reverse
                     slide projector 1, high = nable, low = disable
slide projector 1, high = mable, low = disable
              3
                     slide projector 3, high a wouble, low = disable
                              HOLD - TOW, D'IN - HEAR, RESET - TOW
             Δ
                     MCC,
                                      7 (11.)
                                                  7 m
                     clocks
                     audio cassette : PLAY = Migh, STOP = low
                     audio cassetto ?. PLAY = hooh, STOP = low
             Я
                     audio cassetta v. P.AY - high. STOD = lov
             0
                     audio reel, FIAV - high, STOP = low
             10
                     video cassetto, DLAY Active High
                     video cassette, PANSE Activo High
            11
   ADDR.
            12
            13
             14
            15
   Notes:
                 stide projectors of not be used for TCAS study
                 audio cassette - will play TCAS Special Messages
                 audio cassetto " will allow ATD "nochal Messages"
                 audio cassette a walk of w 4% Cackground Communication
                 audio rool will els to and Engine Noise
```





Figure A.3.3.1. Master Conductor Console Layout



A-28

Device Interface #2, Address 2 (0010B)

This address is used to direct the TAV microprocessor or to sound the alerting tones and light the glareshield mounted master warning/caution switch. Values are latched and held until changed by host.

```
Data Line - O
                       master warning light, high = on, low = off
                       master caution light, high = on, low = off
                       warning tone, high = on, low = off
caution tone, high = on, low = off
              3
                       advisory tone, high = on, low = off
              q
                       N/C
                       N/C
             10
                       N/C
            11
                       N/C
   ADDR.
             12
                       0
            13
                       1
             14
                       0
             15
                       0
```

Device Interface #3, Address 3 (0011B)

This address controls the Aero and Engine Noise Programmable Amplifiers. Aero uses amp. #1 and Engine uses amp. #2. Values are latched and held until changed by the host.

A.4 HOST COMPUTER AND INTERFACING EQUIPMENT

The simulation host computer was comprised of three Varian V75 computers operating in parallel. A nine-track magnetic tape system was used to record pilot responses, flight parameters, and flight data.

All simulation equipment, including the flight instruments, were controlled by the simulation host computer through a chaining I/O controller (or chain controller). The chain controller on instruction from the host computer passed data to selected instruments (or hardware) or retrieved data from the simulator. The chain controller also interfaced with the test conductor's console and the model room. The chain controller cycled at a rate of 2.5 to 10 milliseconds. Maximum usage brought it down to 10 milliseconds per cycle. Therefore, the maximum delta between a pilot's or flight engineer's action and the notation of that action was approximately one one-hundredth of a second.

APPENDIX B

PILOT TRAINING CHECKLIST

PILOT BRIEFING CHECKLIST

INTRODUCTION

1. Background

- a. This is an FAA program that develops a systematic approach to collision avoidance systems.
- b. The program is a two-phase effort, this is the first phase.
- c. This first phase evaluates elements of the potential TCAS alerting system.
- d. The second phase will place a candidate system in an operational simulator.

You will participate in these tests, as well as the operational tests. Eventually, a system will go on to flight test abound an FAG 727.

2. Phase 1 objectives

- a. Evaluate TCAS display technology for both conventional and electronic flight decks.
- b. Validate voice only as a viable command display.
- c. Determine the effect on the pilots response performance of adding threat advisory alert(s).
- d. Evaluate the effect of adding range and altitude to the throat advisory information.
- e. Evaluate the effect of adding bearing to the threat advisory information.
- f. Investigate the effect of presenting threat advisories which do not progress to avoidance maneuver commands.

II. FLIGHT TASK

- 1. Active displays
 - a. EADI, HUD (if installed)
 - b. HSI/DME/gourse arrow

- c. Airspeed
- d. Altimeter
- e. Vertical speed/resolution advisory display
- f. Clock
- q. Alert display(s)
- h. Engine instruments
- i. Flaps
- j. 12 key
- k. LED resolution advisory display
- 1. AID traffic advisory display
- m. CRT traffic advisory display

2. Active controls

- a. Wheel and column
- Rudder and toe brake
- c. Speed brake
- d. Flaos
- e. Gear
- f. Fire handles
- g. Response switches
- h. 12 key
- i. Throttles

3. Flight path

- a. Takeoff
- b. Climb-cloud layer VFR on top
- c. Cruise
- d. Descent-cloud layer 280' ceiling
- e. Land
- f. Turns
- q. Autothrottle
- h. Windshear
- i. Updates

4. ATC

- a. Flight path direction
- b. Traffic annunciation

III. CREW ALERTING

- 1. Advanced system displays
 - Information (systems/AID/CRT)
 - b. Master visual
 - c. Master aural
 - d. Voice alerts
 - e. Time critical (LED/IVSI)
 - f. EADI/HUD change
- Conventional system display (not used in this test)
 - a. Distributed alerts
 - b. Annunciator panel
 - c. Discrete tones
- Alert response
 - a. Flight management responses
 - b. System management responses
 - c. Collision avoidance responses
- 4. Review alerts and responses

IV. TRAINING FLIGHTS

- 1. Airplane familiarization flight
 - a. Review handling
 - b. Introduce ATC quidance
 - c. Familiarization with flight plan
 - d. Familiarization with visual encounters
- 2. TCAS system familiarization
 - a. Review possible alerts
 - b. Review responses

APPENDIX C

POST FLIGHT OUESTIONNAIRES

POST-FLIGHT QUESTIONNAIRE (IVSI)

Please complete the following questions with respect to the BCAS configuration that you flew with on your last flight. Use the Comments section freely since your input is important to the development of useful recommendations. Also use the Comments section to enumerate any operational difficulties you foresee with this TCAS configuration.

Pilot:			Da	ite:	
TCAS Config	uration:				
l. In gene unambig	eral, were the ac	tions required	hy the commands	s clear and	
	Always	Usually	Sometimes	Sel dom	Never
	75%	<u>25%</u>			
Comments:					
2. Did the	use of colors t	melp in interpr	eting the comman	nd display?	
	Very much	Some	Very little	None	
	33%	42%	17%	8%	
Comments:					
	modification of ne primary purpos			and lights d	etract
	io pi imorgi par por		-		
	YES	NO			
	8%	92%			
Comments:					
		C-2			

				100 MUCH or TO not informativ	00 LITTLE inform ve enough?	mation; that
	Ahout r	iaht <u>83%</u>				
	Add the	following:	How much and	how fast, use	TCAS light mo	re
	Delete	the following	:			
Com	nments:					
						· · · · · · · · · · · · · · · · · · ·
		fpm) vertica	l acceleratio	ons? Sometimes	ke larger than Seldom	
			17%	<u>50</u>	<u>8%</u>	25%
Com	ments:					
Com	nments:			<u>50</u>		
						25%
	Did the	master alert	(s) enhance o	or detract fro	m system effec	25%
	Did the	master alert	(s) enhance o	or detract fro		25%
	Did the	master alert	(s) enhance o	or detract fro	m system effec Greatly	25%
6.	Did the Greatly Enhance	master alert	(s) enhance o No Effect	n detract fro Detract	m system effec Greatly	25%
6.	Did the Greatly Enhance	master alert	(s) enhance o No Effect	n detract fro Detract	m system effec Greatly	25%

In the space below please describe any difficulties you had during the flight and/or with the TCAS equipment. Also use the space to give any overall comments on the TCAS display(s) and information presentation.

POST-FLIGHT OUESTIONNAIRE (LED)

Please complete the following questions with respect to the BCAS configuration that you flew with on your last flight. Use the Comments section freely since your input is important to the development of useful recommendations. Also use the Comments section to enumerate any operational difficulties you foresee with this TCAS configuration.

10+:				Nate:_	
AS Configurat	ion:			·	
In general, unambiquous		ctions requ	ired by the co	ommands cle	ar and
	A1 ways	lisually	Sometimes	Seldom	Never
	25°	<u>50</u>	179	8%	
omments: <u>Limit</u>	Commands d	ifficult to	read		
. Did the use	e of colors	help in int	erpretima the	command di	splay?
	Very much	Some	Very little	e None	
	170	668		17%	
omments:					
Ommeries.					·
					
					·

3.				MUCH or TOO not informative		nformation; that
	About rig	ht <u>42%</u>				
	Add the f	ollowing: 8% a		nformation		
	Delete th	e following: <u>5</u> 0	7% too bus	sy, make graphi	cs more si	mple
Com	ments:					
				· · · · · · · · · · · · · · · · · · ·		
		pm) vertical ad Always ——	Usually 8%		Seldom	17%
5.	Did the m	aster alert(s)	enhance o	or detract from	system ef	fectiveness?
	Greatly	Enhance	No	Detract	Greatly	
	Enhance		Effect		Detract	
	17%	83%				
Com	ments:	······				

In the space below please describe any difficulties you had during the flight and/or with the TCAS equipment. Also use the space to give any overall comments on the TCAS display(s) and information presentation.

POST-FLIGHT OUESTIONNAIRE (VOICE)

Please complete the following questions with respect to the TCAS configuration that you flew with on your last flight. Use the Comments section freely since your input is important to the development of useful recommendations. Also use the Comments section to enumerate any operational difficulties you foresee with this TCAS configuration.

Pil.	ot:				Date:	
TCA						
1.	In general		actions requ	ired by the c	ommands cle	ar and
		A1 ways 50%	Usually <u>50%</u>	Sometimes	Seldom	Never
Com	ments: <u>With</u>	out visual,	voice/shoul	d stay on unt	il problem	is saved.
2.			_	00 MUCH or TO		formation; that
	About right	t 25%				
	Add the fol	llowing: 75	% voice shou	ld stay on, n	eed visual	
	Delete the	following:				
Com	ments:					
					·- · · · · · · · · · · · · · · · · · ·	

		A1 ways	Usually	Sometimes	Sel dom	Never
				33%	17%	50%
mn	nents:					
_	Did the d	isplay and/or	command car	use you to ma	ke larger t	han normal (.2
	to 1900 f	pm) vertical	acceleration	ns?		
		Always	Usually	Sometimes	Sel dom	Never
			0.50	C00	O or	170
			<u>25%</u>	<u>50%</u>	<u>8%</u>	17%
				n detract from		
					n system ef	
Omn	Did the m	aster alert(s	s) enhance of	r detract fro	n system ef	

In the space below please describe any difficulties you had during the flight and/or with the TCAS equipment. Also use the space to give any overall comments on the TCAS display(s) and information presentation.

POST-FLIGHT QUESTIONNAIRE (CURRENT GRAPHIC)

Please complete the following questions with respect to the TCAS configuration that you flew with on your last flight. Use the Comments section freely since your input is important to the development of useful recommendations. Also use the Comments section to enumerate any operational difficulties you foresee with this TCAS configuration.

		Date:			
ration:					
traffic advi	sories present	ted in time	to be effec	tively used?	
A1 ways 64%	Usually 36%	Sometimes	Sel dom	Never	
				······································	
				fic advisories?	
				THE GIVE SOLLES	
64%	272	99.			
	traffic advi Always 64% traffic advi More useful	traffic advisories present Always Usually 64% 36% traffic advisories as use More About useful as useful	traffic advisories presented in time Always Usually Sometimes 64% 36% traffic advisories as useful as curre More About Seldom useful as useful as useful	traffic advisories presented in time to be effect Always Usually Sometimes Seldom 64% 36% traffic advisories as useful as current ATC traff More About Seldom Never useful as useful as useful	

	Unacceptable	•			Large
	increase in	increase i	in on workload		decrease
	workload	workload	Λα	in workload	
		73%	<u>9%</u>	9%	9%
OM	ments: Much eas	ier than tab	oular, looking at s	creen breaks	up scan
•	Do you feel the normally see?	e threat dis	splay would help yo	u locate traf	ffic you would r
	Al ways	Usually	Sometimes	Sel dom	Never
		64%	36%		
or	ments:				
	Do you fee		naster caution alex	t was necessa	ary to draw you
	Do you fee attention	of that the m	naster caution alex	t was necessa	ary to draw you Never
	Do you fee attention	that the mean to the threa	naster caution alex		
5.	Do you fee attention Always	that the metor to the thread	naster caution alem at display? Sometimes		
5.	Do you fee attention Always 27% ments:	that the meto the thread	naster caution alem at display? Sometimes	Seldom	
. Off	Do you fee attention Always 27% ments:	that the meto the thread	naster caution alex of display? Sometimes 18% clear and unambig	Seldom	
S.	Do you fee attention Always 27% ments:	that the material to the thread Usually 55%	naster caution alex of display? Sometimes 18% clear and unambig	Seldom	Never

	format?	oo much or coo	TISCIE INTORNAC	ion provided by	the quibility
	About right	73%			
	Add the fol	lowing: 27% sys	stem accuracy, p	oredicted track	
	Delete the	following:			
	to indicate d	irection of mov	vement.	ntruder because	
			~		
١.	Did the use	of color in th	ne display aid y	ou in interpret	ing the
١.			Some	Very little	None
	message?	Very much	Some	Very little	None <u>18%</u>
	message?	Very much	Some	Very little	None <u>18%</u>
Commen	message? its: Were you ab	Very much	Some 9%	Very little 73% ation of the tra	None <u>18%</u>
Commen	message? its: Were you ab	Very much	Some 9% graphic presenta	Very little 73% ation of the tra	None <u>18%</u>

POST-FLIGHT QUESTIONNAIRE (NEW GRAPHIC)

Please complete the following questions with respect to the TCAS configuration that you flew with on your last flight. Use the Comments section freely since your input is important to the development of useful recommendations. Also use the Comments section to enumerate any operational difficulties you foresee with this TCAS configuration.

'1!ot:					Date	2:
CAS	Conf	figuration:				
•	Were	the traffic	advisories pr	resented in t	ime to be ef	ffectively used?
		Al ways	Usually 18%	Sometimes	Sel dom	Never
mme	ents:					
	Were	the traffic	advisories as	s useful as ci	urrent ATC 1	traffic advisories
		More	About	Seldom	Never	
		useful <u>64%</u>	as useful 27%	as useful	as useful	

U	nacceptable	Acceptable	No effect	Small	Large
i	ncrease in	increase in	on workload	decrease	decrease
,	vorkload	workload		in workload	in workload
		64%	9%	27%	
Commen	ts:				
		······································			
4. De	you feel th	e threat displa	y would help y	you locate tr	affic you woul
ne	ot normally s	ee?			
	Always	Usually	Sometimes	Sel dom	Never
	18%	45%	37%		
Commen	ts: Possibili	ty of misidenti	fication exist	ts	
					
		at the master c	caution alert w	was necessary	to draw your
5. Do	you feel th	nat the master c the threat displ		was necessary	to draw your
5. Do	you feel th	he threat displ	ay?		
5. Do	you feel th ttention to t Always	he threat displ Usually	ay? Sometimes		Never
5. Do	you feel th	he threat displ	ay?		
5. Do	you feel that tention to to the Always 18%	the threat displ Usually <u>64%</u>	ay? Sometimes $\frac{9\%}{}$	Sel dom	Never 9%
5. Do	you feel thattention to to the Always 18% ts: Do not ne	he threat displ Usually	ay? Sometimes $\frac{9\%}{}$	Sel dom	Never 9%
5. Do	you feel thattention to to the Always 18% ts: Do not ne	the threat displ Usually <u>64%</u>	ay? Sometimes $\frac{9\%}{}$	Sel dom	Never 9%
5. Do	you feel thattention to to the Always 18% ts: Do not ne	the threat displ Usually <u>64%</u>	ay? Sometimes $\frac{9\%}{}$	Sel dom	Never 9%
5. Do	you feel thattention to to the Always 18% ts: Do not ne	the threat displ Usually <u>64%</u>	ay? Sometimes $\frac{9\%}{}$	Sel dom	Never 9%
5. Do	you feel thattention to to the Always 18% ts: Do not ne	the threat displ Usually <u>64%</u>	ay? Sometimes 9% , visual and a	Seldom	Never 9%
5. Do	you feel thattention to to the Always 18% ts: Do not ne	the threat displushed three levels	ay? Sometimes 9% , visual and a	Seldom	Never 9%
5. Do	you feel thattention to to the Always 18% ts: Do not ne	the threat displushed Usually 64% ed three levels	Sometimes 9% visual and a	Seldom nural should	Never 9% come oN at the

7.	Was ther format?	e too much	or too littl	e informatio	n provided	by the grap	hic
	About ri	ght <u>91%</u>					
	Add the	following:	9% instruder	's speed		·	
	Delete t	he followi	nq:				
Com	ments:						
							
۸.	Were you	able to r	read the tabul	ar informati	on fast end	ough?	
	A1 w	ays	Usually	Sometimes	Seldom	Never	
	98		26%	64%			
Com	ments:						
9.	Were you	able to u	ise the tabula	ir data to an	ticipate th	ne evasive m	naneuver?
	AT w	ays	Usually	Sometimes	moh fa2	Never	
			64%	36%			
Com	ments:						

POST-FLIGHT OUESTIONNAIRE (TABULAR WITHOUT BEARING)

Please complete the following questions with respect to the TCAS configuration that you flew with on your last flight. Use the Comments section freely since your input is important to the development of useful recommendations. Also use the Comments section to enumerate any operational difficulties you foresee with this TCAS configuration.

	:)ate:	
rcas I	Confi	guration:					
. Were	Were	the traff	fic adviso	ries presented	es presented in time to be effectively u		
		Always 45%	Often 36%	Sometimes	Seldom	Never	
Comme	ents:						
			traffic a	idvisories as us	***************************************	ent ATC traffic	
		Were the	traffic a	dvisories as us	***************************************	ent ATC traffic Never	
		Were the	traffic a es? More	dvisories as us	eful as curr Seldom	Never	
2.		Were the	traffic a es? More useful 9%	idvisories as us About	eful as curr Seldom	Never	

3.	How did the a		affect you	ur workload	as compare	ed to current
	Unacceptable increase in workload 27%		se in on oad	No effect n workload		Large dacrease id in workload
Comments:	Too much inte	erpretation	n, multiple	alerts imp		
4.	Do you feel to			ould help yo	ou locate t	raffic you
Comments:	Always Us	sually ——	Sometimes 91%	Se1 do	N mx	ever
5.	Do you feel t			ion alert wa	is necessar	y to draw your
	Al ways Us	sually 5 <u>%</u>	Sometimes	Seldom	Never	
Comments:	Chime is ina	inquate				
6.	Did the tabul		rovide a ci	lear and una	ambiguous r	epresentation
	Al ways Us	•	Sometimes 36%	Se1do <u>9%</u>		ever <u>6%</u>
Comments:	Too hard to than the actu		where the	traffic is.	. Colors w	ere more

7.	Was there format?	too much or	too little in	formation prov	ided by the tabula
	About riq	ht <u>27%</u>			
	Add the f	ollowing:		3	
	Delete th	e following:			
Comments:	Do not li	ke update ra	ite		
৪.	Were you	able to read	I the tahular i	nformation fas	t enough?
	Al ways	Usually 54%	Sometimes	Seldom 9%	Never
Comments:					
۹.	Were you maneuver?		the tabular da	ta to anticipa	ite the evasive
	Al ways 27%	Usually 18%	Sometimes	Seldom	Never
Comments:	Especiall	y difficult	with multiple	intruders	

POST-FLIGHT QUESTIONNAIRE (TABULAR WITH BEARING)

BCAS Conf	figuration	·				
1.	Were the	traffic adv	visories present	ted in time to be	e effectivel	y used?
		A1 ways 55%	Usually <u>36%</u>	Sometimes	Seldom	Never
Comments	: <u>Multiple</u>	intruders	difficult.			
2				ful as current A	TO Aug SSign	

Were the traffic advisories as useful as current ATC traffic advisories?

More	About	Seldom	Never
useful	as useful	as useful	as usefu
18%	73%		q g
			

Comments	·		 	 	
		 	 	 	

3.	How did		s affect your	workload	as compared	to current
Common+c	increase workload	in incre 1 work <u>649</u>		workload	decrease in workload 9%	decrease in workload
		Juli 1119 111001				
4.		eel the threat t normally se	at display wou ee?	uld help yo	ou locate tra	ffic you
	Always	Usually <u>54%</u>	Sometimes 27%	Sel do 18%	om Nev	er
Comments:	:					
5.	<u>-</u>	eel that the n to the thre	master cautionate deat display?	on alert w	as necessary	to draw you
	=	Usually 27%	Sometimes	Selda	om Never	
Comments:						
6.	Nid the	tabular data	provide a clo	ear and un	ambiquous ren	resentation
·.	of the t		province a con			
	Al ways	Usually 36%	Sometimes	Seld	om Nev	er
Comments						

7.	Was there too much or too little information provided by the graphic format?
	About right 91%
	Add the following: 9% direction of intruder vertical motion
	Delete the following:
Comments:	Multiple intruders could not be understood
8.	Were you able to read the tabular information fast enough? Always Usually Sometimes Seldom Never
Comments:	9% 27% 64%
9.	Were you able to use the tabular data to anticipate the evasive maneuver?
	Always Usually Sometimes Seldom Never 64% 36%
Comments:	

APPENDIX D

DEBRIEFING OUESTIONMATRE

TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) FLIGHT CREW OUESTIONNAIRE

Name:							
Company:					PA	e:	·····
Present Position	n:			Aircr	aft:		
Pilot Certifica	te(s) Held:						· · · · · · · · · · · · · · · · · ·
Total Hours:			P	ast Year:			
In the space be above the aircress on.							
42% 83% (B-727)	50% (B-737)					8% L-1011)	(Other)
no you regularly	y fly into	TCA's?					
YES 100%							
<pre>(approximately _ (which airports')</pre>					· · · · · · · · · · · · · · · · · · ·)
Were you familia selection to par					r solicita	ation or	
YES 67%	NO	17%		VAGUEI	LY <u>17%</u>		
Comments concerr	ning TCAS:_	· · · · · · · · · · · · · · · · · · ·	_~~				
		· · · · · · · · · · · · · · · · · · ·			~~~~~		
							

Collision Avoidance System (TCAS) specifically. Although the comments are optional, they can provide a valuable contribution to the test program. Comments may be used to expand upon or qualify your initial answer, or to note that the question is not framed in a manner which allows your true opinion to be expressed. Therefore, please use the Comments sections liberally to ensure proper interpretation of your answers. If you are not familiar with certain aspects of the TCAS, please answer the question and indicate in the Comments section your reservations. If you comment exceeds the space provided please continue it on the back of the page or on a separate piece of paper (be sure to number the continuation with the question number). In this section of the questionnaire there are two types of questions: The first is multiple choice in which you should select the answer that most closely matches your opinion. Secondly, there are the open-ended questions asking for a written response. Please answer these completely. Remember there is no right or wrong answer; your thoughts are important.

- 1. In general, do) u feel that a collision avoidance system should be
 - a. Required on all aircraft immediately.
- 75% h. Required on all aircraft as soon as it can be implemented and demonstrated to perform reliably.
 - c. Required on all aircraft in the terminal area only.
- d. Required on all aircraft above or helow certain altitude
 (indicate altitude).

 above helow
- 8% e. Required on air carrier aircraft only.
- 89. f. Implemented as soon as it can be tied to the ATC system to provide total traffic control.
- 8% q. Not required.

Comments: Used as a back-up for ATC. System should be reliable, economically reasonable and compatible with ATC.

?a.		the display configurations that you flew during the test red to 3 = least preferred.
	1	IVSI AND VOICE
	2	LED AND VOICE
	1 2 3	VOICE ONLY
2b.	Please rank all	the threat advisory (TA) display formats that you observed
	(1 = most prefe	rred to 6 = least preferred).
	6	None
	2.6	Precursor Light
	$\frac{4.4}{3.2} \\ \frac{2.3}{1.5}$	Tabular without Angle of Arrival
	3.2	Tabular with Angle of Arrival
	2.3	Minimum Graphic
	1.5	Advanced Graphic
2c.	Are there any di	splays or formats that you would add? If so please
	describe them an	d give a rank relative to the above.
2d.	What display or	combination of displays would you like to see used by the
	TCAS system?	
	TCAS light plus	IVSI (45%) advanced graphic plus IVSI (55%) could use
EADI	on new aircraft	

3a.	Rank	the	following	items	in	relative	importance	for	accurate	resolution	of
	a coi	nflic	t (1 = mo:	st impo	orta	nt, 18 =	least impor	rtani	:).		

	Rank	Check if the item is essential
Altitude of other aircraft	1.8	100%
Heading of other aircraft	6.4	25%
Relative bearing	3.1	75%
Range of other aircraft	3.5	75%
Other aircraft type	16.8	
Vertical speed of other aircraft	8.7	17%
Horizontal closure rate	6.4	17%
Vertical closure rate	7.6	179
Closure angle	9.7	
Other aircraft identify	17.1	
Projected miss distance horizontal	9.2	
Projected miss distance vertical	9.5	
Direction of miss (e.g., passing to left)	12.7	
Time to closest approach	9.5	17%
Turning/not turning status of intruder	9.5	8%
Whether or not the intruder is TCAS equip	ped12.4	
Airspeed of intruder	11	
If intruder is ATC controlled	12.4	
mments:		
. Are there any other items of information conflict situation? If so please describe essential.	· ·	
Direction of vertical movement (42%)		
D-5		

	Unnecessary	CORRECTIVE	RESTRICTIVE 25%	
	Useful	8%	42%	
	Necessary	92%	33%	
. Do you feel t	hat both types of comman	nd have equal op	erational	
criticality?				
Corrective mo	ore Both the		Restrictive	
critical	same cri	ticality	more critical	
67%	33%			
	on, what is the hest process (e.g., alphanumeric, applice (100%)			
command aleri	cs (e.q., alphanumeric, a			
Arrow plus vo	cs (e.q., alphanumeric, a	arrows, pictoria	11, etc.)?	
Arrow plus vo	cs (e.g., alphanumeric, a	for restrictive	11, etc.)?	
Arrow plus vo	es (e.g., alphanumeric, obice (100%) Dest presentation format	for restrictive	11, etc.)?	
Arrow plus vo	es (e.q., alphanumeric, obice (100%) nest presentation format	for restrictive	11, etc.)?	
Arrow plus vo	es (e.g., alphanumeric, obice (100%) Dest presentation format	for restrictive	11, etc.)?	

Yes		NO		
67%		33%		
lain:				
	al, were the a clear and unam		by the command	is during the tes
ALWAYS	USUALLY	SOMETIMES	SELDOM	NE VER
ALWAYS 25%	USUALLY 58%	SOMETIMES	SELDOM	NE VER
			SELDOM	NE VER
25% ments:	58% eel that the c	17%		NEVER
25% nents: Do you f	58% eel that the c	17%		

8%		SOMETIMES	SELDOM	NE VER
	92%	<u> </u>		
ments: When	a pilot antid	cipates the comma	nd and it is	different he will
reluctant.				
	· · · · · · · · · · · · · · · · · · ·			
Did the dis	splay and/or	command cause yo	u to make lar	rger than briefed
) fpm) vertical a		*
ALWAYS	USUALLY	SOMETIMES	SELDOM	NEVER
8%	8%	33%	25%	17%
lights are	too bright	add horizontal a	mmowe indian	to manufued elimb
Lights are rate	too bright,	add horizontal a	rrows, indica	te required climb
	too bright,	add horizontal a	rrows, indica	te required climb
	too bright,	add horizontal a	rrows, indica	te required climb
rate				te required climb
rate		made in the LED		te required climb
what change		made in the LED :		te required climb
what change	es should be	made in the LED :		te required climb
what change	es should be	made in the LED :		te required climb
What change	es should be	made in the LED :	lisplay?	te required climb
What change	es should be nove to glare	made in the LED a	lisplay?	te required climb

YES	NO			
8%	92%			
omments:				
				
····				
No	61		42-2-1	
	e use of color or tion presented?	i the command	display help in i	nterpreting the
morna	cron presencen:			
	VERY MUCH	SOME	VERY LITTLE	NONE
	67%	25%		99
omments:				
		···	~. ~.	
hetween	your aircraft ar	nd an intruder	oresent the horizon. The first is because rat	y time (TAU) whic
hetween takes i	your aircraft ar	nd an intruder only range but	. The first is b	y time (TAU) whice. The second is
hetween takes in the acti	your aircraft ar	nd an intruder only range but	. The first is b also closure rat	y time (TAU) whice. The second is
between takes in the acti	your aircraft ar ito account not d ual range (distan	nd an intruder only range but nce to the int	t. The first is because ratering transfer to the control of the co	y time (TAU) whice. The second is
hetween takes in the acti	your aircraft an ito account not d ual range (distan	nd an intruder only range but ace to the int Range	t. The first is because ratering transfer to the control of the co	y time (TAU) whice. The second is formation would y
hetween takes i the acti prefer?	your aircraft an ito account not d ual range (distan	nd an intruder only range but ace to the int Range 42%	The first is be also closure rateruder). Which in No Preference	y time (TAU) whice. The second is formation would y
hetween takes i the acti prefer?	your aircraft and to account not of gual range (distant Time 42°	nd an intruder only range but ace to the int Range 42%	The first is be also closure rateruder). Which in No Preference	y time (TAU) whice. The second is formation would y
hetween takes i the acti prefer?	your aircraft and to account not of ual range (distant lime) 429 scale used in the	nd an intruder only range but nce to the int Range 42% ne test satisf	The first is be also closure rateruder). Which in No Preference	y time (TAU) whice. The second is formation would y
hetween takes in the acti prefer? 2b. Was the	your aircraft and to account not of ual range (distant lime) and the scale used in the Satisfactory	nd an intruder only range but nce to the int Range 42% ne test satisf	The first is be also closure rateruder). Which in No Preference	y time (TAU) whice. The second is formation would y Other 17%
hetween takes in the acti prefer? 2b. Was the Very	your aircraft and to account not of ual range (distant lime) and the scale used in the Satisfactory	nd an intruder only range but nce to the int Range 42% ne test satisf	The first is be also closure rateruder). Which in No Preference	y time (TAU) whice. The second is formation would y Other 17% Very
hetween takes in the acti prefer? The Was the Very Satisfactor	your aircraft and to account not of ual range (distant distant	nd an intruder only range but not the interest satisface test satisface Rorderline	The first is be also closure rateruder). Which in No Preference	y time (TAU) whice. The second is formation would y Other 17% Very
hetween takes in the acti prefer? Wery Satisfactor 9%	your aircraft and to account not of ual range (distant distant	nd an intruder only range but not the interest satisfies Rorderline 25%	The first is be also closure rateruder). Which in No Preference	y time (TAU) whice. The second is formation would y Other 17% Very

	YES 92%	NO9%		
Comments: Av	oid altitude (crosses, when ve	rtical change is	inappropriate whe
	altitude, in			
14. Since t	he present sy	stem provides on	ly vertical reso	lution advisory
	-	is the inclusio	n of vertical sp	eed on the TCAS
Command	Display?			
Extremely	Useful	Of No	Detrimental	Extremely
Useful		Use		Detrimental
33%	<u>50%</u>		17%	And Parlington
				ed in the same pla
•			arning was neede ion to the TCAS	
לנות ממס	ter aurai to	maw your accent	TON CO THE TOAS	alerist
	USUALLY	SOMETIMES	SELDOM	NEVER
ALWAYS		Οα	Oα	8%
ALWAYS 25%	50%	8%	8%	0.6

13. The current collision avoidance system prescribes only vertical evasive maneuvers. If technology would permit, do you feel that horizontal

maneuver should also be included and if so when would they be most useful

Excellent	Good	Fair	Poor	Unacceptable	Not
No Changes	Minor	Minor	Major	Major Changes	Needed
	Changes	Changes	Changes	Required	
	Beneficial	Recommended	l Recommended		
33%	58%		<u>8%</u>		
Comments: <u>T</u>	CAS light ver	ry heneficial	, aural must c	nincide with the	visual
				ed to ensure TCA	
			onditions (noise, liaht, de	compression
etc.) o	n the flight	deck?			
	YES 83%	NO 17%			
Comments:					
			-A (DA) da	facil Abak sama	£ £
10. 11.			rts (KA) do you	Teel that some	iomi oi
	ition to the			procood most PA	h fuow
cautio				preceed most RA	s, would
cautio	n alert (trad t TCAS?	ffic advisory		preceed most RA	s, would
cautio	n alert (trad t TCAS? VERY		v), which would	none	s, would
cautio	n alert (trad t TCAS? VERY MUCH	ffic advisory SOME	/), which would		s, would
cautio	n alert (trad t TCAS? VERY	ffic advisory	v), which would		s, would
cautio benefi	n alert (trad t TCAS? VERY MUCH 67%	ffic advisory SOME 33%	VERY LITTLE	NONE 	s, would
cautio benefi	n alert (trad t TCAS? VERY MUCH 67%	ffic advisory SOME 33%	v), which would	NONE 	s, would
cautio henefi 18h. If you	n alert (trad t TCAS? VERY MUCH 67% feel these v	ffic advisory SOME $\frac{33\%}{2}$ would be a be	VERY LITTLE	NONE xplain.	
cautio henefi 18b. If you <u>Takes</u>	n alert (train t TCAS? VERY MUCH 67% feel these w	ffic advisory SOME $\frac{33\%}{2}$ would be a be	VERY LITTLE	NONE 	
cautio henefi 18h. If you	n alert (train t TCAS? VERY MUCH 67% feel these w	ffic advisory SOME $\frac{33\%}{2}$ would be a be	VERY LITTLE	NONE xplain.	

	None (light only), more time	•	
8d.	What t	raffic sho	uld be displ	ayed on the th	nreat display (TA)?
	33%	Only thr	eats as d <mark>ef</mark> i	ned by the TCA	AS algorithms.
	33%	TCAS thr	eats with an	option to dis	splay surrounding traffic.
	33%	TCAS thr	eats with su	rrounding trad	ffic displayed automatically
		when a t	hreat is pre	esent.	
		All surr	ounding traf	fic displayed	with some filtering logic
		used to	reduce the r	umber.	
		All surr	ounding traf	fic displayed.	•
		Others -	explain.		
9.	If tho	twaffic a	duicomios (1	A) contain on	ly altitude and range informa-
					ill he considered an essential
		f a TCAS?	ne anciare	would liney so	The way was a second the
	μ υ	. 4 10/15			
		VERY	SOME	VERY	NONE
		MUCH		LITTLE	
		MUCH			
		мисн 33%	17%	17%	33%

20a. How useful do you feel the TCAS threat display will be in each flight phase?

		Ver			11 - 1 - 1 - 1 - 1 -
		Usef	ul Useful	Usefu1	Undesirable
Takeo	off		50%	17%	33%
C1 imb)	58%	17%	8%	17%
Cruis	se .	58%	8%	17%	17%
Desce	ent	58%	17%	8%	17%
Appro	pach	58%	8%	17%	17%
Landi	ina	8%	50%	8%	33%
?nb.	visual threa	at display, d	o you feel that	the format wi	11 have an effect
	visual threa	at display, d	o you feel that	the format wi	hic formats for th 11 have an effect ase? If so please
	visual three on the disponent	at display, d lays utilizat	o you feel that	the format wi t to flight ph	11 have an effect
	visual three on the disponent	at display, d lays utilizat	o you feel that ion with respec	the format wi t to flight ph	11 have an effect
	visual three on the disponent	at display, d lays utilizat	o you feel that ion with respec	the format wi t to flight ph	11 have an effect
	visual three on the disponent	at display, d lays utilizat	o you feel that ion with respec	the format wi t to flight ph	11 have an effect
21.	visual three on the displexplain. Graphic best	at display, d lays utilizat t (100%), nei	o you feel that ion with respec ther is too use	the format wi t to flight ph ful (42%)	11 have an effect
21.	visual three on the disp explain. Graphic best In the test	at display, d lays utilizat t (100%), nei	o you feel that ion with respec ther is too use	the format wi t to flight ph ful (42%)	ll have an effect ase? If so please

the traffic advisory alerts? Excellent Good Fair Poor Unacceptable Not to Changes Minor Minor Major Major Changes Needed Changes Changes Changes Required Beneficial Recommended Recommended 58% 25% 17% Explain: Will let you know when visual acquistion is not possible 4. What type of presentation do you feel was most appropriate for the traffic advisories? (Please rank 1 = most, 7 = least) None Precursor Tabular Tabular Minimum Advanced Both light without with graphics graphics tabular angle-of- angle-of- and arrival arrival		its: <u>As few</u>	as possit	ole			
Changes Changes Changes Required Beneficial Recommended Recommended 58% 25% 17% Explain: Will let you know when visual acquistion is not possible 44. What type of presentation do you feel was most appropriate for the traffic advisories? (Please rank 1 = most, 7 = least) Hone Precursor Tabular Tabular Minimum Advanced Both light without with graphics graphics tabular angle-of- angle-of- and arrival arrival graphic					gle of arriva	il (AOA) or bear	ing in usi
Changes Changes Changes Required Beneficial Recommended Recommended 58% 25% 17% Explain: Will let you know when visual acquistion is not possible 44. What type of presentation do you feel was most appropriate for the traffic advisories? (Please rank 1 = most, 7 = least) Hone Precursor Tabular Tabular Minimum Advanced Both light without with graphics graphics tabular angle-of- angle-of- and arrival arrival graphic	xcell	ent (Good	Fair	Poor	Unacceptable	Not
Reneficial Recommended Recommended 58% 25% 17% Explain: Will let you know when visual acquistion is not possible 4. What type of presentation do you feel was most appropriate for the traffic advisories? (Please rank 1 = most, 7 = least) Hone Precursor Tabular Tabular Minimum Advanced Both light without with graphics graphics tabular angle-of- angle-of- and arrival arrival graphic	o Cha	inges M	1inor	Minor	Major	Major Changes	Needed
4. What type of presentation do you feel was most appropriate for the traffic advisories? (Please rank 1 = most, 7 = least) lone Precursor Tabular Tabular Minimum Advanced Both light without with graphics graphics tabular angle-of- angle-of- and graphic			-			Required	
4. What type of presentation do you feel was most appropriate for the traffic advisories? (Please rank 1 = most, 7 = least) Hone Precursor Tabular Tabular Minimum Advanced Both light without with graphics graphics tabular angle-of- angle-of- and arrival arrival							
traffic advisories? (Please rank 1 = most, 7 = least) Ione Precursor Tabular Tabular Minimum Advanced Both light without with graphics graphics tabular angle-of- angle-of- and arrival arrival		_					
light without with graphics qraphics tabular angle-of- angle-of- and arrival arrival graphic		_			acquistiion	is not possible	
angle-of- angle-of- and arrival graphic	Explai	n: <u>Will le</u>	t you know	w when visual	eel was most	. appropriate fo	
arrival arrival graphic	(xplai	n: Will le	f presentatisories?	when visual ation do you f (Please rank	Feel was most 1 = most, 7 Minimu	: appropriate for = least) m Advanced	r the Both
	'A. W	n: Will le	f presentatisories? Tabular	ation do you f (Please rank Tabular t with	feel was most 1 = most, 7 Minimu graphi	: appropriate for = least) m Advanced	r the Both tabular
3/5 5.1 4.1 2.2 1.4 4.7	Explai	n: Will le	f presenta isories? Tabular without angle-of	when visual ation do you f (Please rank Tabular t with f- angle-of	feel was most 1 = most, 7 Minimu graphi	: appropriate for = least) m Advanced	r the Both tabular and

25.	When	all factors a	re considered	, how would you	describe the	value of TA's
	with	bearing compa	red to TA's w	ithout bearing?		
92%	Much	better with h	earing —			
8%	Bette	er with bearing	9			
	About	t the same - p	ro's and con'	s balance		
	Less	valuable with	bearing			
· 	Much	less valuable	- hearing is	detrimental		
	•					
Comm	ents:					
	·					
26.	Were	the traffic a	dvisories as	useful as verbal	l advisories f	rom ATC?
MUCH	MORE	MORE		SELDOM AS	NEVER AS	
USE	FUL	USEFUL	USEFUL	USEFUL	USEFUL	
_8	<u>~</u>	58%	8%	<u>25%</u>		
Comm	ents:					
27.				at display (Red		
				dvisories (caut		
	proxi	imate advisory) help you in	interpretina th	ne threat info	rmation?
		Vanue munh	Como.	Vanue little	None	
			Some	Very little	None	
		83%	17%			
۲		Dametaulaulu				
Comm	ients:	<u>Particularly</u>	at transition	ציוויטק ו	 	
		 	 			
						

28a.	Should form?	the altitude	e of the intrud	ier aircra	ift he given and if so in t	what:
	Al ti tud	le Informatio	วท	MSL	Relative to	
		Required			own Altitude	
				25%	75%	
285.	In what	: intervals :	should the alti	tude info	ormation be given?	
	a. one	foot				
		foot				
		idred foot	92%			
	d. tho	usand foot				
Comm	ents:					
	raft by		ights were you it (them) with SOMETIMES		visually acquire the intr sory present? NEVER	uder
					100%	
Comm	ents: <u>Nev</u>	er saw the i	intruder			
30a.			ne master cauti raffic advisori		was necessary to draw you	r
	ALWAYS	USUALLY	SOMETIMES	SELDOM	NEVER	
	8%	67%	17%	8%		
Comm	ents:					
						

30 b .	Do you	feel that t	his feature of	f the master	caution is desirable	?
	ALWAYS	USUALLY	SOMETIMES	SELDOM	NE VER	
	42%	33%	25%			
Comm	ents: <u>Co</u>	oncerned wit	h high density	activation	too frequently	
30.	•		se the traffic vasive maneuve	-	formation to anticir	oate the
	ALWAYS	USUALLY	SOMETIMES	SELDOM	NEVER	
		<u>58%</u>	25%	8%	8%	
Comm	ents:					
31.		eral what do reat display		ut the amount	of information prov	ided by
75%	about r	riaht				
18%	too lit	ttle, add to	the following	critical mo	vement of intruder	
8%	too mud	ch, delete t	he following			
Comm	ents:					
						

remaine went?	ed active afte	r your maneuv	ver to show wher	re the target aircraf	ft
Extremely	Useful	Of No	Detrimental	Extremely	
Useful		Use		Detrimental	
17%	17,%	<u>67%</u>			
10 to	6	. 7 4 . 4 .			L
-		•	•	ong should the target it is in range, 5-10	:
seconds		· Filos open	on, as tond as i	c is in range, 5-10	
30001103	,				
		·			
Comments:					
transpo	nder equipped	aircraft?		al scanning for non-	
ALWAYS		SOMETIMES		NEVER	
C	<u>50</u> Significant ch	<u>17</u>	<u>17</u>	17	
with be		tion, will yo	u be concerned	and a threat displa about maneuvering in	_
ALWAYS	USUALLY	SOMETIMES	SELDOM	NEVER	
75%	8%	33%	33%		
`amonto.					
Comments:					
		D	-18		

32a. During the test, the intruder aircraft symbol on the threat display went

away when the threat was resolved. How useful would it be if the display

34a.	-	_	acquires the air			
	cluding	that the RA	is unnecessary?	If so what	are they?	
			acquire the wro	ong target, pa	arallel approac	ch_
	notating j	pattern, Visi	ual illusions	····		
3 4 b.	Would the	e pilot be j	ustified in not	following the	RA in these	situations?
		•	(67%) Only if h			
	-		zontal maneuver			
	the RA	3 43. G 1.0. 1.		, 0.00	· · · · · · · · · · · · · · · · · ·	3 10 10 10 10 10 10 10 10 10 10 10 10 10
	- CIN TOTAL			·		
				······································		
340	What inf	luence does	the type of TA :	service heina	provided have	on vour
J7C•		s to these qu	• .	service wing	Di Ovina nave	on your
	response.	3 10 cm. 31; q	ac, 5 c (cm 5 .			
	None - a	n RA command	is a command, r	must be relial	ole with drank	nice milat
			ence in the RA	HUST. DE L'ELLE	ne, with diap	ires prior
	may nave	more control	ence in the RA			
				 		
35.	-		wing the intrud		•	
	• •		with a traffic			
	informat	ion to allow	you to minimize	e the anticipa	ated deviation	from your
	planned	flight path?				
	ALWAYS	USUALLY	SOMETIMES	SELDOM	NE VER	
	8%	50%	33%	8%		
Comm	ents:					
						
		·····				
				 		

	ALWAYS	USUALLY	SOMETIMES	SELDOM	NEVER
		33%	58%	8%	
Omm	ents: Als	o need head	ing		
7.	What effe	ct would the	e TCAS have on	your confidenc	e when overflying/
	underflyi	ng another a	aircraft by 100	00 feet?	
	INCREASE	CONFIDENCE	NO CHANGE	LESS CONFI	DENCE
		67%	33%		
	·				
8a.	Do you fe		of TCAS could	allow reduced	vertical traPfffic
8a.	•	n?			
8a.	separatio	n? MUCH	SOMEWHAT	NO	INCREASED
8a.	separatio	n?			

386.	Reduced	Horizonta?	Traffice	Separation?
	110000	HOT I LOTT CU.	11411	oapa, ao.,,,,

		MUCH	SOMEWHAT	١	NO	INCREASED	
	RE	DUCED	REDUCED	RE	DUCTION	SEPARATION	
			33%		67%		
<u>39.</u>	Do you feel	that the	TCAS will re	esult in	more or le	ess communica	tion with
	ATC?						
	MUCH LESS	SOMEWHAT	LESS NO	CHANGE	SOMEWHAT	MORE MUCH	MORE
	8%	33%		17%	42%	_	
, COMm	ents:				. — . —		
							
40.	Do you feel	that a re	liable TCAS	will res	ult in saf	er operation	s in
	respect to	midair coli	lisions?				
		OMEWHAT	NO CHAN		SOMEWHAT	MUCH L	
		SAFER		,	LESS SAFE	SAFE	
	58%	42%					•
Comm	ents: <u>Key i</u>	s reliabil	ity, prohab	ly to the	same exte	ent that GPWS	prevents
<u>coll</u>	ision with t	he ground				· · · · · · · · · · · · · · · · · · ·	
							
41.	What change	s would be	required in	n aircraf	t and ATC	operating pr	ocedures
	if TCAS wer	e implemen	ted?				
Comm	ents: RAs sh	ould be au	tomatically	transmit	ted, who h	nas priority	on
conf	lictina info	rmation he	tween alert	and ATC,	ATC shoul	ld not rely o	n TCAS,
Emer	gency author	ity to bre	ak clearanc	e			
_							

SEMANTIC DIFFERENTIAL INSTRUCTIONS

The semantic differential gives us a way to judge pilot opinions of the TCAS in a systematic fashion. You can help by checking the degree to which your opinion falls between each of these 21 adjective pairs.

An example may help. Suppose we ask you to judge "politics" on the following scale:

GOND								BAD
------	--	--	--	--	--	--	--	-----

If you feel that politics are very good, then you should check the box nearest that adjective. If you feel that politics are bad, then your check mark should be in one of the right-hand boxes. If your opinion is neutral, neither positive nor negative, check the center box.

There are no "right" or "wrong" answers; we are simply asking your opinion. Don't be hesitant to check the far left or far right boxes if you feel strongly about the concept. It's better that you don't change a check mark once it is made; your first opinion may be most valid.

Both positive and negative adjectives may appear on either right or left sides, so consider each pair carefully before you make the check mark.

Using the following descriptors, judge the TCAS IVSI command display and its operational uses as you currently know them.

CLEAR	CONFUSING
DEMANDING	UNDEMANDING
LIMITED	VERSATILE
DESIRABLE	UNDESIRABLE
UNTRUSTWORTHY	TRUSTWORTHY
COMPLEX	SIMPLE
ASSISTANCE	HINDRANCE
VALUABLE	WORTHLESS
NONESSENTIAL	ESSENTIAL
COMPLETE	INCOMPLETE
NATURAL	UNNATURAL
EASY	DIFFICULT
HAZARDOUS	SAFE
TIMELY	UNTIMELY
UNACCEPTABLE	ACCEPTABLE
UNBURDENING	BURDENING
STARTLING	UNOBTRUSIVE
INFORMATIVE	UNINFORMATIVE
INDISTINCTIVE	DISTINCTIVE
RELIABLE	UNRELIABLE
ACCURATE	INACCURATE

Using the following descriptors, judge the TCAS LED command display and its operational uses as you currently know them.

CLEAR	CONFUSING
DEMANDING	UNDEMANDING
LIMITED	VERSATILE
DESIRABLE	UNDESIRABLE
UNTRUSTWORTHY	TRUSTWORTHY
COMPLEX	SIMPLE
ASSISTANCE	HINDRANCE
VALUABLE	WORTHLESS
NONESSENTIAL	ESSENTIAL
COMPLETE	INCOMPLETE
NATURAL	UNNATURAL
EASY	DIFFICULT
HAZARDOUS	SAFE
TIMELY	UNTIMELY
UNACCEPTABLE	ACCEPTABLE
UNBURDENING	BURDENING
STARTLING	UNOBTRUSIVE
INFORMATIVE	UNINFORMATIVE
INDISTINCTIVE	DISTINCTIVE
RELIABLE	UNRELIABLE
ACCURATE	INACCURATE

Using the following descriptors, judge the TCAS voice command display and its op-rational uses as you currently know them.

CLEAR	CONFUSING
DEMANDING	UNDEMANDING
LIMITED	VERSATILE
DESIRABLE	UNDESIRABLE
UNTRUSTWORTHY	TRUSTWORTHY
COMPLEX	SIMPLE
ASSISTANCE	HINDRANCE
VALUABLE	WORTHLESS
NONESSENTIAL	ESSENTIAL
COMPLETE	INCOMPLETE
NATURAL	UNNATURAL
EASY	DIFFICULT
HAZARDOUS	SAFE
TIMELY	UNTIMELY
UNACCEPTABLE	ACCEPTABLE
UNBURDENING	BURDENING
STARTLING	UNOBTRUSIVE
INFORMATIVE	UNINFORMATIVE
INDISTINCTIVE	DISTINCTIVE
RELIABLE	UNRELIABLE
ACCURATE	INACCURATE

Using the following descriptors, judge the TCAS tabular display and its operational uses as you currently know them.

CLEAR	CONFUSING
DEMANDING	UNDEMANDING
LIMITED	VERSATILE
DESIRABLE	UNDESIRABLE
UNTRUSTWORTHY	TRUSTWORTHY
COMPLEX	SIMPLE
ASSISTANCE	HINDRANCE
VALUABLE	WORTHLESS
NONESSENTIAL	ESSENTIAL
COMPLETE	INCOMPLETE
NATURAL	UNNATURAL
EASY	DIFFICULT
HAZARDOUS	SAFE
TIMELY	UNTIMELY
UNACCEPTABLE	ACCEPTABLE
UNBURDENING	BURDENING
STARTLING	UNOBTRUSIVE
INFORMATIVE	UNINFORMATIVE
INDISTINCTIVE	DISTINCTIVE
RELIABLE	UNRELIABLE
ACCURATE	INACCURATE

Using the following descriptors, judge the TCAS graphic (minimum) display and its operational uses as you currently know them.

CLEAR	CONFUSING
DEMANDING	UNDEMANDING
LIMITED	VERSATILE
DESIRABLE	UNDESIRABLE
UNTRUSTWORTHY	TRUSTWORTHY
COMPLEX	SIMPLE
ASSISTANCE	HINDRANCE
VALUABLE	WORTHLESS
NONESSENTIAL	ESSENTIAL
COMPLETE	INCOMPLETE
NATURAL	UNNATURAL
EASY	DIFFICULT
HAZARDOUS	SAFE
TIMELY	UNTIMELY
UNACCEPTABLE	ACCEPTABLE
UNBURDENING	BURDENING
STARTLING	UNOBTRUSIVE
INFORMATIVE	UNINFORMATIVE
INDISTINCTIVE	DISTINCTIVE
RELIABLE	UNRELIABLE
ACCURATE	INACCURATE

Using the following descriptors, judge the TCAS graphic (advanced) display and its operational uses as you currently know them.

CLEAR	CONFUSING
DEMANDING	UNDEMANDING
LIMITED	VERSATILE
DESIRABLE	UNDESIRABLE
UNTRUSTWORTHY	TRUSTWORTHY
COMPLEX	SIMPLE
ASSISTANCE	HINDRANCE
VALUABLE	WORTHLESS
NONESSENTIAL	ESSENTIAL
COMPLETE	INCOMPLETE
NATURAL	UNNATURAL
EASY	DIFFICULT
HAZARDOUS	SAFE
TIMELY	UNTIMELY
UNACCEPTABLE	ACCEPTABLE
UNBURDENING	BURDENING
STARTLING	UNOBTRUSIVE
INFORMATIVE	UNINFORMATIVE
INDISTINCTIVE	DISTINCTIVE
RELIABLE	UNRELIABLE
ACCURATE	INACCURATE

SYSTEM DISPLAY DESIGN

In the following space please design the TCAS display(s) that you would put into the flight deck. Design a command display for a conventional and one for an electronic flight deck. Provided for your information are the alerts which this display must present at a minimum. Along with your design please give the location of the display in the instrument panel. Then design the information presentation that you would like to see on the threat display. Again please describe its location. Use the back side of the papers to continue your display description if you require more space.

In order to standardize the responses to this section of the questionnaire it will be necessary to use the smae prescribed alert situations and the same scenarios to illustrate your recommended threat/display relationship. We will consider two situations, one requiring a vertical command and one requiring a limit command.

(1) Vertical Command

- (a) Scenario: Own aircraft is straight and level at 300 kts at 15000 ft. Threat alert aircraft is coming from 10 o'clock position and is initally 2000 ft below and 6 nmi away. This results in a closure rate of 480 knots. The threat is climbing such that it will collide which gives a climb rate of about 2600 fpm. The total length of time from start to potential collision is 45 seconds.
- (b) Command: The vertical resolution advising command will be a climb command with a desired 1/4 G pullup to 1000 fpm rate of climb.

(2) Limit Command


(a) Scenario: Own aircraft is straight and descending at 2000 fpm, 250 kts, passing 10000 ft. Threat aircraft is coming from 2 o'clock, it is at your altitude and also descending at 2000 fpm. Again, you are on collision trajectories, 45 seconds from impact. Assume a closure rate of 200 kts which places you initially at 2.5 miles apart.

(b) Command: Assume you are both TCAS equipped and received complementary commands. He is commanded to descend. Your command is to Limit Descent to 500 fpm. The proposed maneuver would again be a 1/4 G pullup.

THREAT DISPLAY

Description:

CONVENTIONAL COMMAND DISPLAY



Description:

ELECTRONIC FLIGHT DECK COMMAND DISPLAY

!
1

Description:

